TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48131276
Order No. / Reference: 27080796
Inspection date: 15 Oct 2026

Manufacturer: Volkswagen	Model: Golf Variant 2.0 TSI OPF 4Motion DSG R-Line
VIN: WVWZZZCD4PW512805	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TSI OPF 4Motion DSG R-Line	
Vehicle Identification number	WVWZZZCD4PW512805
Mileage (Read)	115,295 km
First registration	2 Dec 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	11/2027
Fuel type	Petrol
Engine displacement / Cylinder	1,984 ccm / 4
Power	140 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Kings Red Metallic
Doors / Seats	5 / 5
Upholstery type	Alcantara / cloth
Colour of upholstery	Anthracite-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	8,300 km
Last service on / at	04/2025 at 60,918 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM775230
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / COW 00579		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,090 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92ZR	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/40 R18 92ZR	Summer tyres on Light alloy	Michelin	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Nexen	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Nexen	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Permanent all-wheel drive
- 30-color ambient lighting
- Exterior mirror housings and door handles in body color
- third brake light
- Car2X
- Decorative inlays "Carbon Grey"
- Parking assistance
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Chassis: Sport chassis
- Windscreen made of laminated safety glass, heat and sound insulating
- Speed limiter
- Rear window heated
- Rear spoiler in car color
- "Climatronic" air conditioning system (with active combination filter)
- LED reading lights at the front (2) and 2 at the rear
- Steering wheel: Multifunction sports steering wheel in leather, with touch controls and paddle shifters
- Non-smoking version
- Emergency call service
- Otto particulate filter
- Brushed stainless steel pedals
- Tire pressure monitoring system (passive)
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in "R-Line" fabric
- Seats: Lumbar support in the front
- Lane keeping assistant “Lane Assist”
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Ambient lighting with logo projection
- Green thermal insulation glazing, sides and rear
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- black roof rails
- Digital Cockpit Pro, multicolor
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Driving profile selection
- Electric windows, front and rear
- Pedestrian protection measures expanded
- luggage compartment cover
- Transmission: 7-speed DSG
- Rear window wiper with intermittent function
- ISOFIX mounting points
- Rear headrests (3)
- Front headrests
- LED taillights
- Dynamic headlight range control
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Package: Seat Comfort Package
- Progressive steering
- Wheels: Tire Mobility Set
- Keyless start system without safe locking
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Top sports seats in the front
- Start-stop system
- Bumpers in body color
- Textile floor mats front and rear
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote folding keys

Extra equipment

- Air conditioning "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Lane change assistant "Side Assist", parking assistant and exit warning (alerts the driver with visual signals in the respective exterior mirror to vehicles that could pose a danger when changing lanes - Parking assistant: monitors the area behind and beside the vehicle when reversing out of a parking space, issues visual and acoustic warning signals if a vehicle is detected crossing the parking space path, can initiate emergency braking to reduce the severity of a collision or to prevent a collision altogether)
- Navigation system "Discover Pro" incl. "Streaming & Internet" (6+1 speakers - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Navigation system "Discover Pro" incl. "Streaming & Internet" - Radio - Voice control - Traffic sign recognition)
- Package: Comfort Package (electrically adjustable, folding, and heated exterior mirrors with memory function and passenger-side mirror lowering - anti-theft alarm system with interior monitoring, backup horn, and tow-away protection - "Park Assist" parking assistant including parking aid - proactive occupant protection system in conjunction with Front Assist and Side Assist - Keyless Access keyless locking and starting system with safe locking - side airbags for the outer rear seats, including front side airbags and head airbag system)
- Package: Design package "Black Style" (Exterior mirror housings in black - Roof rails in black - Illuminated strip between headlights and door handle recesses - With individual installation)
- Radio accessories: "Harman Kardon" sound system (8+1 speakers, 425 watts total power, 12-channel amplifier, subwoofer)
- Rear side windows and rear window tinted
- Wheels: Spare wheel, weight and space saving (on-board tools and jack - instead of Tire Mobility Set)
- IQ.LIGHT - LED matrix headlights, including Light and Sight package (Dynamic Light Assist high beam control for LED matrix headlights - Automatically dimming interior mirror - IQ.LIGHT - LED matrix headlights with LED daytime running lights, cornering lights and dynamic turn signals - LED taillights with dynamic turn signals - Dynamic headlight range control with dynamic cornering lights - Multifunction camera - Rain sensor - Bad weather lights and cornering lights)
- Package: Business Premium incl. navigation system (R-Line DSG) (6+1 speakers, App-Connect incl. App-Connect Wireless for Apple CarPlay, Android Auto, automatic distance control, adaptive cruise control (ACC) stop/go, speed limiter, emergency brake, pedestrian detection, travel assist, lane assist, emergency assist, multifunction sports steering wheel with LED and heated steering wheel, paddle shifters, multifunction camera, Discover Media navigation incl. streaming & internet (MP3, touchscreen, USB), cargo net, radio, heated windshield washer system, voice control, telephone interface, comfort with inductive charging, textile floor mats, traffic sign recognition, heated front seats)
- Package: Winter (DSG) (R-Line) (Multifunction sports steering wheel in leather, heated, with touch controls and shift paddles - Automatically heated front windscreen washer nozzles - Heated front seats)
- Paint finish: Metallic
- Park Assist system including parking aid
- Rear View reversing camera
- Towbar, foldable with electric release
- Wheels: Alloy wheels (4) "Bergamo" 7.5 J x 18 (in black, polished surface - with individual installation - wheel locks with enhanced theft protection - tires 225/40 R 18)
- Wheels: Winter wheels (additional) steel, 6.5 J x 16 (4 steel wheels 6.5 J x 16 - wheel wrench and jack - winter tires 205/55 R16 H)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Scratch(es) - Loss in value
2	Side panel - rear right side	Side panel - dent(s) - Smart repair

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 14 Mar 2026	1.145,40 €
2	Side right, Provided by user / customer, from 14 Feb 2025	1.522,57 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Damage 1: Boot lid / rear door: Boot lid - Scratch(es) - Loss in value




Damage 1: Boot lid / rear door: Boot lid - Scratch(es) - Loss in value



Damage 1: Boot lid / rear door: Boot lid - Scratch(es) - Loss in value



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smart repair