MACADAM

Opel Corsa 5d '19 BEV

Vehicle information


Make:	**Opel**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Corsa 5d '19 BEV**	VIN:	**VXKUHZKXZM4287166**
Fuel type:	**Electric**	Power:	**100 kW**
Version:	**Corsa-e 50 Bus.E. 11kW 3 f. 5d**	First registration	**30/10/2021**
Mileage:	**94236 km**	N° of doors:	

Damage summary

Front	1
Left	6
Rear	1
Right	5
Roof & others	1

Commercial pictures




OPEL CORSA
OPEL CORSA


VXKUHZKXZM4287166



















Batterijcertificaat
Datum van diagnose: 29/10/2026
89,31%
Status van de gezondheid (SOH)*
Opel Corsa e
VIN : VXKUHZKXZM4287166
Kilometerstand : 94.236 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA



Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Radio multimedia	**Yes**	Rear view camera	**Yes**	Telephone equipment	**Yes**

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left




Alloy rim RL
Scratch(es)
Repair and paint (complete)
Left





Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right




Bumper F
Scratch(es)
Repair and paint (complete)
Front




Bumper R
Scratch(es)
Repair and paint (complete)
Rear




Door FL
Scratch(es)
Repair and paint (complete)
Left






Door FR
Scratch(es)
Repair and paint (complete)
Right





Door RL
Scratch(es)
Repair and paint (complete)
Left






Door RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right





Roof
Chemical polution
Repair and paint (complete)
Roof & others





Wing FR
Scratch(es)
Repair and paint (complete)
Right





Wing RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left




Wing RL
Scratch(es)
Repair and paint (complete)
Left





Wing RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right





Tyres

Front Left
Winter
195/55/16/91/H
Bridgestone
6.2 mm
Front Right
Winter
195/55/16/91/H
Bridgestone
5.4 mm
Rear Left
Winter
195/55/16/91/H
Continental
7.0 mm
Rear Right
Winter
195/55/16/91/H
Continental
5.2 mm

Checks

CO2 Emission	**0**	Digital maintenance	**N/A**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**2**
Number of keys total	**2**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**Yes**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.