TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48404217
Order No. / Reference: 27236905
Inspection date: 28 Oct 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG 4x4 RS Plus
VIN: TMBLK0NX0PY010407	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG 4x4 RS Plus	
Vehicle Identification number	TMBLK0NX0PY010407
Mileage (Read)	105,318 km
First registration	19 Sept 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Blau Race Metallic (F5W)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	15,500 km
Last service on / at	02/2026 at 90,791 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ955506
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AVJ 00071		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,141 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R19 93Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	225/40 R19 93Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18	Summer tyres on Steel		5 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Airbag: Center airbag front
- Ambient lighting (dashboard, front trim strips and footwell with selectable color climate) in the interior as well as logo projector on the outside)
- Center section of the dashboard with microfiber cover in black and red decorative stitching
- Exterior mirrors with memory function (boarding spots in the exterior mirrors as well as memory function and mirror lowering)
- Hill start assist including auto-hold function
- Glasses compartment in the headliner
- Roof rails, black
- Diesel particulate filter
- Tachometer
- Electronic parking brake
- Electronic Stability Control (ESC)
- Driving profile selection
- Chassis: Sport chassis (15 mm reduced ground clearance - modified damper settings)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Rear spoiler
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Removable boot cover
- LED fog lights
- LED taillights in crystal glass look and animated turn signals
- LED headlights with LED daytime running lights
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Heated steering wheel in a sporty design with paddle shifters
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters (leather steering wheel and gearshift lever with leather elements - infotainment and driver assistance system operation)
- Package: Comfort Plus (Combi RS, Sportline) (3-zone Climatronic - acoustic glazing in the front side windows - heated outer rear seats - heated steering wheel - 230 V socket and 3 x USB charging ports - sunshades in the rear doors - multifunction storage compartment in the boot - sleeping headrests in the rear - semi-automatic luggage compartment cover)
- Front and rear parking sensors
- Storage compartments (Four roof grab handles, rear with coat hooks; holder for the warning vest under the driver's seat; storage compartments in the front door panels with 1.5l bottle holders; storage compartments in the rear door panels with 0.5l bottle holders; ticket holder on the windshield; coat hooks on the B-pillars; storage compartments in the doors with felt lining)
- All-wheel drive 4x4
- Trailer hitch preparation including trailer stabilization
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Hydraulic brake assist (HBA)
- black headliner
- Dark Carbon decorative trim
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant (Coming Home / Leaving Home function)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Luggage net partition
- Cruise control system
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Electronic child safety lock
- Comfort opening with electric tailgate operation (Combi) (incl. semi-automatic luggage compartment cover)
- LED license plate lights
- LED matrix headlights and dynamic high beam assist (AFS) (Dynamic and automatic headlight range control - headlight cleaning system including washer fluid level control)
- Steering wheel: height and reach adjustable
- Rear center armrest with pass-through option
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Package: Infotainment Columbus Plus (Columbus navigation system - Infotainment Online (3-year term) - Head-Up Display)
- Package: Parking & Lighting (cornering lights in the fog lights - headlight cleaning system - ambient lighting - matrix headlights - rear lights in crystal glass look and animated turn signals - reversing camera - parking assist)

- Pedals in stainless steel look
- Progressive steering
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: Bluetooth hands-free system
- Radio accessories: Digital radio reception DAB+
- Radio accessories: SmartLink (Apple CarPlay - Android Auto)
- Rain sensor
- Wheels: 19" Altair alloy wheels, anthracite polished (7.5J x 19, ET 48 with 225/40 R19 tires)
- Seats: Heated rear seats
- Seats: Electrically adjustable Ergo sports seats in the front (massage function - extendable leg support - microfiber interior (combined with high-quality materials) - front seats and exterior mirrors with memory function - boarding spots in the exterior mirrors - lane change and parking assistant as well as exit warning)
- Speed limiter
- Lane keeping assistant (Lane Assist)
- Lane change and parking assist as well as exit warning
- 12V socket in the trunk
- 230V socket and USB charging port (230V socket and 2 x USB charging ports in the rear as well as USB charging port in the rearview mirror)
- Sunset (rear window and rear side windows tinted dark)
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Textile floor mats
- Glazing: Acoustic glazing in the front side windows and Sunset (dark tinted rear window and rear side windows)
- Central locking including remote control integrated into the key and EASY Start
- Package: Travel Plus (DSG) (Traveller assistance system: - Traffic sign recognition - Predictive and adaptive cruise control (pACC) - Adaptive lane keeping assist - Emergency and traffic jam assist (with DSG) - Capacitive steering wheel with hands-off detection - Adaptive cruise control (ACC) (control range 210 km/h) - Driver fatigue detection - Driving profile selection - Adaptive chassis control (DCC) - Automatically dimming exterior mirror (driver's side))
- Radio accessories: Voice control
- Tire pressure monitoring
- Seat belts (Three three-point seat belts in the rear)
- Safety lights in the front side doors
- Seats: Heated front seats
- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear.
- SKODA Care Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Phone: Wireless SmartLink for Apple CarPlay
- Front door sill trims
- Lashing eyes in the trunk
- Immobiliser

Extra equipment

- Paint finish: Metallic
- Radio accessories: CANTON sound system and 18" steel spare wheel (12 speakers (10 speakers, 1 central speaker, 1 subwoofer in the spare wheel well) - 18" steel spare wheel (tire 125/70 R18) including jack and wheel wrench)
- Package: Safety (Drowsiness detection - Rear side airbags - Proactive occupant protection with rear impact detection)
- Heated windscreen

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
5	Door - rear left side	Door - Scratch(es) - Smart repair
6	Front bumper	Front bumper - Scratch(es) - Smart repair
7	Front bumper	Spoiler - Scratch(es) - Replace
8	Body	Body - Damage by hail - repair according to calculation

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen im demontagefreien Zustand erstellt. Es können Mehrkosten und somit Abweichung der für den Hagelschaden ausgewiesener Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 5: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 5: Door - rear left side: Door - Scratch(es) - Smart repair




Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 7: Front bumper: Spoiler - Scratch(es) - Replace




Damage 7: Front bumper: Spoiler - Scratch(es) - Replace




Damage 8: Body: Body - Damage by hail - repair according to calculation




Damage 8: Body: Body - Damage by hail - repair according to calculation



Damage 8: Body: Body - Damage by hail - repair according to calculation



Damage 8: Body: Body - Damage by hail - repair according to calculation



Damage 8: Body: Body - Damage by hail - repair according to calculation