TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48376704
Order No. / Reference: 27199683
Inspection date: 26 Oct 2026

Manufacturer: Volkswagen	Model: Caddy Cargo 2.0 TDI BMT
VIN: WV1ZZZSKZNX056887	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Caddy Cargo 2.0 TDI BMT	
Vehicle Identification number	WV1ZZZSKZNX056887
Mileage (Read)	150,699 km
First registration	7 Oct 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	55 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	3,600 km
Last service on / at	09/2026 at 147,375 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ173218
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CPF 00148		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,220 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R15 99T	Summer tyres on Steel rim with wheel cover	Continental	0mm / 0mm
2)	205/65 R15 99T	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R15 99H	Summer tyres on Steel	Hankook	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (Various shelves and storage compartments)
- Exterior mirror housings and door handles in black, sliding door track in silver
- Floor coverings: Carpet in the driver's cab
- third brake light
- Roof rail/roof rack preparation
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioners)
- Automatic headlight control with daytime running lights
- Windows: Laminated glass front pane in heat-insulating glazing
- Transmission: 6-speed transmission
- Rear wing door (asymmetrically divided) without window cutout
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Center console with 2 universal cup holders
- Multi-collision brake
- Fatigue detection
- Non-smoking version
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Wheels/Tires: Steel wheels 6J x 15, in black
- taillights
- Windscreen wiper intermittent control with light sensor
- Standard side panels in the cargo area
- Speed-sensitive power steering (Servotronic)
- Seats: Left and right seats in the 1st row (including headrests)
- Start-stop system (with brake energy recuperation)
- Tire Mobility Set (12-volt compressor and tire sealant)
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing
- Towing eye front and rear, screw-in
- Exterior mirrors: electrically adjustable
- Reinforced battery (70 Ah/ 420 A)
- Operating voltage 12 V
- Brake booster
- Cockpit panel, matte
- Three-phase generator 140 A
- Electronic parking brake including auto-hold function
- ESP Electronic Stability Program with Brake Assist (incl. Anti-lock Braking System (ABS), Traction Control (ASR), (EDS and MSR))
- Electric windows, front
- Halogen dual headlights-H7
- Heating system with electronic control
- Interior lighting in the cargo area (1 light)
- Steering column adjustable in height and tilt
- Headlight range control
- Multifunction display: 16.51 cm (6.5 inch) color touchscreen for convenient operation (with USB charging port (Type C), no radio function)
- eCall emergency call system
- Wheels, tires: Wheel covers
- Wheels/Tires: 205/65 R 15 99 H XL, optimized for low rolling resistance
- Gearshift lever in plastic
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- Seats: Height adjustment for left seat, manual
- Sun visors without mirrors, with ticket pocket on the driver's side, plus airbag label on the sun visor
- Bumper in grey
- Partition wall (tall) without window
- Lashing points: 6 lashing points for securing cargo
- Electronic immobilizer
- Central locking with remote control and interior operation

Extra equipment

- Storage compartments: Glove compartment with lockable, illuminated flap
- Rigid towbar (including trailer stabilization)
- Floor coverings: Rubber floor covering in the driver's cab
- Deletion: Lettering on the rear (excluding lettering for type/model designation - excluding promotional lettering and decals)
- Package: Cool & Sound (Refrigerant R1234yf - Safety interior mirror, automatically dimming - Air Care Climatronic air conditioning with 2-zone temperature control and air purification function)
- Upholstery: Robust fabric seat covers, "Robusta" design
- Radio "Composition Audio" with 20.96 cm (8.25 inch) touch color display (2 USB interfaces (Type C) in the center console, front - 4 speakers - mobile phone interface)
- Radio accessories: Digital radio reception DAB+
- Smoker's version (12V socket with cigarette lighter and ashtray)
- Sliding door, left side in the passenger/cargo area
- Telephone: Mobile phone interface
- Partition wall (high) with grilles
- Airbag, side and head airbags for driver and front passenger
- Floor coverings, rubber floor covering in the cargo area
- Parking assistance (rear parking distance control)
- Interior lighting in the cargo area, 2 LED spotlights
- Paint finish: Solid
- Fog lights including cornering lights
- Package: Window package (Caddy Cargo with rear wing doors) (Rear wing doors with asymmetrically divided window cutouts - Fixed side window in the load/passenger compartment, front left - Fixed side window in the load/passenger compartment, front right - Fixed side window in the load/passenger compartment, rear left - Heated rear window - Fixed side window in the load/passenger compartment, rear right - Rear window wiper/washer system with intermittent function)
- Wheels/Tires: Spare wheel in driving tire size, steel (spare wheel in driving tire size, steel - on-board tools and jack)
- 12-volt sockets in the instrument panel and in the cargo area

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Trim / covers - Broken / torn - Replace
2	Boot lid / rear door	Rear door - right side (Dichtung) - Broken / torn - Replace
3	Seat - front	Seat cover - left side - Burn hole (cigarettes) - Smart repair
4	Instrument panel	Centre console - front - Scratch(es) - Conditioning
5	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
6	Sill - right side	Sill - Dent / paintcoat damage - Smart repair
7	Door - front left side	Door - dent(s) - Smart repair
8	Boot lid / rear door	Seal - Broken / torn - Replace
9	Roof	Roof - Dent / paintcoat damage - Loss in value
10	Roof	Roof rail - right side - Dent / paintcoat damage - Smart repair
11	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
12	Door - front right side	Door (Unterhalb) - Dent / paintcoat damage - Smart repair
13	Front structure	Emblem - Missing - Replace
14	2nd wheel set	2 tyres - Worn - Replace
15	Body	Body - Glued / labelled - De-glue / neutralise
16	Front bumper	Front bumper (unpainted) - Broken / torn - Replace
17	Boot lid / rear door	Rear door - right side (Oberhalb) - Deformed - Repair and paint
18	Boot lid / rear door	Rear door - left side (+Rost) - Dent / paintcoat damage - Repair and paint
19	Sliding door - left side	Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint
20	Sliding door, right	Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint
21	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Sill - left side	Sill - dent(s) - No deduction
2	Interior	Interior - Dent / paintcoat damage - No deduction
3	Wing mirror - right side	Cap - Scratch(es) - No deduction
4	Wing mirror - left side	Cap - Scratch(es) - No deduction
5	Door - front left side	Door handle - outside - Scratch(es) - No deduction
6	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Smart repair
7	Rear bumper	Rear bumper (unpainted) - Dent / paintcoat damage - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Interior - Cigarette lighter

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Stoßstange vorne wurde aufgrund der Laufleistung und des Alter des Fahrzeuges gemindert.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Damage 1: Trim / covers: Trim / covers - Broken / torn - Replace




Damage 1: Trim / covers: Trim / covers - Broken / torn - Replace



Damage 2: Boot lid / rear door: Rear door - right side (Dichtung) - Broken / torn - Replace



Damage 3: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



Damage 3: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



Damage 4: Instrument panel: Centre console - front - Scratch(es) - Conditioning



Damage 4: Instrument panel: Centre console - front - Scratch(es) - Conditioning



Damage 5: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 5: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 6: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Sill - right side: Sill - Dent / paintcoat damage - Smart repair




Damage 7: Door - front left side: Door - dent(s) - Smart repair



Damage 7: Door - front left side: Door - dent(s) - Smart repair



Damage 7: Door - front left side: Door - dent(s) - Smart repair



Damage 8: Boot lid / rear door: Seal - Broken / torn - Replace



Damage 8: Boot lid / rear door: Seal - Broken / torn - Replace



Damage 9: Roof: Roof - Dent / paintcoat damage - Loss in value



Damage 9: Roof: Roof - Dent / paintcoat damage - Loss in value



Damage 9: Roof: Roof - Dent / paintcoat damage - Loss in value




Damage 10: Roof: Roof rail - right side - Dent / paintcoat damage - Smart repair



Damage 10: Roof: Roof rail - right side - Dent / paintcoat damage - Smart repair



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 11: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 12: Door - front right side: Door (Unterhalb) - Dent / paintcoat damage - Smart repair




Damage 12: Door - front right side: Door (Unterhalb) - Dent / paintcoat damage - Smart repair



Damage 12: Door - front right side: Door (Unterhalb) - Dent / paintcoat damage - Smart repair



Damage 13: Front structure: Emblem - Missing - Replace



Damage 14: 2nd wheel set: 2 tyres - Worn - Replace



Damage 14: 2nd wheel set: 2 tyres - Worn - Replace



Damage 14: 2nd wheel set: 2 tyres - Worn - Replace



Damage 14: 2nd wheel set: 2 tyres - Worn - Replace



Damage 15: Body: Body - Glued / labelled - De-glue / neutralise



Damage 15: Body: Body - Glued / labelled - De-glue / neutralise




Damage 16: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 16: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 16: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 16: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 16: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 17: Boot lid / rear door: Rear door - right side (Oberhalb) - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side (Oberhalb) - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side (Oberhalb) - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side (Oberhalb) - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side (Oberhalb) - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side (Oberhalb) - Deformed - Repair and paint



Damage 18: Boot lid / rear door: Rear door - left side (+Rost) - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - left side (+Rost) - Dent / paintcoat damage - Repair and paint




Damage 18: Boot lid / rear door: Rear door - left side (+Rost) - Dent / paintcoat damage - Repair and paint




Damage 18: Boot lid / rear door: Rear door - left side (+Rost) - Dent / paintcoat damage - Repair and paint



Damage 19: Sliding door - left side: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 19: Sliding door - left side: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint




Damage 19: Sliding door - left side: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 19: Sliding door - left side: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 20: Sliding door, right: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 20: Sliding door, right: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint




Damage 20: Sliding door, right: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 20: Sliding door, right: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint




Damage 20: Sliding door, right: Sliding door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 21: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 21: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 21: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 21: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 1: Sill - left side: Sill - dent(s) - No deduction



Wear and tear 2: Interior: Interior - Dent / paintcoat damage - No deduction



Wear and tear 6: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Wear and tear 6: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Wear and tear 7: Rear bumper: Rear bumper (unpainted) - Dent / paintcoat damage - No deduction



Wear and tear 7: Rear bumper: Rear bumper (unpainted) - Dent / paintcoat damage - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Wear and tear 7: Rear bumper: Rear bumper (unpainted) - Dent / paintcoat damage - No deduction