TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48486292
Order No. / Reference: 27222652
Inspection date: 4 Nov 2026

Manufacturer: Audi	Model: A6 Avant allroad quattro 55 TDI tiptronic
VIN: WAUZZZF2XPN088303	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A6 Avant allroad quattro 55 TDI tiptronic	
Vehicle Identification number	WAUZZZF2XPN088303
Mileage (Read)	139,457 km
First registration	19 Sept 2023
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	2,967 ccm / 6
Power	253 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Manhattangrau Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	14,900 km
Last service on / at	06/2026 at 124,521 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV322056
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BWT 00224		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,695 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R21 100Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	245/40 R21 100Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 104H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	235/55 R18 104H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Audi virtual cockpit plus
- Exterior mirror housings in body color
- Vehicle tool kit
- Fabric headliner
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Door sills with aluminum inlay front and rear
- Chassis: adaptive air suspension allroad
- Luggage compartment lid, electrically opening and closing
- Transmission: 8-speed automatic transmission tiptronic
- rear window wiper
- Interior mirror dimming
- 2-zone automatic climate control
- Comfort center armrest in front
- Paint finish: Solid
- Steering wheel: Double-spoke leather steering wheel with multifunction and paddle shifters
- MMI Navigation plus with MMI touch response
- Progressive steering
- Wheel: 5-arm design alloy wheels (allroad)
- Wheel: Tire repair kit
- Radio accessories: 8 speakers (passive) front and rear
- Rail system with fixing set
- Seats: Standard front seats
- Sun visor on driver and passenger side
- Start-stop system
- First aid kit including warning triangle and high-visibility vests
- Camera-based traffic sign recognition
- Electronic immobilizer
- Central locking
- Airbag for driver and front passenger
- All-wheel drive "quattro" with self-locking center differential
- Audi connect navigation & infotainment
- Audi drive select
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- Control buttons, matte black
- third brake light
- Decorative inlays, fine lacquer, graphite grey
- Tachometer
- Parking aid plus with surround view
- Electronic Stability Control (ESC)
- key fob
- Cruise control system with speed limiter
- Heated rear window
- Interior lighting
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Headrests (4)
- LED headlights
- Manual steering wheel adjustment
- MMI navigation with MMI touch response
- Non-smoking version
- Wheel: 5-arm design alloy wheels
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio plus with MMI touch response
- Headlight cleaning system
- Fabric seat covers with effect
- Seats: Split-folding rear seat backrest Avant
- Lane Departure Warning
- Allroad bumper in contrasting paint finish
- Glazing: Windscreen in heat-insulating glazing
- Glazing: Rear window, rear door and side windows in clear glass
- Thermal insulation glazing on the sides and rear
- Central locking with remote control

Extra equipment

- AdBlue tank with increased filling volume
- Airbag cover in color-matched leather Audi exclusive (airbag cover on steering wheel in leather)
- Airbag cap in black leather
- Dynamic all-wheel steering (Dynamic all-wheel steering combines the advantages of dynamic steering and all-wheel steering. It supports the driver through active steering interventions at the front and rear axles. The vehicle's driving dynamics are enhanced across the entire speed range. At low speeds, the steering effort for the driver is reduced, and the vehicle's turning circle is decreased by counter-steering of the rear wheels. Steering inputs from the driver are translated quickly.)
- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides, with memory function.
- Control buttons in glossy black with haptic feedback and aluminum-look interior
- Control buttons in glossy black with haptic feedback and aluminum-look interior (control button strip in the center console and light buttons in glossy black, control button and light button strip with haptic feedback - light button strip including proximity sensor - control buttons for driver assistance systems, buttons for parking brake, auto-hold function, central locking front and rear, rear locking, frame around the interior door handles and window regulators in aluminum look)
- Door sills with aluminum inlays front and rear (illuminated, front with allroad lettering)
- Head-up display
- Head-up Display (Upon request, the speed and other driver-relevant information from MMI Navigation plus, as well as from optional equipment such as assistance systems and warning messages, are projected into the driver's direct line of sight. This reduces the need to take the eyes off the road. The multi-color display provides a high-contrast image. The projection area of the discreetly integrated head-up display is adjustable in height and brightness.)
- Ionizer and flavoring
- Ionizer and fragrance system (contains ionizer and fragrance system - Ionization reduces harmful particles and germs in the air and improves the air quality in the vehicle interior. - The fragrance system provides a feeling of freshness in the interior, with a choice between 2 high-quality fragrances (summer and winter) and 4 different intensities according to personal preference. No fragrance molecules are deposited on textile surfaces of the vehicle or on clothing.)
- Headrests: variable headrests for front seats
- Headrests: variable headrests for front seats (with manual adjustment of headrest height and distance)
- Fuel tank (73 liters)
- Fuel tank (73 liters) (fuel tank for 73 liters of gasoline/diesel fuel)
- Paint finish: Metallic
- LED headlights HD Matrix, LED taillights and headlight cleaning system
- AdBlue tank with increased filling volume (AdBlue tank with 22 liter filling volume - for diesel vehicles with SCR technology, to reduce nitrogen oxides in the exhaust gas)
- All-wheel steering dynamics
- Towbar including trailer assist
- Trailer hitch including trailer assist (The mechanically swiveling trailer hitch can be conveniently locked and unlocked via a release mechanism. It features a mechanically swiveling ball head with electric release, controlled by a button in the luggage compartment. Trailer stabilization via ESC - trailer assist supports the driver when using the vehicle as a towing vehicle. When reversing, the trailer combination can be steered automatically with the trailer assist. When the system is active, collisions are avoided when reversing.)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides, with memory function (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- Black fabric headliner
- Entry-level LED with logo projection at the front
- Door sills with aluminum inlays at the front and rear
- Electric door closing aid
- Deletion of model designation and performance/technology lettering
- Instrument panel and door trim, two-piece, single/multi-color
- Interior elements in leather, top and bottom
- Interior elements in leather, top and bottom (instrument panel and door sills in black leather with contrasting stitching in steel grey. Armrest in the doors and trim of the center console optionally in: - Black with contrasting stitching in rock grey - Okapi brown with contrasting stitching in steel grey - Sard brown with contrasting stitching in steel grey - Pearl beige with contrasting stitching in agate grey - Rotor grey with contrasting stitching in anthracite)
- ISOFIX child seat attachment for the front passenger seat
- ISOFIX child seat attachment for the front passenger seat (with deactivation switch for passenger airbag including electric child safety lock for the rear doors)
- Comfort key with sensor-controlled luggage compartment unlocking including anti-theft alarm system
- Comfort key with sensor-controlled luggage compartment unlocking including anti-theft alarm system (The vehicle can be opened by operating the door handle without actively using the key. To lock the vehicle from the outside, simply touch one of the sensor buttons on the door handles. The drive authorization is also activated without actively using the comfort key. The driver must be inside the vehicle and have the comfort key with them. The engine is started and stopped using the engine start/stop button in the center console.)
- Steering wheel: Leather steering wheel, 3-spoke, with multifunction, paddle shifters and steering wheel heating

- HD Matrix LED headlights, LED taillights and headlight cleaning system (The HD Matrix LED headlights include: - Dynamic turn signals - Daytime running lights - Low beam - High beam - Position lights - Cornering lights - All-weather lights (to reduce glare in poor visibility conditions) - Maneuvering lights (illumination of the maneuvering area to the side when reversing) - Highway lights - Automatic dynamic headlight range control - Static cornering lights (lateral illumination in tight curves) - Dynamic light sequence for the coming home/leaving home function.)
- Assistance Package Plus
- Assistance Package Plus (Parking Assistance Package with Remote Parking Assistant Plus (surround view cameras, Remote Parking Assistant Plus) - City Assistance Package (Intersection Assist, Lane Change Warning, Exit Warning, Rear Cross Traffic Assist, Audi pre sense 360°) - Tour Assistance Package (Adaptive Cruise Assist, Efficiency Assist, Turn Assist, Evasive Steering Assist, Emergency Assist))
- Audi pre sense rear seat package (The package includes a selection of features that increase safety and comfort in the rear seat - Side airbags in the rear - Reversible rear seat belt tensioners with illuminated seat belt buckles)
- Black Optics Package Plus
- Black Optics Package Plus (Includes: - black accents in the area of the Audi Singleframe, the trim strips on the side windows, the front and rear bumpers, between the taillights and in the area of the tailpipe optics - Audi rings front and rear and model designation on the rear in black)
- Package: Ambient lighting package plus
- Package: Ambient lighting package plus (contour lighting front/rear doors, color-matched - ambient fabric lighting front/rear doors, color-matched - ambient lighting front center console, color-matched - contour lighting front center console, color-matched - contour lighting with illuminated quattro lettering (for all-wheel drive) on the instrument panel on the passenger side, color-matched - ambient lighting of the instrument panel)
- Parking assistant with parking aid plus
- Parking assistant with parking aid plus (The parking assistant supports parking maneuvers by making suitable steering corrections. Ultrasonic sensors search for suitable parallel and perpendicular parking spaces. For perpendicular parking spaces (forwards and backwards), the ideal parking path is calculated; for parallel parking spaces, the ideal entry and exit paths are calculated. The system takes over the steering. The driver only needs to follow the instructions on the display to change gears, accelerate, brake, and monitor the parking process.)
- Radio accessories: USB ports with charging function in the rear.
- Radio accessories: USB ports with charging function in the rear (2 USB-C ports with charging function in the rear in addition to two further ports in the first row of seats. Easy connection using a USB cable, 15 watts output)
- Seats: 4-way lumbar support
- Steering wheel: Leather steering wheel, 3-spoke with multifunction, paddle shifters and steering wheel heating (paddle shifters allow manual changing of the driving modes. The steering wheel rim is also heated.)
- Electric steering wheel adjustment
- Electric steering wheel adjustment (adjustable in height and distance, with automatic entry and exit)
- Night vision assistant
- Night Vision Assistant (This system assists with night driving by displaying an infrared thermal image of the road ahead in the Audi virtual cockpit. Detected pedestrians and larger wild animals are highlighted in yellow. If a potential hazard is identified based on their movement and position, the highlight changes to red. A warning triangle also appears on the display, and an acoustic warning is triggered. The Night Vision Assistant activates automatically in darkness.)
- Audi pre sense rear package package
- Business Package
- Business Package (Assistance Package Tour (adaptive speed assist, efficiency assist, turn assist, evasive steering assist, emergency assist) - 4-zone automatic climate control - heated front seats - Audi phone box - automatically dimming interior mirror - automatically dimming exterior mirrors - adaptive windscreen wipers with integrated washer nozzles - high-beam assist)
- Package: Filing package
- Package: Storage package (2 cup holders in the rear center armrest, luggage compartment net for fixing to the lashing eyes on the luggage compartment floor)
- Panoramic glass roof (2-piece)
- Panoramic glass roof (2-piece) (extra-large, tinted glass surface for a progressive design; electric operation for tilting and opening, including an electrically operated, lightproof sunshade; convenient opening and closing from the outside via the remote key ensures a pleasant, light-flooded interior; improved interior climate through efficient ventilation; integrated wind deflector reduces wind noise when the roof is open)
- Wheel: Audi new car tire warranty
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (sound reproduction via 16 speakers including 3D sound speakers, center speaker and subwoofer, 15-channel amplifier with a total output of 705 watts; spatial sound reproduction thanks to the 3D sound feature for the front seats. This is created by additional speakers in the A-pillars, the midrange speakers and Fraunhofer Symphoria technology. The 3D sound can be played back with all sources.)
- Servo closing for doors (comfortable and safe door closing, automatically pulls doors that are not fully latched into the lock with the support of a servo motor)

- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Seats: Individual contour front seats (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt and thigh support; pneumatic adjustment of seat and backrest side bolsters and pneumatic adjustment of lumbar support; manual adjustment of headrest height and distance as well as belt height; including memory function for driver and front passenger seats as well as exterior mirrors and steering wheel)
- Heated seats front and rear
- Front and rear seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger on the climate control unit - additionally for the outer rear seats, separately adjustable in multiple stages)
- Allroad bumpers in contrasting paint finish (front and rear bumper lower section, wheel arch trims and side skirts painted in Manhattan Grey Metallic)
- Glazing: Acoustic glazing for the side windows
- Glazing: Acoustic glazing for the side windows (improved external noise insulation through double glazing)
- Glazing: Sun protection glazing, tinted
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Seats: Individual contour seat in front
- Seats: Seat ventilation and massage function in the front
- Seats: Front seat ventilation and massage function (Regulates ventilation in the center of the seat and backrest. Ensures a comfortable seating climate even at high outside temperatures. Air is drawn through the perforated leather of the seat and backrest center by a fan. The airflow strength is adjustable in three levels using the lower climate control panel. Protection against excessive cold is achieved through automatic heating. Available massage programs: Wave, Tapping, Stretch, Relaxation, Back, Shoulder, Activation, Vitalization)
- sunshade roller blind, manual
- Manual sunshade (for the rear door windows)
- Auxiliary heating/ventilation
- Auxiliary heater/ventilation (The auxiliary heater warms the interior and defrosts the windows without starting the engine. The auxiliary ventilation system supplies fresh air and lowers the interior temperature. Both functions can be activated via a timer and separate remote control. An intelligent control system with timer and departure time programming calculates the heating duration efficiently in terms of time and energy. Separate remote control with illuminated display. 2 selectable heating modes: - defrost (defrost mode for the windows only) - warm)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Sill - right side	Sill - dent(s) - Smart repair
2	Door - rear left side	Door (Radhausverbeiterung) - Scratched - Smart repair
3	Wing mirror - right side	Cap - Scratched - Smart repair
4	Side panel - rear right side	Wheel well extension - Differs from the original configuration - Un- / install
5	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
6	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
7	Side panel - rear left side	Wheel well extension - Scratched - Repair and paint
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Bonnet	Bonnet (Mehrere) - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Trim / covers	Boot lid - interior trim - Scratched - No deduction
3	Misc.	Inspection / maintenance (Unvollständig) - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof	113 µm	Boot lid / rear door	123 µm
Mudguard - left side	114 µm	Mudguard - right side	116 µm
Bonnet	123 µm	Side panel - rear left side	115 µm
Side panel - rear right side	201 µm	Door - rear left side	117 µm
Door - rear right side	115 µm	Door - front left side	107 µm
Door - front right side	111 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Interior - rear




Figure 9: Instrument cluster



Figure 10: Instrument panel



Figure 11: Instrument panel

Figure 12: Interior 360° view (Online Link)



Figure 13: Cargo area




Figure 14: VIN



Figure 15: Mounted tyres



Figure 16: Mounted tyres



Figure 17: Mounted tyres



Figure 18: Mounted tyres



Figure 19: Mounted tyres




Figure 20: Documents



Figure 21: Documents




Figure 22: Documents



Figure 23: Additional tyres



Figure 24: Navigation




Figure 25: Navigation



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.




Figure 39: Misc.




Figure 40: Misc.




Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.




Figure 44: Misc.




Figure 45: Misc.



Figure 46: Misc.



Figure 47: Misc.



Figure 48: Misc.



Figure 49: Misc.



Figure 50: Misc.




Figure 51: Misc.



Figure 52: Misc.



Figure 53: Misc.



Figure 54: Misc.




Figure 55: Diagonal front



Figure 56: Diagonal front




Figure 57: Diagonal rear



Figure 58: Diagonal rear




Figure 59: Engine compartment




Figure 60: Engine compartment



Figure 61: Sill



Figure 62: Sill




Damage 1: Sill - right side: Sill - dent(s) - Smart repair




Damage 1: Sill - right side: Sill - dent(s) - Smart repair



Damage 2: Door - rear left side: Door (Radhausverbeiterung) - Scratched - Smart repair



Damage 2: Door - rear left side: Door (Radhausverbeiterung) - Scratched - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratched - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratched - Smart repair



Damage 4: Side panel - rear right side: Wheel well extension - Differs from the original configuration - Un- / install



Damage 4: Side panel - rear right side: Wheel well extension - Differs from the original configuration - Un- / install



Damage 5: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Side panel - rear left side: Wheel well extension - Scratched - Repair and paint



Damage 7: Side panel - rear left side: Wheel well extension - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 9: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Wear and tear 2: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 2: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side