TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48111763
Order No. / Reference: 27009990
Inspection date: 25 Sept 2026

Manufacturer: Ford	Model: Kuga 2.0 EcoBlue Hybrid VIGNALE
VIN: WF0FXXWPMFLS88018	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.0 EcoBlue Hybrid VIGNALE	
Vehicle Identification number	WF0FXXWPMFLS88018
Mileage (Read)	125,416 km
First registration	15 Jan 2021
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,995 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Obsidian-Schwarz Met
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	35 %
Last service on / at	07/2026 at 121,263 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FY051742
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BTG 00026		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,155 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104W	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/60 R18 104W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 106H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	225/65 R17 106H	Winter tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Active Noise Compensation (Active Noise Control)
- Anti-lock braking system
- Electrically adjustable, heated and folding exterior mirrors (VIGNALE) (painted in body color - with memory function - with integrated turn signals and ambient lighting)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Fabric headliner
- Roof rails, silver-colored
- Diesel particulate filter
- Dual exhaust system
- Front door sill trim
- Lane keeping assist including lane keeping assist
- Electric front and rear windows (with quick-down function including all-around closing function)
- Ford EcoCoach (shows the efficiency of current driving behavior)
- Ford Power Start function & Ford Key Free system (keyless locking/unlocking)
- FordPass Connect (including eCall, live traffic information and Wi-Fi hotspot)
- Cruise control
- Illuminated glove compartment
- Heated rear window
- rear window wiper
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Front and rear headrests (5) height adjustable
- Paint finish: Mineral Silver Metallic
- Leather steering wheel, 3-spoke design
- Steering column, adjustable in height and reach
- Front center console with integrated armrest (2 front cup holders (illuminated) - 12-volt socket)
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Package: Winter II (Heated windscreen - Heated leather steering wheel - Heated outer rear seats)
- Pedal assembly with aluminum surface
- Upholstery: Premium leather upholstery (seat center panels and side bolsters in leather - driver's seat 10-way electrically adjustable with memory function and electrically adjustable lumbar support)
- Radio accessories: B&O Sound System (575 Watt premium sound system with 10 speakers, including subwoofer - based on the renowned sound and design expertise of Bang & Olufsen)
- Rear view camera
- Headlights with delayed shut-off
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Ambient lighting (front including front door storage, footwell and cup holder lighting with LED technology)
- Passenger airbag deactivation
- Tires: 7.5 J x 18 light alloy wheels (4) in 5x4 spoke design Luster Nickel premium paint finish (with tires 225/60 R 18)
- third brake light
- Overhead console with glasses storage compartment
- Roof spoiler (painted in car color)
- 12.3-inch digital instrument panel
- Tachometer
- Electronic Stability Program (ESP) (with hill start assist, traction control and emergency brake assist)
- Electric parking brake with auto hold function
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: 6-speed manual transmission
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Inductive charging station for mobile devices
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts in all seats, height-adjustable in the front - warning system for unfastened driver and front passenger seat belts)
- LED taillights
- Leather gear knob
- Rear center armrest with cup holder
- MyKey key system (individually programmable second key)
- Navigation system: Ford navigation system incl. Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth® hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - SMS text-to-speech function - Road map for Europe)
- Post-Collision Assist
- Pre-Collision Assist (including forward alert system (FA) with pedestrian and bicycle detection - active from approx. 5 km/h to 130 km/h, pedestrian and bicycle detection up to approx. 80 km/h.)
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Rear bench seat, sliding, with split-folding backrest

- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front seats, individually and variably heated
- Start-stop system
- Power outlet: 12-volt connection in the luggage compartment
- Immobiliser
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Static LED headlights (high beam assist - LED fog lights)
- Carpet floor mats front and rear
- Electric door child safety lock
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Package: Driver Assistance Package (Manual Transmission) (Intelligent Adaptive Cruise Control with Traffic Sign Recognition - Wrong-Way Driver Warning - Evasive Steering Assist - Driver Alert - Blind Spot Assist incl. Cross Traffic Alert - Active Park Assist with Parallel and Perpendicular Parking Function - Front Camera with Split View Technology - Door Edge Protection - Intelligent Speed Limiter with Speed Limit Display)
- Paint finish: Special metallic paint finish
- Reversible luggage compartment mat
- Fuel-operated auxiliary heater (including remote control)
- Mounting points behind the 1st row of seats according to ISO 27955 (required for the installation of the safety partition available as an accessory from your participating Ford dealer)
- Safety partition net (including attachment points behind the first and second rows of seats)
- Swiveling towbar (ESP trailer stabilization function)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Roof	Roof - dent(s) - Smooth repair work
3	Trim / covers	Brightware / decorative strip (Ausgeklippst) - Loose - Repair
4	Roof	Roof rail - right side - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 28 Aug 2023	858,90 €
2	Front, Provided by user / customer, from 7 Sept 2024	2.155,83 €

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des
Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Roof: Roof - dent(s) - Smooth repair work




Damage 2: Roof: Roof - dent(s) - Smooth repair work



Damage 3: Trim / covers: Brightware / decorative strip (Ausgeklippst) - Loose - Repair



Damage 3: Trim / covers: Brightware / decorative strip (Ausgeklippst) - Loose - Repair



Damage 4: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 4: Roof: Roof rail - right side - dent(s) - Smooth repair work