
1.0 TSI 95pk · 21 October 2026 · Schiphol


Specifications


License Plate Number	
Manufacturer	VOLKSWAGEN
Model	Polo
Model Versions	1.0 TSI 95pk
Body Type	5 door hatchback
Color	White
Paint Type	Matte
BPM	
Production Year	2023
KW	70
Fuel Type	Gasoline
VIN	WVWZZZAWZPU027609

Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie5
MOT	13-03-2027
First Admission	13-03-2023
First Registration	13-03-2023
License Plate 1a Avilable	
VAT/Marge	BTW
Odometer	186.478 Km
Numer Of Keys	1
Interior	Darkgrey - Cloth
Number Headrests	5

Images
























Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable & heated exterior mirrors
ASR	ESP
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Seat heating
Dimming interior mirror	Steering wheel multifunction

Condition

Condition exterior	Adequate	Maintenance Remarks	De onderhouds indicator is actief
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	Unknown		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Vredestein	185 mm	65 mm	15 inch	All Season
Rear Left	5 mm	Vredestein	185 mm	65 mm	15 inch	All Season
Front Right	4 mm	Vredestein	185 mm	65 mm	15 inch	All Season
Rear Right	5 mm	Vredestein	185 mm	65 mm	15 inch	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	6 mm					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Small dent(s)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Scratch(es)	Rim repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dent(s)	Kentekenplaat voorzijde vervormd	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Headlight – Left	Broken	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	Dent(s)	Replace & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Front	Scratch(es)	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Taillight – Left	Flat	Acceptable	Yes




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	small dents / small scratches	Dakstijl rechts deukjes lakbeschadigingen	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	small dents / small scratches	Dakstijl links deukjes krassen	Panelbeating & Spray	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Dent(s) & Scratch(es)	4 x deukje lakbeschadigingen	Panelbeating & Spray	No