TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48028319
Order No. / Reference: 27061298
Inspection date: 8 Oct 2026

Manufacturer: Audi	Model: A3 35 TFSI Sportback S tronic advanced
VIN: WAUZZZGY3RA008207	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 35 TFSI Sportback S tronic advanced	
Vehicle Identification number	WAUZZZGY3RA008207
Mileage (Read)	15,691 km
First registration	15 Aug 2023
Number of holders	2
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,498 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Manhattangrau Metallic (X7L)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-2 Monat(e)
Last service on / at	12/2025 at 12,292		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV320594
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BYB 00356		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,875 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Pirelli	8mm / 8mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Pirelli	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger (with front passenger airbag deactivation)
- Anti-lock braking system (ABS) (with electronic brake force distribution (EBD), hydraulic brake assist)
- Traction control ASR (prevents wheel spin by reducing engine power, thus providing more stability and improved traction on the road)
- Audi pre sense front (within system limits, uses a front radar to detect the area in front of the vehicle and warns the driver with visual and acoustic signals to indicate a potential hazard from vehicles ahead, whether moving or stationary – pedestrian and cyclist detection registers, within system limits, when a pedestrian or cyclist is moving on or crossing the road. The system then warns the driver with an acoustic and visual signal)
- Electrically adjustable and heated exterior mirrors (with integrated LED indicator lights - left mirror glass aspherical, right convex - including heated windshield washer nozzles)
- Exterior mirror housings in body color
- third brake light
- Headliner in steel grey fabric
- Decorative inlays in satin-effect lacquer, platinum grey (for instrument panel and center console)
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches (speed, time, mileage, outside temperature, fuel warning with remaining range, shift indicator (for manual and automatic transmissions in manual mode), current radio station or music track, radio and media lists, classic-style display; if available: telephone menu (in conjunction with multifunction steering wheel), trip computer with short- and long-term memory, fuel-saving tips for more economical driving including break recommendations)
- Electric windows front and rear
- Remote key (without Safe-Lock) (locks and unlocks doors, luggage compartment and fuel filler flap - including comfort closing/opening of windows)
- Speed limiter (assists you in maintaining a constant driving style and adhering to speed limits by adjusting the maximum speed)
- Electrically operated child safety lock
- i-Size child seat attachment and top tether for the outer rear seats
- Front headrests
- Light and rain sensor
- Mild hybrid (Mild hybrid features an enhanced start-stop function, extended energy recuperation during braking to charge the starter battery, and additional lithium-ion storage. This allows the system to recover more energy and switch off the engine more frequently. A supplementary belt-driven starter generator (BSG) is conceptually included for mild hybrid systems. Purely electric driving is not possible.)
- Airbag: Front side airbags with head airbag system and front interaction airbag (In addition to the front side airbags and the head airbags, an interaction airbag is installed at the front, which deploys within the system boundaries between the driver and front passenger seats if required)
- Audi connect Emergency Call & Service with m.connect Remote & Control (The Audi connect Emergency Call & Service services ensure a safe feeling on every journey. - Emergency call - Online breakdown call - Audi damage service - Audi service appointment online Audi connect Remote & Control: - Vehicle status - Remote locking/unlocking - Parking position - Remote control of auxiliary heating - Push notification of anti-theft alarm system)
- Evasive Steering Assist and Turning Assist (The Evasive Steering Assist can help the driver steer the vehicle around an obstacle in an evasive situation deemed critical. If the driver actively avoids the obstacle after the acute warning, the Evasive Steering Assist supports them by selectively braking the wheels and applying a small steering torque to correct the steering angle.)
- Roof edge spoiler
- Decorative trim strips in black glass look (accent area in the instrument panel around the MMI touch color display in black glass look)
- Tachometer
- Electric auxiliary air heater
- Electromechanical parking brake (includes parking brake function when stationary, starting aid by automatic release when starting off and emergency braking function while driving via all four wheels)
- Electronic Differential Lock (EDS)
- Electronic Stability Control (ESC)
- Chassis: Standard chassis (Standard comfort chassis with balanced tuning, for very good ride comfort with good driving dynamics.)
- Front and rear floor mats (made of velour in black)
- Removable luggage compartment cover
- Transmission: S tronic 7-speed
- rear window wiper
- Interior lighting (front and rear roof module, including reading lights (incandescent bulbs) - glove box lighting (incandescent bulb) - LED trunk lighting right)
- Rear headrests (3)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction controls and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with six multifunction buttons. Shift paddles allow manual gear changes.)
- Non-smoking version (with 12-volt socket and storage compartment)
- Otto particulate filter
- Tire pressure monitoring system (visual and audible warning in case of pressure loss in one or more wheels)
- Tire repair kit (with tire sealant and compressor)

- Radio: MMI Radio plus (10.1-inch color display (1,540 x 720) including MMI touch operation, digital instrument cluster with 10.25-inch color display, Audi music interface with two USB-C ports, each with data and charging function, Bluetooth interface (hands-free calling and audio streaming), passive speakers with 4 speakers in the front and 2 in the rear (80 watts), AM/FM phase diversity, DAB+ speed-dependent volume adjustment, voice control system for controlling infotainment and vehicle functions, WLAN hardware)
- Seats: Standard front seats (with manual adjustment of seat height, seat longitudinal position, backrest angle, headrest and seatbelt height)
- Lane Departure Warning (Within system limits, this helps prevent unintentional lane departures. If the system is activated, operational, and no turn signal has been used, the Lane Departure Warning assists by making corrective steering interventions to prevent crossing detected lane markings. Additional steering wheel vibration can be activated upon driver request. The system is functional from approximately 60 km/h.)
- Electromechanical power steering (with speed-dependent steering assistance)
- 3-point automatic seat belts (3-point automatic seat belts for all seats, pyrotechnic belt tensioners, belt height adjustment at the front, belt force limiters on all outer seats)
- Seat covers in fabric (seat center panel in fabric - seat side bolsters, front center armrest (if ordered) and headrests in solid black fabric)
- Seats: Rear seat backrest foldable (split, in a 40:60 ratio or fully foldable)
- Start-stop system
- 12-volt power outlet in the rear
- 12V socket
- Glazing: Green tinted heat-insulating glazing (for rear window, door and side windows - rear window heated, with timer)
- Electronic immobilizer

Extra equipment

- 3-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver, front passenger and rear - sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Assistance package with MMI Navigation plus with MMI touch (Audi pre sense front (pedestrian and cyclist detection) - High-beam assistant - Parking assistant with parking aid plus - Adaptive cruise assistant (supports the driver with acceleration, braking, maintaining speed and distance, and lane keeping) - Emergency assistant - Efficiency assistant - Camera-based traffic sign recognition - MMI Navigation plus with MMI touch (10.1-inch color display, natural language interaction, Audi connect Navigation & Info.) - Adaptive cruise control)
- Deletion of model designation and performance/technology lettering
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- LED headlights and LED taillights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights (to reduce glare in poor visibility conditions), motorway lights, static cornering lights, maneuvering lights (illumination of the maneuvering area at the front and sides when reversing), automatic dynamic headlight range control, intersection lights (in conjunction with MMI Nav. plus), dynamic rear turn signals, brake lights, tail lights, rear license plate lights, reversing lights)
- S line interior package (S tronic) (front sport seats with manual adjustment of seat height, seat fore/aft position, seat tilt, backrest tilt and seat belt height, as well as headrests; fabric Puls/mono.pur 550-K synthetic leather; 3-spoke leather steering wheel with multifunction plus and shift paddles including leather steering wheel grips; front and rear door armrests in synthetic leather; aluminum spectrum dark decorative inlays; illuminated front door sill trims with aluminum inlays and S lettering; black fabric headliner; front center armrest; stainless steel floor mats, pedals and footrest)
- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Seats: Driver's seat electrically adjustable, passenger seat manually adjustable (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt for the driver's seat)
- Ambient Lighting Package Plus (Glove box lighting (incandescent bulb), LED trunk lighting (right side), front/rear roof module including reading lights (LED), illuminated vanity mirrors (LED), entry lights on the underside of front doors (LED), front footwell lighting (LED), entry lights on the underside of rear doors (white), dashboard contour lighting (multicolor), ambient door lighting (front/rear, multicolor), door contour lighting (front/rear, multicolor), center console storage compartment (multicolor))
- Business package in conjunction with assistance package (USB ports with charging function in the rear - Audi connect Navigation & Infotainment plus - Audi phone box - Audi virtual cockpit plus - Smartphone interface (Android Auto and Apple CarPlay) - MMI Navigation plus with MMI touch - Cruise control)
- Comfort key without Safelock (The vehicle can be unlocked at all doors and the tailgate via wireless communication. The comfort key simply needs to be carried and does not need to be actively used. The vehicle can be locked again using the sensors on the door handles. The engine is started and stopped using the engine start/stop button.)
- High-beam assist (within the system's limitations, it automatically detects oncoming headlights, taillights of other road users, and light sources in built-up areas. Depending on the traffic situation, the high beams are automatically switched on or off. The system thus improves the driver's visibility and increases comfort.)
- Paint finish: Metallic
- Phone: LTE support for Audi phone box
- Seat covers in microfiber Dinamica/mono.pur 550 synthetic leather combination with S embossing (for front sport seats: - Seat center panels of the front seats and the two outer rear seats in microfiber Dinamica - Seat side bolsters, headrests, middle rear seat and front center armrest (if ordered) in mono.pur 550 synthetic leather - Contrast stitching and diamond quilting - S embossing in the backrests of the front seats)
- Seats: Rear seat backrest foldable (three-part), with center armrest (split in a 40:20:40 ratio or fully foldable; with center armrest and cupholders)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with twelve multifunction buttons. Shift paddles allow manual gear changes.)
- Telephone: Audi Phone Box (universal Bluetooth interface - convenient, integrated hands-free system - coupling antenna for connecting the mobile phone to the external antenna for improved reception quality - reduced radiation in the vehicle interior - LTE support - charging option via USB port or wireless charging (Qi standard) - forget-to-use warning - charging status indicator in the MMI touch display - connection of a second mobile phone)

- Telephone: Smartphone interface in conjunction with MMI Navigation plus with MMI touch (The smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display. Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI touch display and voice control. The connection can be established either using a suitable USB cable or wirelessly.)
- Wheel: Alloy wheels - 18 inch - 5-V spokes, polished (8.0 J × 18, tire 225/40 R 18)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Smart repair
2	Door - front left side	Door - dent(s) - Smart repair
3	Door - front right side	Door - Scratch(es) - Smart repair
4	Front bumper	Front bumper - Scratch(es) - Smart repair
5	Misc.	Inspection / maintenance - Due - Perform
6	Rear bumper	Rear bumper - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 9 Mar 2026	1.541,49 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair




Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair




Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 5: Misc.: Inspection / maintenance - Due - Perform



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Paint



Damage 6: Rear bumper: Rear bumper - Dent / paintcoat damage - Paint