MACADAM
Renault Arkana '21


Vehicle information


Make:	**Renault**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Arkana '21**	VIN:	**VF1RJL002UC314466**
Fuel type:	**Hybrid Petrol**	Power:	**105 kW**
Version:	**Arkana E-Tech 145 R.S.Line Aut**	First registration	**04/05/2022**
Mileage:	**188518 km**	N° of doors:	

Damage summary

Front	1
Interior	2
Left	5
Rear	4
Right	3

Commercial pictures










5.2
km/h
0
READY
Charge
My Sense
Gordel vastmaken
of zet motor uit


ARKANA


VF1RJL002UC314466

















Kijk in alle richtingen


15°
Gebruiker 1
15:23
NPO R1
Telefoon
Aanraakscherm



Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Hook	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Telephone equipment	**Yes**				


Damages


Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left






Boot lid covering R
Scratch(es)
Smart repair
Rear





Bumper corner RL
Scratch(es)
Repair and paint (complete)
Rear










Bumper corner RR


Scratch(es)

Repair and paint (complete)

Rear









Bumper F


Scratch(es)

Repair and paint (complete)

Front









Bumper R

Scratch(es)

Replace

Rear






Door RL
Deformed / Strained
Repair and paint (complete)
Left






Outside rear-view mirror housing R
Scratch(es)
Replace and paint
Right




Roof liner
Worn
Replace
Interior





Roof pillar L
Scratch(es)
Repair and paint (complete)
Left




Shutter / cover
Broken
Replace
Interior




Wing FL
Scratch(es)
Repair and paint (complete)
Left

Wing FR
Scratch(es)
Repair and paint (complete)
Right




Wing RL
Scratch(es)
Repair and paint (complete)
Left






Wing RR

Dent(s) and scratch(es)


Repair and paint (complete)

Right









Tyres

Front Left	
Winter	
215/55/18/99/V	
Bridgestone	
6.5 mm	
Front Right	
Winter	
215/55/18/99/V	
Bridgestone	
6.2 mm	
Rear Left	
Winter	
215/55/18/99/V	
Michelin	
7.5 mm	
Rear Right	
Winter	
215/55/18/99/V	
Michelin	
5.2 mm	

Checks

CO2 Emission	**96**	Digital maintenance	**Yes**
Luggage cover	**Yes**	Number head rests	**5**
Number of charging cables (rapid charge)	**0**	Number of keys total	**2**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Service book	**N/A**
User's manual	**Yes**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.