DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	VR3UPHMHD P5179581	Registration date	28/05/2024	Exterior Color	Unknown
Brand	PEUGEOT	Licence Plate	EU-FA 3183	Odometer	28 523 km
Model	208 PureTech 75 Active				

Inspection Details

Arrival Date	20/08/2026	Inspection ID	7126593	Inspection date	25/08/2026
Assign Date	20/08/2026	Fleet owner	Leasys FINN	Inspection loc.	Leasys AKB Schöneck



Generic equipment

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✗

Tyres

Maxxis 195/55/16 V All seasons 5.0 mm

Maxxis 195/55/16 V All seasons 5.0 mm





Maxxis 195/55/16 V All seasons 6.0 mm

Maxxis 195/55/16 V All seasons 6.0 mm

Exception / Damage

1



Part	Service	Repair Time	-	Part Cost	250.00€
Position	-	Repair Cost	-	Gross Cost	250.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**250.00€**

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Bumper	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Polishing	Flat Rate	50.00€	**Net Cost**	**50.00€**

3



Part	Door	Repair Time	-	Part Cost	-
Position	Back left	Repair Cost	-	Gross Cost	150.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	150.00€	**Net Cost**	**150.00€**

4



Part	Door	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	150.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	150.00€	**Net Cost**	**150.00€**

5



Part	Door	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	80.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	80.00€	**Net Cost**	**80.00€**

6



Part	Roof	Repair Time	-	Part Cost	-
Position	Centre	Repair Cost	-	Gross Cost	50.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Polishing	Flat Rate	50.00€	**Net Cost**	**50.00€**

Summary Inspection

Gross Price	730.00€	Depreciation	-	Net Price	730.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	250.00€	-	-	250.00€
Flat Rate	230.00€	-	-	230.00€