TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48408297
Order No. / Reference: 27216277
Inspection date: 28 Oct 2026

Manufacturer: Volkswagen	Model: Transporter T6.1 Kurz
VIN: WV1ZZZ7HZMH102107	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Transporter T6.1 Kurz	
Vehicle Identification number	WV1ZZZ7HZMH102107
Mileage (Read)	52,509 km
First registration	17 Aug 2021
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A) Uni
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Grey-Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	5,800 km
Last service on / at	02/2025 at 35,095 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC308945
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BXU 59330		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Steel rim with wheel cover	Goodyear	4mm / 4mm
2)	205/65 R16 107T	Winter tyres on Steel rim with wheel cover	Goodyear	5mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments and boxes (glove compartment with lockable flap)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors, left and right convex
- Floor coverings: Rubber floor covering in the driver's cab
- Tachometer
- Chassis: 16" chassis with 16" brake system
- Electric windows, front
- Transmission: 6-speed transmission
- Heating and ventilation system in the driver's cab
- Headrests (2)
- Paint finish: Solid
- Multi-collision brake
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Radio: Digital radio reception (DAB+)
- Radio accessories: 2 speakers (wideband)
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Crosswind assist
- Seat belts: Three-point automatic seat belts (height-adjustable on the outer seats in the driver's cab)
- Daytime running lights (continuously switched on while driving)
- Green thermal insulation glazing
- Registration as a truck
- Airbag for driver and front passenger (with front passenger airbag deactivation - seat belt tensioners for the outer seats)
- Hill Start Assist
- third brake light
- Electronic Stability Program (including ABS, ASR, EDS, Hill Start Assist, Brake Assist)
- Fresh air system with multi-stage fresh air blower (recirculation flap, center vents and defroster nozzles)
- Child safety lock, electrically operated
- Fuel tank with a 70-liter tank capacity
- Headlight range control
- Non-smoking version (12V socket and cup holder in the dashboard)
- "Composition Audio" radio with TFT display (monochrome) (USB interface, Bluetooth interface)
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Keys for locking system: 2 remote control flip keys
- Electromechanical power steering (speed-dependent control, steering column height and length adjustable)
- Start-stop system (with brake energy recuperation)
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation

Extra equipment

- Rigid towbar (including trailer stabilization)
- Batteries: 2nd battery with isolating relay
- Roof rails/roof load carrier: Mounting rails on the roof (preparation for sliding roof load carriers)
- Electrical interface
- Driver assistance systems: Front Assist area monitoring system with City Emergency Braking function
- Windows: Front window and closed rear side wall, in the cargo/ passenger compartment, right
- Fleet management system interface (electrical terminal block and function control unit 1 with body manufacturer (ABH) programming)
- Rear window with heat-insulating glazing, heated, and rear window wiper/washer system
- air conditioning system with electric control
- Steering wheel: Multifunction leather steering wheel (3 spokes)
- Retrofitting an alarm system
- Fog lights including cornering lights
- Upholstery: Robust fabric seat covers, "Robusta" design in the driver's cab (artificial leather, "Mesh" design for existing seats in the passenger compartment)
- Tire pressure monitoring system
- Mud flaps, front and rear
- Seat configuration - 3. Seat settings: Height adjustment for the left single seat in the driver's cab
- Seat configuration - 5. Armrests: Armrests for the left seat in the driver's cab
- Sortimo
- Telephone: Mobile phone interface "Comfort" (with inductive charging function)
- Water auxiliary heater
- Premium winter tires for vans, 205/65 R16 107/10
- Medium delivery package
- Braking systems: Electronic Stability Program, ABS, ASR (with deactivation button), EDS (Hill Start Assist, Brake Assist)
- Driver assistance systems: Rearview camera "Rear View" ((static lines))
- Chassis: Reinforced suspension, damping and stabilizers (suitable for rough roads) (permissible front axle load 1,680 kg)
- Total weight: Permissible total weight 3000 kg
- Cruise control system including speed limiter
- Glove compartment with light
- Rear wing doors with windows, heated (Rear wing doors with window cutouts - Rear wing door locking with unlocking function from inside - Rear window, heated - Safety interior mirror, dimmable)
- Multifunction display "Plus" with fatigue detection (Multifunction display "Plus" with black and white display)
- ParkPilot in the rear area
- Radio "Composition Colour" (Radio "Composition Colour" with 6.5" touchscreen, 2 USB ports (Type C) in the dashboard, 4 speakers: 2 tweeters, 2 woofers, App-Connect)
- "Transporter" lettering on the fender, no lettering on the rear
- Seat configuration - 4. Lumbar support: Lumbar support (manually adjustable) for single seat in the driver's cab, left.
- Power outlets: 2 12-volt sockets in the dashboard
- Partition walls: High partition wall with fixed window and 8 lashing rings for securing cargo (partition wall, high, with window - without child safety lock in passenger compartment - lashing rings for securing cargo, reinforced (ISO 27956))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Screen cleaning	Windscreen wiper blade - rear left side (Abdeckung) - Missing - Replace
2	Wheel / tyres	Wheel cover - front left side - Scratch(es) - Replace
3	Wheel / tyres	Wheel cover - front right side - Scratch(es) - Replace
4	Instrument panel	Centre console - front - Broken / torn - Replace
5	Equipment	Tirefit filler - Expired - Replace
6	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Smart repair
7	Trim / covers	Door trim - rear right side - Broken / torn - Replace
8	Tail light	Auxiliary brake light - Broken / torn - Replace
9	Body	Body - Glued / labelled - De-glue / neutralise
10	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front (Über 4mm) - No deduction
2	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Door - front right side	Door - dent(s) - No deduction
5	Boot lid / rear door	Rear door - right side - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Roof - Stub aerial

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Screen cleaning: Windscreen wiper blade - rear left side (Abdeckung) - Missing - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratch(es) - Replace



Damage 2: Wheel / tyres: Wheel cover - front left side - Scratch(es) - Replace



Damage 3: Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



Damage 3: Wheel / tyres: Wheel cover - front right side - Scratch(es) - Replace



Damage 4: Instrument panel: Centre console - front - Broken / torn - Replace



Damage 4: Instrument panel: Centre console - front - Broken / torn - Replace



Damage 5: Equipment: Tirefit filler - Expired - Replace



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 6: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 7: Trim / covers: Door trim - rear right side - Broken / torn - Replace



Damage 7: Trim / covers: Door trim - rear right side - Broken / torn - Replace



Damage 8: Tail light: Auxiliary brake light - Broken / torn - Replace



Damage 8: Tail light: Auxiliary brake light - Broken / torn - Replace



Damage 8: Tail light: Auxiliary brake light - Broken / torn - Replace



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 10: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 10: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 4: Door - front right side: Door - dent(s) - No deduction



Wear and tear 4: Door - front right side: Door - dent(s) - No deduction



Wear and tear 5: Boot lid / rear door: Rear door - right side - dent(s) - No deduction



Wear and tear 5: Boot lid / rear door: Rear door - right side - dent(s) - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Missing part 1: Roof: Stub aerial - Missing - Replace