MACADAM








Peugeot 408 (UKL): 2DSM266

Vinnumber:	**VR3FPHNSTPY567653**	Versionname:	**408 Allure 1.2 Puretech 130pk/cv 5p EAT8**
First Registrationdate:	**13/06/2023**	Fiscalpower:	
Expertise Mileage:	**147615**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**in 12900 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/17/99 V**			
	Fr.L.	**Vredestein: 5 mm**	Fr.R.	**Vredestein: 5 mm**
	Re.L.	**Vredestein: 5 mm**	Re.R.	**Vredestein: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/65 R 17 99 V**
Tyre size FR	**215/65 R 17 99 V**
Tyre size RL	**215/65 R 17 99 V**
Tyre size RR	**215/65 R 17 99 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**2480**
Tyre make RR	**2480**


Assistance equipment

Repair kit	**No**	Compressor	**Yes**

Seat cover FL, Worn, Acceptable




Interior, Dirty, Forfeit



Backrest cover FL, Hole, Smart repair



Ignition key, Not functioning (well), Acceptable



Bonnet, Stone chip(s), Acceptable



Central pillar L, Dent(s) and scratch(es), Acceptable



Wheel cover RL, Missing, Replace



Alloy rim FL, Scratch(es), Acceptable



Tyre repair kit, Missing, Replace



Bumper R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Repair and paint (complete)






Alloy rim RR, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Onderhoudshistorie van: VR3FPHNSTPY567653

ALPHABET

Kenteken	2DSM266
Merk Model	Peugeot 408 Allure 1.2 Puretech 130pk/cv 5p EAT8
Brandstofsoort	Benzine
Datum deel1	6/13/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/6/26	137,012	140000 km	Uitvoeren
8/6/26	137,012	luchtfilter interieur	Vervangen
8/6/26	137,012	oliezeef	Vervangen
8/6/26	137,012	ruitenwisserrubber vooraan	Vervangen
2/13/26	117,302	120000 km	Uitvoeren
2/13/26	117,302	bougie	Vervangen
2/13/26	117,302	luchtfilter	Vervangen
2/13/26	117,302	luchtfilter interieur	Vervangen
2/13/26	117,302	oliezeef	Vervangen
8/25/25	98,852	100000 km	Uitvoeren
8/25/25	98,852	distributieriem en spanner	Vervangen
8/25/25	98,852	luchtfilter interieur	Vervangen
8/25/25	98,852	oliezeef	Vervangen
8/25/25	98,852	remblokken vooraan	Vervangen
8/25/25	98,852	remvloeistof	Vervangen
8/25/25	98,852	riem of multiriem	Vervangen
8/25/25	98,852	ruitenwisserrubber vooraan	Vervangen
5/13/25	81,456	ruitenwisserrubber vooraan	Vervangen
4/29/25	78,526	80000 km	Uitvoeren
4/29/25	78,526	luchtfilter	Vervangen
4/29/25	78,526	luchtfilter interieur	Vervangen
4/29/25	78,526	oliezeef	Vervangen
4/29/25	78,526	remvloeistof	Vervangen
11/12/24	62,516	60000 km	Uitvoeren
11/12/24	62,516	luchtfilter interieur	Vervangen
11/12/24	62,516	oliezeef	Vervangen
5/22/24	41,132	40000 km	Uitvoeren
5/22/24	41,132	bougie	Vervangen
12/20/23	22,996	20000 km	Uitvoeren
12/20/23	22,996	luchtfilter interieur	Vervangen
12/20/23	22,996	oliezeef	Vervangen