TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

# Expertise

Protocol number: 48473261
Order No. / Reference: 27252799
Inspection date: 2 Nov 2026

| Manufacturer: Volkswagen | Model: Tiguan 1.4 eHybrid OPF DSG Elegance |
|---|---|
| VIN: WVGZZZ5NZNW407312 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Volkswagen Tiguan 1.4 eHybrid OPF DSG Elegance | |
| **Vehicle Identification number** | WVGZZZ5NZNW407312 |
| **Mileage** (Read) | 76,826 km |
| **First registration** | 30 Aug 2022 |
| **Number of holders** | 1 |
| **Fuel type** | Hybr.B/E ext.aufl |
| **Engine displacement / Cylinder** | 1,395 ccm / 4 |
| **Power** | 110 kW |
| **Gearbox / Number of gears** | Automatic / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | SUV |
| **Colour / colour code** | Pure White (C9A) |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Alcantara / cloth |
| **Colour of upholstery** | Black |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital evidence / incomplete | **Next maintenance in** | 12,400 km |
| **Last service on / at** | 06/2023 at 14,389 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GJ249604 |
| **Previous damage / Accident** | Detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 0603 / CNC 00276 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,350 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/50 R19 99V | Summer tyres on Light alloy | Hankook | 5mm / 5mm |
| 2) | 235/50 R19 99V | Summer tyres on Light alloy | Hankook | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R17 99V | Winter tyres on Light alloy | Dunlop | 8mm / 8mm |
| 2) | 215/65 R17 99V | Winter tyres on Light alloy | Dunlop | 8mm / 8mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Turning and bad weather lights
- Airbag: Head airbag system for front and rear passengers including front side airbags
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable and heated exterior mirrors (driver's side exterior mirror aspherical)
- Chrome applications on mirror adjustment switches, window regulator switches, door pull handles (interior door operation in matte chrome)
- Tachometer
- Parking aid (warning signals for obstacles in the front and rear area)
- Electronic stability program and electromechanical brake booster
- Electric windows front and rear
- Windscreen made of laminated safety glass, heat and sound insulating
- Tailgate with electric opening and closing, adjustable opening angle
- Interior mirror automatically dimming
- LED license plate lighting
- Air conditioning "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Front headrests (safety-optimized - adjustable lengthwise and height)
- LED matrix headlights with LED daytime running lights and cornering lights
- Light in the front footwell
- Front center armrest adjustable in height and length, with storage box and rear air vents
- Mains charging cable for household socket
- Emergency call service (no registration required, service is activated upon delivery)
- Package: Ambient lighting package (ambient lighting version 2 - chrome applications on mirror adjustment and window regulator switches, door pull handles; interior door controls in matt chrome - decorative inserts for instrument panel and front door trim - illuminated aluminum door sill trims at the front)
- Radio accessories: 8 speakers
- Rain sensor
- Tire pressure monitoring system
- Gearshift knob in leather
- Drawers under the front seats
- Electromechanical power steering (speed-dependent control)
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear including belt tensioner for the outer rear seats - warning tone and light for unfastened seat belts at the front and rear)
- Seats: Top comfort seats in the front
- Seats: Front seats with height adjustment
- Start-stop system with brake energy recuperation
- Power outlet: 2 USB-C ports on the front
- Bumpers in body color
- Airbag for driver and front passenger including knee airbag on the driver's side (passenger airbag deactivation - knee airbag on the driver's side)
- Adaptive Cruise Control ACC (DSG) (Adaptive Cruise Control ACC "stop & go", with speed limiter - Emergency Brake Assist "Front Assist" (for ACC up to 210 km/h))
- third brake light
- Silver anodized roof rails
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- e-Sound (artificially generated engine noise to inform other road users about the approach of the e-vehicle)
- Electronic parking brake including auto-hold function
- Automatic headlight control with LED daytime running lights ("Coming home" and "Leaving home" function)
- High beam control Light Assist
- Pedestrian detection
- Transmission: 6-speed DSG
- Rear window heated
- rear window wiper
- ISOFIX mounting points, also for i-Size child seats (device for attaching 2 child seats to the rear seats)
- Instrument cluster with electronic speedometer (odometer, trip meter, tachometer)
- Rear headrests (3)
- Mode 3 Type 2 charging cable, 16 A
- LED reading lights, 2 in the front and 2 in the rear
- Steering wheel: Multifunction leather steering wheel, heated, with paddle shifters
- Dynamic headlight range control (with dynamic cornering lights)
- Fatigue detection
- Non-smoking version (storage compartment and 12V socket at the front)
- Otto particulate filter
- Package: Chrome package (chrome trim on the side windows - silver anodized roof rails)
- Package: Winter (front windshield washer nozzles automatically heated - front seats heated)
- Padding: Microfleece
- Radio "Ready 2 Discover" incl. "Streaming & Internet" (20.3 cm TFT touchscreen - FM radio reception - Prepared for later activation: "Discover Media" navigation function incl. "Streaming & Internet" - Dual tuner with phase diversity for best possible radio reception - Radio Data System (RDS) - Radio station logos - MP3 playback - USB-C interface with Apple compatibility - Output power 4 x 20 watts - 3-band tone control - Telephone interface - Gesture control - Digital radio reception DAB+)
- Seats: Front passenger seat backrest folds down completely
- Seats: Lumbar support in the front

- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Seats: Rear bench seat asymmetrically split (longitudinally sliding and folding - with pass-through and center armrest)
- Lane keeping assistant “Lane Assist”
- 12-volt power outlet (on the rear center console and in the luggage compartment)
- Textile floor mats front and rear
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys

### Extra equipment

- Foldable towbar (electric release)
- Navigation system "Discover Media" incl. "Streaming & Internet" (20.3 cm TFT touchscreen - FM radio reception - Dual tuner with phase diversity for best possible radio reception - Radio Data System (RDS) - Radio station logos - MP3 playback - USB-C interface with Apple compatibility - 4 x 20 watt output power - Map with 2D display - 3-band sound control - Telephone interface - Traffic sign recognition - Points of interest - DAB+ digital radio reception)
- Rear View reversing camera
- Windows: Rear side windows and rear window tinted
- Paint finish: Uni Pure White
- Mesh partition
- Package: Business Premium (DSG) (App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Leather multifunction steering wheel, heated, with shift paddles - Automatically heated front windscreen washer nozzles - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats)
- Wheels: Alloy (4) "Auckland" 7 J x 19, Volkswagen R (in Dark Graphite, polished surface - AirStop tires 235/50 R 19 - wheel locks with enhanced theft protection)

### Retrofitted equipment

- Marten defense

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Inspection / maintenance - No evidence - No deduction |
| 2 | Wing mirror - right side | Cap - Scratch(es) - Smart repair |
| 3 | Indicator - front | Mirror - right side - Scratch(es) - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Main inspection - No evidence - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Front, Side - left, Side right, Provided by user / customer, from 17 Dec 2024 | 1.131,04 € |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Der beiliegende Winterradsatz ist nicht Bestandteil der Ausstattung.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents



**Figure 15:** Documents



**Figure 16:** Additional tyres




**Figure 17:** Navigation



**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.





**Figure 28:** Misc.




**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 3:** Indicator - front: Mirror - right side - Scratch(es) - Replace



**Damage 3:** Indicator - front: Mirror - right side - Scratch(es) - Replace