MACADAM

Ford Mustang '19 BEV

Vehicle information

Make:	**Ford**	License:	**N157DL**
Gearbox:	**Automatic**	Body color:	
Model:	**Mustang '19 BEV**	VIN:	**WF0TK1EMXMMA22319**
Fuel type:	**Electric**	Power:	**198 kW**
Version:	**Mustang EV 75kWh RWD St.Ran.**	First registration	**27/09/2021**
Mileage:	**94433 km**	N° of doors:	


Damage summary

Front	1
Left	1
Rear	1
Right	2

Commercial pictures










Rijbereik
322 km
Veiligheids-
gordels
OK
km/h
0
P
R
N
D
L
READY
94433.0km




WF0TK1EMXMMA22319




Continental




Continental










Batterijcertificaat
Datum van diagnose: 01/10/2026
94,5%
Status van de gezondheid (SOH)*
Ford Mustang MACH e
Standard Range
VIN : WF0TK1EMXMMA22319
Kilometerstand : 94.433 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA



Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Radio multimedia	**Yes**	Rear view camera	**Yes**	Telephone equipment	**Yes**

Damages

Bumper F
Scratch(es)
Repair and paint (complete)
Front




Bumper R
Scratch(es)
Repair and paint (complete)
Rear




Door FR
Dent(s) and scratch(es)
Repair and paint (complete)
Right




Door RL
Scratch(es)
Repair and paint (complete)
Left




Door RR
Scratch(es)
Repair and paint (complete)
Right




Tyres

Front Left
Summer
225/60/18/104/V
Continental
3.8 mm
Front Right
Summer
225/60/18/104/V
Continental
2.5 mm
Rear Left
Summer
225/60/18/104/V
Continental
2.9 mm
Rear Right
Summer
225/60/18/104/V
Continental
3.6 mm

Checks

Certificate of Conformity	**No**	CO2 Emission	**0**
Digital maintenance	**Yes**	GPS storage	**Yes**
GPS storage	**HD**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**N/A**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.