Mercedes

VIN: W1K5M8GBXPN340713



Description

Registration number 2CMN282	**First registration date** 16/09/2022	**Odometer** 85653 km
Color MOUNTAINGRAU - MET.	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1332	**Gearbox type** Automatic	**Engine type** Plug-in Hybrid
Number of gears 8	**Drivetrain** Front Wheel Drive (FWD)	**Max power** 160 KW

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

DEKRA

Vehicle Equipments

Standard

Seat Comfort package	comfort seats front	rear seat backrest split/folding
beverage holder front (dual)	steering wheel (Sport) with multiple function	light alloy rims
airbag driver side/passenger side	airbag passenger side deactivatable	lap airbag front (Pelvisbag)
kneebag driver side	sidebag front	transmission 8-speed - dual-clutch transmission DCT
body: 5-door	voice-command system extended functions (MBUX)	vehicle setup (online services / Apps)
USB connection in rear seat area	Electronic Stability Control (ESP)	tire pressure control system
charging cable with three-pin plug	radio reception digital (DAB)	direct steering with variable steering assistance
side skirt vehicle colour	windshield wiper with rain sensor	radiator grille diamond optic
hybrid 160 kW (engine 1,3 liter - 118 kW)	Keyless Go starting system	window lifter electric front + rear
Mercedes-Benz emergency call system	communication module (LTE) preparation Mercedes me connect	Moteur 1,3 litre(s) - 118 kW CGI Hybride
electric motor 75 kW (hybrid drive)	Light and Vision package	sun visors with mirror (illuminated)
tire 205/55 R17 ..W	power outlet (12V outlet) front	acoustic pedestrian protection (external sound)
cruise control (cruise control)	fuel tank: 105 liter	floor mats velours
vehicle monitoring (vehicle tracking system)	comfort suspension (Agility Control)	head airbag system (Sideguard)
antilock braking system (ABS)	driver assistance system: active brake assistant	driver assistance system: active lane-keeping assistant
driver assistance system: Multi-Sense (driving mode switch)	driver assistance system: speed limit display	multimedia system MBUX (digital multimedia system)
start/stop system	Touchpad (center console)	rear axle: torsion beam
central locking system with remote control	WSS Catégorie : Hybride	

Optional

alarm system for seat belts rear	change year with code 803	antenna for telephone (GPS)
lumbar support seat front left and right, electrically adjustable	reversing camera	multi-functional camera
active hood	automatic air-conditioning system	center console front with roll-up cover / tray
charging cable (7,0 m) with three-pin plug (mode 2)	Design and equipment line Progressive	interior equipment decorative trim inserts black
roof liner cloth	seat covers/upholstery: cloth / leather look	baggage net at front seatback
steering wheel (leather)	instrument cluster digital (virtual cockpit)	trailer coupling (pivoting ball head)
dual sun visors (sliding, extendable)	fire extinguisher	refrigerant R 1234 YF
roof liner black	Light-alloy rims	tire repair kit
Ligne d'échappement avec FAP essence - Generation 2.0	media display	moteur 4 cyl. en ligne essence M 282
low emissions according to emission standard Euro 6d	Parking package	driver assistance system: parking assistant (Active Park Assist)
mirror package	exterior mirror electrically folding	side/rear-view mirrows with automatic dimming
metallic paintwork	headlight LED High Performance	preparation car sharing
preparation digital radio	seat covers/upholstery: synthetic leather Artico	seat heating front
Smartphone integrated	Isofix mounts for child seat at rear seat	driver assistance system: traffic information system Live traffic
navigation system: hard disk navigation	charging system alternating current (AC)	infotainment system: Remote & Charging Services Plus
Transmission hybride 75 kW - 84 kW - version (compr. Plug-in)	steering wheel with shift rockers/buttons	radiator grille, active air doors
ambient lighting		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	22/10/2026	23/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Tyre / Front Right Tyre Brand : BRIDGESTONE / Width : 225 mm / Anti-puncture technology : None / Aspect ratio : 45 / Rim/Tyre diameter : 18 " / Season : Summer	Worn Out	Replace
	 		
002	Bumper / Back Painted : Yes	Scratched	Acceptable
	 		
003	Rear light (wing) / Back Left [1]	Defective	Warranty
	 		
004	Door sill / Back Right [2]	Scratched	Painting
	 		
005	Roof / -	Paint etching	Polishing
	 		

[1] Infiltration d'eau

[2] + enfoncement

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Slow charging cable (Type 2, Mode 2)
- [x] Quick charging cable (Type 2, Mode 3)
- [x] Load cover
- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Compressor tyre repair kit
- [x] Hook /Hicth ball
- [x] Spare Key
- [x] User manual
- [x] Document holder

Main set of tyres

Front Left	BRIDGESTONE	225/45/18 Summer	4 mm
Front Right	BRIDGESTONE	225/45/18 Summer	4 mm
Back Left	BRIDGESTONE	225/45/18 Summer	8 mm
Back Right	BRIDGESTONE	225/45/18 Summer	8 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment



Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation


Spare Tyre


Cable


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Cable




Vin



Other



Other



Other



Other



Tyre / Front Right / Worn Out



Tyre / Front Right / Worn Out



Bumper / Back / Scratched



Bumper / Back / Scratched




Rear light (wing) / Back Left / Defective



Rear light (wing) / Back Left / Defective



Door sill / Back Right / Scratched



Door sill / Back Right / Scratched



Roof / - / Paint etching

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Roof / - / Paint etching

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.