MACADAM









TESLA Model Y: 2CMZ470

Vinnumber:	**LRWYGCEK0NC452267**	Versionname:	
First Registrationdate:	**22/09/2022**	Fiscalpower:	
Expertise Mileage:	**115466**	Power Kw:	**370**
Bodytype:		Body colour	**Blue**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:	**4 Wheel-drive**		
Fueltype:	**Electric**		
Maintenance	**OK**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**4**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**No**		

Options

Number of keys total	**2**	Seats electric F L	
Number keys remote	**0**	Seats electric F R	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Board Computer		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather			
Seats F heated			
Type of headlighting	**Headlighting LED**		
Type of GPS	**GPS big screen color**		
Type of Lining	**Lining leather**		
Type of climate control	**Autom climate control**		
Type of radio	**Multimedia**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**255/45/19/104 V**			
	Fr.L.	**Goodyear: 6 mm**	Fr.R.	**Goodyear: 6 mm**
	Re.L.	**Goodyear: 5 mm**	Re.R.	**Goodyear: 5 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**255/45 R 19 104 V**
Tyre size FR	**255/45 R 19 104 V**
Tyre size RL	**255/45 R 19 104 V**
Tyre size RR	**255/45 R 19 104 V**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**2**

Total cost ex VAT	2390,68
Interior, Dirty, Acceptable	0,00




Backrest cover FL, Scratch(es), Smart repair	70,75






Backrest cover FR, Scratch(es), Smart repair	70,75







Bumper F, Scratch(es), Repair and paint (complete)	232,99






Fog lamp R, Scratch(es), Replace	132,00




Bonnet, Scratch(es), Acceptable	0,00




Alloy rim FL, Scratch(es), Repair and paint (complete)	161,12









Door FL, Scratch(es), Acceptable	0,00




Door RL, Scratch(es), Repair and paint (complete)	350,20



Wing trim RL, Scratch(es), Replace	15,84



Wing RL, Dent(s), Spot repair	183,21



Alloy rim RL, Scratch(es), Repair and paint (complete)	161,12



Roof pillar L, Scratch(es), Acceptable	0,00




Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00




Internal boot lining L, Scratch(es), Acceptable	0,00





Internal boot lining R, Scratch(es), Acceptable	0,00




Boot cover, Scratch(es), Acceptable	0,00





Boot lid covering R, Scratch(es), Acceptable	0,00









Tailgate / Boot, Scratch(es), Acceptable	0,00




Bumper R, Scratch(es), Acceptable	0,00





Wing RR, Scratch(es), Spot repair	183,21



Alloy rim RR, Scratch(es), Repair and paint (complete)	161,12



Wheel cover RR, Scratch(es), Replace	33,00




Door RR, Scratch(es), Acceptable	0,00



Door FR, Dent(s) and scratch(es), Spot repair	183,21



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)	242,20



Wing trim FR, Scratch(es), Replace	15,84



Alloy rim FR, Scratch(es), Repair and paint (complete)	161,12








Wheel cover FR, Scratch(es), Replace	**33,00**



