Audi

VIN: WAUZZZFY0L2112804



Description

Registration number 1YLK718	**First registration date** 29/09/2020	**Odometer** 109667 km
Color Manhattangrijs	**Model year** -	**Upholstery** -
Number of doors 5	**Number of seats** -	**Generation** -
Engine displacement 1968	**Max power** 100 KW	

Vehicle Equipments

Climate control	Rain-sensitive wipers	Automatic headlights
Electrically foldable door mirrors	Heated door mirrors	Heated seats
Park Assist	SATNAV	Cruise control
Alloy wheel rims	Rear-view camera	Hydraulic tail board

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 21/10/2026	**Inspection approval date** 22/10/2026


Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Doorframe seal / Lower Back Right	Tear	Replace
	 		
002	Door sill / Back Left [1]	Scratched	Painting
	 		
003	Wing / Back Left	Dent	Acceptable
	 		
004	Bumper / Back Painted : Yes	Scratched	Acceptable
	 		

[1] Avec enfoncement

Loose Items

- Load cover
- Registration certificate owner
- Hook /Hicth ball
- Conformity certificate
- Card key
- Spare Key
- Registration certificate
- Compressor tyre repair kit

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	HANKOOK	235/60/18 Summer	7 mm
Front Right	HANKOOK	235/60/18 Summer	7 mm
Back Left	MICHELIN	235/60/18 Summer	9 mm
Back Right	MICHELIN	235/60/18 Summer	9 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right




Odometer




Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Other



Doorframe seal / Lower Back Right / Tear



Doorframe seal / Lower Back Right / Tear



Door sill / Back Left / Scratched



Door sill / Back Left / Scratched




Wing / Back Left / Dent



Wing / Back Left / Dent



Bumper / Back / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.