
· 1.0 TSI 95pk R-Line Business · 21 October 2026 · Schiphol

## Specifications


| | |
|---|---|
| Manufacturer | VOLKSWAGEN |
| Model | Polo |
| Model Versions | 1.0 TSI 95pk R-Line Business |
| Body Type | 5 door hatchback |
| Color | Blue |
| Paint Type | Metallic |
| Production Year | 2024 |
| KW | 70 |
| Fuel Type | Gasoline |
| VIN | WVWZZZAW6RU030260 |

| | |
|---|---|
| Cylinder Capacity | 999 cm3 |
| Transmission Type | Handmatig geschakelde transmissie5 |
| MOT | 17-05-2028 |
| First Admission | 17-05-2024 |
| First Registration | 17-05-2024 |
| License Plate 1a Avilable | |
| VAT/Marge | BTW |
| Odometer | 81.041 Km |
| Numer Of Keys | 1 |
| Interior | Darkgrey - Cloth |
| Number Headrests | 5 |


## Images

























## Accessories

| | |
|---|---|
| ABS | Electric sliding roof |
| Airbags | Electric windows front |
| Alloy wheels | Electrically adjustable & heated exterior mirrors |
| ASR | ESP |
| Audio System | Front & rear parking sensors |
| Automatic air conditioning | Leather steering wheel |
| Bluetooth car kit | Navigation system |
| Central door locking | Rear view camera |
| Centre armrest | Roller cover / parcel shelf |
| Cruise control | Seat heating |
| Dimming interior mirror | Steering wheel multifunction |
| Electric rear windows | |

## Condition

| | |
|---|---|
| Condition exterior | Bad |
| Condition interior | Adequate |
| Last Maintenance | Unknown |

| | |
|---|---|
| Maintenance Remarks | De onderhouds indicator is actief |
| Previous Repairs | Unknown |
| Peculiarities | Diverse storingen ivm voorschade |

## Tire Specifications

| Tire | Profile | Brand | Width | Aspect Ratio | Radial | Type |
|---|---|---|---|---|---|---|
| Front Left | 3 mm | Vredestein | 195 mm | 55 mm | 16 inch | All Season |
| Rear Left | 6 mm | Vredestein | 195 mm | 55 mm | 16 inch | All Season |
| Front Right | 3 mm | Vredestein | 195 mm | 55 mm | 16 inch | All Season |
| Rear Right | 6 mm | Vredestein | 195 mm | 55 mm | 16 inch | All Season |
| Spare Tire Type | Compressor | | | | | |

## Notes

Verborgen schade voorzijde onder voorbehoud

## Damages




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Roof | Small dent(s) | Dakstijl links deukjes | Restyle | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Roof | Dent(s) | Panelbeating & Spray | No |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Interior | Burned | Vloerbekleding linksvoor schroeiplekken | Cloth Repair | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Mirror - leftside | Small scratch(es) | Acceptable | Yes |





| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Frontdoor – Left | Small dent(s) | Restyle | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Fender – Rear Left | Dent(s) | Panelbeating & Spray | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Bumper – Rear | Scratch(es) | Spray | No |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Roof | Small dent(s) | Dakstijl rechts 2 x deukje | Restyle | No |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Interior | Burned | Vloerbekleding rechtsvoor schroeiplek | Cloth Repair | No |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Interior | Damaged | Verduistering zonnedak defect | Repair | No |





| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Alloy – Right Front | Scratch(es) | Rim repair | No |





| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Fender – Front Right | Small dent(s) | Acceptable | Yes |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Frontdoor – Right | small dents / small scratches | Panelbeating & Spray | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Alloy – Left Front | Scratch(es) | Rim repair | No |




| Damage Part | Damage Type | Notes | Repair Type | Acceptable |
|---|---|---|---|---|
| Grille | Broken | Bovenlijst gebroken | Replace | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Bumper – Front | Broken | Replace & Spray | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Hood | Dent(s) | Panelbeating & Spray | No |




| Damage Part | Damage Type | Repair Type | Acceptable |
|---|---|---|---|
| Headlight – Left | Broken | Replace | No |





| Damage Part | Damage Type | Repair Type | Acceptable |
| --- | --- | --- | --- |
| Fender – Front Left | Replace due to repair | Replace & Spray | No |