Rapport d'inspection



PEUGEOT 5008

-

Immatriculation

VIN	VF3MRHPYERS015324
Kilométrage	58 421 km
Première immatriculation	02/02/2024
Couleur carrosserie	Noir

DÉTAILS DE L'INSPECTION

Adresse d'inspection

Adresse d'inspection

INFORMATIONS SUR LE VÉHICULE

Marque	PEUGEOT	Type de carrosserie	SUV
Modèle	5008	Nbre portes	5
VIN	VF3MRHPYERS015324	Nbre sièges	7
Première immatriculation	02/02/2024	Transmission	Avant
Kilométrage	58 421 km	Couleur intérieur	Noir
Catégorie	Vehicule particulier	Couleur carrosserie	Noir

DOCUMENTS ET CLÉS

Carnet d'entretien	Oui	Manuel d'utilisation	Oui
Nbre clés total	2	Certificat immatriculation (original)	N/A
Nbre clés télécommandes	2	Certificat immatriculation (original)	Non

OPTIONS

Batterie fonctionnante	Oui	Camera de recul	Oui
Moteur fonctionnant	Oui	Cache bagages	Oui
Véhicule roulant	Oui	Compresseur	Oui
Niveau carburant	75	Kit réparation	Oui
GPS	Oui	Nature de peinture	Metallisé

PNEUS

Pneus montés

Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	6,0 mm	Bridgestone	215/65 R 17 103 V	Hiver	Aluminium	Non
Avant	Droite	5,2 mm	Bridgestone	215/65 R 17 103 V	Hiver	Aluminium	Non
Arrière	Gauche	6,3 mm	Bridgestone	215/65 R 17 103 V	Hiver	Aluminium	Non
Arrière	Droite	5,3 mm	Bridgestone	215/65 R 17 103 V	Hiver	Aluminium	Non

Rapport d'inspection

DAMAGES




Wing RL

Damage type	Dent(s) and scratch(es)
Repair mode	Repair and paint (complete)




Wing RR

Damage type	Scratch(es)
Repair mode	Paint




Door RR

Damage type	Scratch(es)
Repair mode	Paint





Bumper corner RL

Damage type	Deformed / Strained
Repair mode	Repair and paint (complete)




Air vent, mid-dashboard

Damage type	Broken
Repair mode	Replace

Rapport d'inspection




Bumper moulding F

Damage type	**Broken**
Repair mode	**Replace**







Alloy rim RL

Damage type	**Scratch(es)**
Repair mode	**Repair/replace (lump sum)**




Wing trim RL

Damage type	**Scratch(es)**
Repair mode	**Repair/replace (lump sum)**




Wing trim RR

Damage type	**Scratch(es)**
Repair mode	**Repair/replace (lump sum)**

Rapport d'inspection




Door trim RR

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)




Door trim FR

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)




Internal boot lining L

Damage type	Scratch(es)
Repair mode	Smart repair




Internal boot lining R

Damage type	Scratch(es)
Repair mode	Smart repair






Seat cover FL

Damage type	Stain
Repair mode	Cleaning

Rapport d'inspection




Alloy rim FL

Damage type	Scratch(es)
Repair mode	Acceptable






Alloy rim RR

Damage type	Scratch(es)
Repair mode	Acceptable






Alloy rim FR

Damage type	Scratch(es)
Repair mode	Acceptable




Door RL

Damage type	Scratch(es)
Repair mode	Polish

Rapport d'inspection







Bumper spoiler F

Damage type	Unclasped
Repair mode	Dismount/Mount







Door FR

Damage type	Scratch(es)
Repair mode	Polish





Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Polish





Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Acceptable

Rapport d'inspection

COMMERCIAL PHOTOS























