TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48507634
Order No. / Reference: 27230238
Inspection date: 3 Nov 2026

Manufacturer: Volvo	Model: XC90 T8 AWD Recharge Geartronic Inscription Edition
VIN: YV1LFH5UDN1871602	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volvo XC90 T8 AWD Recharge Geartronic Inscription Edition	
Vehicle Identification number	YV1LFH5UDN1871602
Mileage (Read)	123,055 km
First registration	20 Jul 2022
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,969 ccm / 4
Power	228 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Savile Grau-Metallic
Doors / Seats	5 / 7
Upholstery type	Leather
Colour of upholstery	Anthracite-Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	193 Tag(e)
Last service on / at	05/2026 at 110,495 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ550293
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	9101 / BUL 00007		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,950 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	275/40 R21 107V	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	275/40 R21 107V	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	275/40 R20 110V	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	275/40 R20 110V	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS - Anti-lock Braking System
- Airbags
- All-wheel drive (AWD)
- Ambient lighting
- Dashboard and door trim in leather look with contrasting stitching
- Electrically folding exterior mirrors
- Heated exterior mirrors and rear window (automatic)
- Attachment system for carrier bags in the luggage compartment
- Fog sensor for automatic activation of the defroster function
- On-board computer
- third brake light
- Chrome trim on the door handles
- Chrome trim strip in the door sill area with Recharge lettering
- Connected Safety
- Roof spoiler
- Tachometer
- Driver Alert - Attention Warning
- Electronic differential lock
- Electronic stability control
- Chrome window surround
- Bottle holder in the luggage compartment
- Luggage compartment partition net
- Transmission: 8-speed Geartronic automatic transmission
- Automatic tailgate
- Heated rear window
- Interior and exterior mirrors automatically dimming
- Intelligent driver information system
- IntelliSafe Surround
- Keyless Drive
- Child lock
- Air conditioning for the 3rd row of seats
- Headrests of the 2nd row of seats can be folded down (electrically)
- Steering wheel adjustable for height and reach
- Steering wheel: Multifunction buttons on the steering wheel
- Front center armrest including cup holder
- Emergency brake lights
- Electric parking brake
- Radio: Sensus Connect infotainment system with high-performance sound
- Radio accessories: Two USB-C ports on the back of the center console
- Road Edge Detection
- Run-off Road Protection
- Rear view camera
- Gearshift lever made of Swedish crystal glass by Orrefors
- Heated windshield washer nozzles
- Whiplash Protection System (WHIPS)
- Speed-sensitive power steering
- Seats: Adjustable (electric) leg rest for driver and front passenger seats
- Passenger side airbag can be deactivated
- Active safety belts with belt tensioners
- Aluminum loading sill protector in the luggage compartment
- Armrests with integrated storage compartment and cup holders for the 3rd row of seats (left and right)
- Electrically adjustable exterior mirrors
- Outdoor temperature display
- Hill Descent Control (HDC)
- Hill Start Assist (HSA)
- LED turn signals integrated into the exterior mirrors
- Brake energy recuperation
- Chrome applications on the rear of the vehicle
- Chrome applications in the front bumper
- City Safety
- CleanZone air quality system with activated carbon filter
- Aluminum roof rails (integrated)
- Digital Instrumentation
- Drive Mode
- Aluminum door sill plates with Recharge lettering, front (illuminated) and rear
- Electric windows front and rear
- Automatic emergency braking
- Front grille in waterfall design in chrome
- Cruise control system with variable speed limiter
- Seat belt height adjustment front and rear (2nd row of seats)
- rear window wiper
- Interior lighting
- IntelliSafe Assistant
- ISOFIX mounting for the outer rear seats
- Keyless Start
- Automatic climate control with 4-zone temperature control
- Headrests (7)
- Charging cable Schuko / Type 2 (Mode 2), 4.5 m length
- Cargo area roller blind (semi-automatic)
- Steering wheel: Steering wheel heating
- Illuminated makeup mirror for driver and front passenger
- Sensus navigation system
- Oncoming Lane Mitigation
- Pollen filter
- Radio accessories: Smartphone integration Apple CarPlay and Android Auto
- Rain sensor with automatic light function
- Tire pressure monitoring system
- Road Sign Information (RSI) - Traffic Sign Recognition
- Wheels: Tire sealant
- Rear seat backrests can be folded down in a 60/40 split or completely.
- Headlight cleaning system
- Sensus Connect infotainment system

- Seats: Driver and passenger seats electrically adjustable
- Seats: Lumbar support (4-way electrically adjustable) for driver and front passenger seats
- Sun blinds for the rear side windows (integrated)
- Storage compartment under the cargo floor
- subwoofer
- Textile floor mats
- Lashing eyes in the luggage compartment (foldable)
- Volvo On Call with Wi-Fi hotspot
- Warning tone/indicator when seat belts are not fastened (for all seats)
- Safety braking system with disc brakes all around (internally ventilated)
- Seats: Third row of seats (7-seater)
- Seats: Driver and front passenger seats are height-adjustable (electrically)
- Seats: Heated front seats
- Start/Stop technology
- Power socket
- Textile floor mat for the 3rd row of seats
- First aid kit and warning triangle
- Full LED headlights "Thor's Hammer" ACTIVE HIGH BEAM
- Preparation for Trailer Stability Assist (TSA)
- Immobiliser
- Central locking system with two remote controls and integrated emergency keys

Extra equipment

- Alarm system (with motion/tilt sensor, safety locking and private locking (separate glove compartment and trunk locking))
- Paint finish: Metallic paint
- Park Assist Pilot (Intelligent parking assistant for parallel and perpendicular parking spaces (left and right) as well as exiting parallel parking spaces. Steering is controlled by the assistant, acceleration and braking by the driver. The parking space must be at least 1.2 times the length of the vehicle. - Front and rear parking aid)
- Parking camera with 360° surround view
- Upholstery: Nappa leather comfort seats (front seats perforated) (with active ventilation and electrically adjustable side bolsters for driver and front passenger seats including rear center armrest (2nd row of seats))
- Glazing: Acoustic glazing for the side windows (UV and burglar-resistant laminated glass panes)
- Glazing: Side and rear windows tinted (from the B-pillar back)
- Towbar (semi-electric)
- Windscreen, heater
- Child safety lock for the rear doors (electric)
- Package: Xenium Package (Panoramic glass sunroof with lifting function and integrated, continuously adjustable sunshade (electric) - Sun blinds for the rear side windows (integrated) - High Performance Sound Pro audio system by Harman/Kardon: - 600 watts of power - 14 speakers - Fresh Air Subwoofer - Dirac Unison sound optimization - Enhanced air quality system with fine dust filtration according to PM2.5 air quality standard)
- Wheels: 21" 8-multi-spoke design alloy wheels, diamond cut/black (tires 275/40 R21; rims 9 x 21")
- Seats: Heated rear seats (outer seats of the 2nd row)
- Phone: Inductive smartphone charging system (Wirelessly charges smartphones that support the QI standard on a charging pad)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front left side	Door - Dent / paintcoat damage - Paint
3	Front bumper	Front bumper - Damaged - Repair and paint
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace
6	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Scratch(es) - Replace
7	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Body	Body (Waschstraßenkratzer) - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.




Figure 43: Misc.



Figure 44: Misc.




Figure 45: Misc.




Figure 46: Misc.



Figure 47: Misc.



Figure 48: Misc.




Figure 49: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 2: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 3: Front bumper: Front bumper - Damaged - Repair and paint



Damage 3: Front bumper: Front bumper - Damaged - Repair and paint




Damage 3: Front bumper: Front bumper - Damaged - Repair and paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace




Damage 5: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace



Damage 5: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratch(es) - Replace




Damage 6: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratch(es) - Replace




Damage 7: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratch(es) - Replace




Damage 7: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratch(es) - Replace



Wear and tear 3: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - No deduction



Wear and tear 3: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - No deduction



Wear and tear 3: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - No deduction