TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48098024
Order No. / Reference: 26745185
Inspection date: 14 Oct 2026

Manufacturer: Opel	Model: Astra Sports Tourer 1.5 D Automatik Business Edition
VIN: VXKFCYHZ0R1019221	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Astra Sports Tourer 1.5 D Automatik Business Edition	
Vehicle Identification number	VXKFCYHZ0R1019221
Mileage (Read)	64,631 km
First registration	24 Apr 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Karbon Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	1,000 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB442705
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / AEY 00109		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,980 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94H	All-season tyres on Light alloy	Hankook	1mm / 1mm
2)	205/55 R16 94H	All-season tyres on Light alloy	Hankook	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94V	Summer tyres (Without wheel rim)	Michelin	3mm / 3mm
2)	205/55 R16 94V	Summer tyres (Without wheel rim)	Michelin	3mm / 3mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (storage compartment in the center console, in the front doors suitable for 1.5-liter beverage bottles, in the rear doors suitable for 0.5-liter beverage bottles, glove compartment with LED lighting)
- Airbag: Front and rear outer head airbags
- Anti-lock braking system (ABS) (including brake assist)
- Exterior mirrors, electrically adjustable, heated and manually foldable
- Exterior mirror housings in black
- On-board computer
- Roof design line, in black
- Tachometer
- Electronic brake force distribution (EBD)
- Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Back window, heater
- Cable set for trailer hitch
- Front headrests and 3 rear headrests, height adjustable
- Paintwork: Roof in car color
- LED headlights (LED headlights - LED daytime running lights - LED taillights - LED turn signals - manual headlight range control - high beam assist - automatic low beam - rain sensor)
- Steering wheel heating
- Multimedia Infotainment System (with 10" color touchscreen display and 10" driver information display, automatic music recognition, Bluetooth audio streaming, hands-free calling, simultaneous pairing of 2 mobile phones, wireless smartphone integration via Apple CarPlay and Android Auto, personalization options, 4x20 watts, favorite station memory (24 per profile), speed-dependent volume control, FM/AM, DAB+, RDS-EON, 2 USB-C ports, breakdown and emergency call, vehicle status and information)
- Rear seat backrest folds forward in a 40:20:40 split
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Heated seats for driver and front passenger (multi-stage adjustable)
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)
- 12V power outlet in the center console
- Pre-installation for ISOFIX child seat mounting system (incl. top tether attachment points, rear outer)
- Central locking with remote control (and interior switch)
- Airbag: Chest-pelvis side airbags, driver and front passenger (side airbag, front passenger can be manually deactivated)
- Airbag: Front airbags, driver and front passenger (front passenger airbag can be manually deactivated)
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag or seatbelt pretensioner)
- Hill Start Assist
- third brake light
- Diesel particulate filter (DPF) maintenance-free (exhaust aftertreatment via SCR (Selective Catalytic Reduction) catalyst with AdBlue (urea injection). Vehicles with BlueInjection technology require refilling of the AdBlue fluid between regular service intervals. A display in the vehicle informs the driver in good time when refilling is necessary.)
- Transmission: 8-speed automatic transmission
- rear window wiper
- Automatic climate control (single-zone automatic climate control with particle and activated carbon filter)
- LED interior lighting (including reading lights, front and rear, and trunk lighting)
- Steering wheel: Leather steering wheel, flat-bottomed, perforated, with steering wheel remote control and paddle shifters
- Illuminated makeup mirrors in both sun visors
- Fog light
- Opel Vizor with frame in high-gloss black
- Electric parking brake
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Tire pressure monitoring system
- Wheels: Alloy wheels 7 J x 16 (5 double spokes) in silver (with low rolling resistance tires 205/55 R 16)
- 180-degree reversing camera (parking pilot, front and rear parking aid)
- Keyless Start system
- Seats: Ergonomic active driver's seat in Modene fabric (certified by the German Campaign for Healthy Backs (AGR) - adjustable length, height, tilt, backrest angle, and seat cushion angle - electro-pneumatically adjustable lumbar support in height and length - extendable thigh support - Modene fabric, black - heated front seats and heated steering wheel)
- Start/Stop system (Driving assistant - Reinforced starter - AGM high-performance battery - eco switch to deactivate the start/stop function - Brake energy recuperation)
- Electronic immobilizer

Extra equipment

- Paint finish: Metallic
- safety net
- Navigation system (Multimedia infotainment system with 10" color touchscreen display and 10" driver information display; navigation system with integrated memory; 3D map display for Europe and Russia; dynamic route guidance via map and/or arrow display and voice prompts; TomTom Online Traffic; online POI search and route guidance; parking information; fuel price information; live weather; over-the-air map updates; intelligent voice control; "Hey Opel" shortcut button; 6 functions; active route suggestions)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Misc.	Inspection / maintenance - No evidence - No deduction
3	Mudguard - right side	Mudguard - right side - dent(s) - Smooth repair work
4	Side panel - rear left side	Side panel (Klebereste / hartz) - Paint defect - Smart repair
5	Engine	Engine cover - Damaged - Replace
6	Door - front left side	Door edge - Scratch(es) - Smart repair
7	Bonnet	Insulation lining - Damaged - Replace
8	Wheel / tyres	Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace
9	Side panel - rear right side	Side panel - Scratch(es) - Paint
10	Front bumper	Front bumper - Stone chips - Paint
11	Rear bumper	Rear bumper (+ Verätzung) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Body	Body - Scratch(es) - No deduction
4	Documents	Service book (serviveheft vorhanden steht nichts drin) - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)




Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster




Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Damage 3: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work



Damage 3: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work




Damage 4: Side panel - rear left side: Side panel (Klebereste / hartz) - Paint defect - Smart repair



Damage 4: Side panel - rear left side: Side panel (Klebereste / hartz) - Paint defect - Smart repair



Damage 5: Engine: Engine cover - Damaged - Replace



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 7: Bonnet: Insulation lining - Damaged - Replace



Damage 7: Bonnet: Insulation lining - Damaged - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace




Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 8: Wheel / tyres: Tyres - complete set (einseitig abgefahren) - Does not meet the leasing specifications - Replace



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 10: Front bumper: Front bumper - Stone chips - Paint



Damage 10: Front bumper: Front bumper - Stone chips - Paint



Damage 10: Front bumper: Front bumper - Stone chips - Paint




Damage 10: Front bumper: Front bumper - Stone chips - Paint



Damage 10: Front bumper: Front bumper - Stone chips - Paint



Damage 10: Front bumper: Front bumper - Stone chips - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper (+ Verätzung) - Scratch(es) - Paint