MACADAM








Seat Ateca (UKL): 2CAN972

Vinnumber:	**VSSZZZ5FZN6533944**	Versionname:	**Ateca Move! 1.0TSi 110pk/cv 5p**
First Registrationdate:	**12/05/2022**	Fiscalpower:	
Expertise Mileage:	**96443**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**over 11500 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/55/17/98 W**			
	Fr.L.	**Vredestein: 4 mm**	Fr.R.	**Vredestein: 5 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/55 R 17 98 W**
Tyre size FR	**215/55 R 17 98 W**
Tyre size RL	**215/55 R 17 94 V**
Tyre size RR	**215/55 R 17 94 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**259**
Tyre make RR	**259**


Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Engine insulation, Hole, Replace




Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable



Step L, Dent(s) and scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair and paint (complete)






Internal boot lining L, Scratch(es), Acceptable





Internal boot lining R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable






Bumper R, Scratch(es), Acceptable






Bumper R, Scratch(es), Spot repair





Bumper trim R, Scratch(es), Acceptable




Tailgate / Boot, Dent(s), Paintless dent repair











Door RR, Scratch(es), Acceptable






Door FR, Scratch(es), Acceptable




Bodywork, Not original part, Remove lettering



Onderhoudshistorie van: VSSZZZ5FZN6533944

ALPHABET

Kenteken	2CAN972
Merk Model	Seat Ateca Move! 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	5/12/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/5/26	92,471	klein materiaal	
5/5/26	92,471	nazicht technische keuring	Uitvoeren
5/5/26	92,471	ruitenwisserrubber achter	Vervangen
5/5/26	92,471	ruitenwisserrubber vooraan	Vervangen
10/23/25	82,666	diagnose	Uitvoeren
10/23/25	82,666	klein materiaal	
10/23/25	82,666	koelwatervloeistof	Bijvullen/-laden
10/23/25	82,666	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
10/23/25	82,666	remschijven en blokken achter	Vervangen
10/23/25	82,666	remvloeistof	Vervangen
10/23/25	82,666	ruitenwisservloeistof	Bijvullen/-laden
7/25/24	54,384	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
7/25/24	54,384	bougie	Vervangen
7/25/24	54,384	klein materiaal	
7/25/24	54,384	koelwatervloeistof	Bijvullen/-laden
7/25/24	54,384	luchtfilter interieur	Vervangen
7/25/24	54,384	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
7/25/24	54,384	ruitenwisservloeistof	Bijvullen/-laden
4/29/24	47,423	klein materiaal	
4/29/24	47,423	ruitenwisserrubber achter	Vervangen
4/29/24	47,423	ruitenwisserrubber vooraan	Vervangen
6/30/23	25,792	klein materiaal	Uitvoeren
6/30/23	25,792	koelwatervloeistof	Bijvullen/-laden
6/30/23	25,792	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
6/30/23	25,792	ruitenwisservloeistof	Bijvullen/-laden
4/25/23	20,448	controle niveaus	Uitvoeren
4/25/23	20,448	klein materiaal	
4/25/23	20,448	koelwatervloeistof	Bijvullen/-laden
4/25/23	20,448	olie bijvullen	Bijvullen/-laden
4/25/23	20,448	ruitenwisservloeistof	Bijvullen/-laden