DEKRA

DEKRA Automotive Solutions


Condition Report

Vehicle details

VIN	ZAC5JACL2 SJL93043	Mileage	43 957 km	Engine (Fuel) Type	Petrol
Licence Plate	2HDY621	Registration date	17/06/2025	Engine size	1199
Brand	JEEP	Fuel level	-	Transmission	Manual
Model	Avenger-2023	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	29/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Rear parcel shelf	✔
Spare wheel kit	✖

Tyres

Goodyear 215/60/17 V All seasons 7.0 mm

Goodyear 215/60/17 V All seasons 7.0 mm



Goodyear 215/60/17 V All seasons 7.0 mm

Goodyear 215/60/17 V All seasons 7.0 mm



Damages

1



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

2



Part	Door
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	90.00€

4



Part	Wing extension moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	162.90€

ovb, vervangen

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Wing
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

6



Part	Door
Position	Back right
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	198.00€
	x2

7



Part	Door sill
Position	Back right
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

8



Part	Spare wheel kit
Position	-
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	100.42€

9



Part	Tailgate / Boot door
Position	Back
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

10



Part	Wiper blade
Position	Back
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	27.69€

Summary Inspection

Net Price (Exclusing VAT)	628.01€