TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48111337
Order No. / Reference: 27113669
Inspection date: 13 Oct 2026

Manufacturer: Ford	Model: Transit Custom 280 L1H1 LKW VA Trend
VIN: WF0YXXTTGYLT42087	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 280 L1H1 LKW VA Trend	
Vehicle Identification number	WF0YXXTTGYLT42087
Mileage (Read)	73,059 km
First registration	23 Jun 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	White University
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	25,000 km
Last service on / at	11/2025 at 61,921 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GE465775
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BMU 06024		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Winter tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm
2)	215/65 R15 104T	Winter tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Summer tyres on Steel	Goodyear	6mm / 6mm
2)	215/65 R15 104T	Summer tyres on Steel	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R15 104T	All-season tyres on Steel	Goodyear	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Headliner in driver's cab (up to the partition wall to the cargo area)
- Tachometer
- Electronic Stability Program (ESP) with Traction Control System (TCS) (Hill Start Assist - Crosswind Assist - Emergency Brake Assist - Rollover Protection)
- FordPass Connect (including live traffic information and Wi-Fi hotspot: Information about the current status or location of the vehicle, as well as control of selected vehicle functions via smartphone with the FordPass app. Real-time traffic information (in conjunction with audio systems 24 and 25). Wi-Fi hotspot (up to 4G/LTE, for up to 10 mobile devices). Further information about FordPass Connect can be found at https://www.ford.de/fordpass-connect.)
- Front air conditioning (including dust and pollen filter)
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"
- Steering column, adjustable in height and reach
- Package: Style color package (front and rear bumpers and exterior mirror caps painted in body color)
- Front and rear parking pilot system including fog lights
- Radio: Audio system 13 additionally with DAB/DAB+ (Radio (FM/AM) - Four speakers, antenna - Audio remote control on the steering wheel - Bluetooth, USB port and hands-free system - MyFord Dock - additionally with digital radio reception DAB/DAB+ (Digital Audio Broadcasting))
- Sliding door entry light automatically illuminates when the door is opened
- Sliding door: Sliding door, right
- Side protection strips
- Power steering
- Start-stop system
- Power outlet: 12-volt connection
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- On-board computer (with consumption and mileage information (e.g. remaining range) and outside temperature display)
- Double-leaf rear door with 180° opening angle (without window)
- Third brake light
- Front electric windows (with quickdown/up function for driver's side)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Generator, 240 A
- Cruise control including leather steering wheel (with adjustable speed limiter)
- Transmission: 6-speed transmission
- Lockable glove compartment with lid
- Interior lighting with delay function (with reading lights at the front)
- Cargo area lighting with activatable switch-off delay (after 30 minutes)
- Emergency brake assist including emergency brake light (pulsating illumination of the brake lights during hard braking)
- Particulate filter: diesel particulate filter
- Wheel trims
- Wheels/Tires: Spare wheel, steel wheel
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires (6.5 J x 15 with 215/65 R 15 tires)
- Headlights: Halogen projector headlights (with LED daytime running lights and fog lights with static cornering lights)
- Mud flaps front and rear
- Low side paneling
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened driver's seat belt)
- Front bumper in body color
- Immobiliser
- Central locking with remote control
- Second key with remote control

Extra equipment

- Airbag (passenger side)
- Seats: Seat Package 15 - Partition (load-through hatch), with window (Custom Truck Trend) (Driver's seat, 4-way adjustable (forward/ backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (fold-out) - Heated driver's seat - Heated passenger seat (outer seat) - Inner armrest for driver - Manual lumbar support (driver's seat) - TREND seat cover: fabric - Partition with window and load-through hatch)
- Visibility Package III (Electrically adjustable and heated exterior mirrors - Heated windscreen - Windscreen washer fluid sensor - Electrically folding exterior mirrors - Rain-sensing wipers - Automatic headlights with day/night sensor - Lane Keeping Assist with Driver Alert and High Beam Assist - Rearview camera - Connected Radio audio system, DAB/DAB+, FordPass Connect 8" touchscreen, antenna control panel and audio remote control on the steering wheel - Android Auto and Apple CarPlay support)
- Parking heater, programmable, with remote control

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Brightware - Scratch(es) - Smart repair
2	Trim / covers	Door trim - front left side - Scratch(es) - Smart repair
3	Door - front left side	Door - Scratch(es) - Smart repair
4	Boot lid / rear door	Rear door - right side (+ Flugrost-Mehrkosten möglich) - Scratch(es) - Conditioning
5	Door - front right side	Door - Dent / paintcoat damage - Smart repair
6	Roof	Roof - Dent / paintcoat damage - Loss in value
7	Mudguard - right side	Mudguard - right side - Corrosion - Smart repair
8	Trim / covers	Trim / covers - Broken / torn - Loss in value
9	Door - front left side	Brightware - lower - Scratch(es) - Replace
10	Sliding door, right	Sliding door - Dent / paintcoat damage - Smart repair

Wear and tear

No.	Component group	Description
1	Multimedia system	Navigation data storage - Missing - No deduction
2	Trim / covers	Boot lining - Dent / paintcoat damage - No deduction
3	Side panel - rear left side	Side panel - Dent / paintcoat damage - No deduction
4	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - No deduction
5	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
6	Vehicle glazing	Windscreen - Stone chips - No deduction
7	Side panel - rear right side	Sill - Dent / paintcoat damage - No deduction
8	Instrument panel	Centre console - front - Scratch(es) - No deduction
9	Sill - right side	Sill - Scratch(es) - No deduction
10	Bonnet	Bonnet - dent(s) - Smooth repair work
11	Wheel / tyres	Wheel cover - front right side - Scratch(es) - No deduction
12	Headlight	Headlight - right side (nicht im Lichtfeld) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	180 µm	Door - front left side	263 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 1: Side panel - rear left side: Brightware - Scratch(es) - Smart repair




Damage 1: Side panel - rear left side: Brightware - Scratch(es) - Smart repair




Damage 2: Trim / covers: Door trim - front left side - Scratch(es) - Smart repair



Damage 2: Trim / covers: Door trim - front left side - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side (+ Flugrost-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 4: Boot lid / rear door: Rear door - right side (+ Flugrost-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 4: Boot lid / rear door: Rear door - right side (+ Flugrost-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 4: Boot lid / rear door: Rear door - right side (+ Flugrost-Mehrkosten möglich) - Scratch(es) - Conditioning



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Smart repair




Damage 5: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 6: Roof: Roof - Dent / paintcoat damage - Loss in value



Damage 6: Roof: Roof - Dent / paintcoat damage - Loss in value



Damage 7: Mudguard - right side: Mudguard - right side - Corrosion - Smart repair



Damage 7: Mudguard - right side: Mudguard - right side - Corrosion - Smart repair



Damage 8: Trim / covers: Trim / covers - Broken / torn - Loss in value



Damage 8: Trim / covers: Trim / covers - Broken / torn - Loss in value



Damage 8: Trim / covers: Trim / covers - Broken / torn - Loss in value



Damage 8: Trim / covers: Trim / covers - Broken / torn - Loss in value



Damage 8: Trim / covers: Trim / covers - Broken / torn - Loss in value



Damage 9: Door - front left side: Brightware - lower - Scratch(es) - Replace




Damage 9: Door - front left side: Brightware - lower - Scratch(es) - Replace



Damage 9: Door - front left side: Brightware - lower - Scratch(es) - Replace



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair




Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair




Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Wear and tear 7: Side panel - rear right side: Sill - Dent / paintcoat damage - No deduction



Wear and tear 10: Bonnet: Bonnet - dent(s) - Smooth repair work



Wear and tear 10: Bonnet: Bonnet - dent(s) - Smooth repair work



Wear and tear 11: Wheel / tyres: Wheel cover - front right side - Scratch(es) - No deduction



Wear and tear 11: Wheel / tyres: Wheel cover - front right side - Scratch(es) - No deduction



Wear and tear 12: Headlight: Headlight - right side (nicht im Lichtfeld) - Scratch(es) - No deduction



Wear and tear 12: Headlight: Headlight - right side (nicht im Lichtfeld) - Scratch(es) - No deduction



Wear and tear 12: Headlight: Headlight - right side (nicht im Lichtfeld) - Scratch(es) - No deduction



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Repainting 2: Door - front left side



Repainting 2: Door - front left side