APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	BMW
Model / version:	3 SERIES TOURING
Vin:	WBA6N91020FM83712
Plate:	2BXU061
Mileage:	129250
SOH:	
First registration:	03/05/2022
Color:	MINERALGRAU

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?




DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES


















































VIN INFORMATION

10 Haut-parleurs	Transmission automatique	8 rapports
Projecteurs antibrouillard à LED	Equipement Advantage	Matière : alliage
Lettre repère (J)	Diamètre avant 17	Diamètre arrière 17
Largeur avant 7,5	Largeur arrière 7,5	Diamètre avant 17
Diamètre arrière 17	Hauteur avant 50	Hauteur arrière 50
Indice de vitesse avant Y	Indice de vitesse arrière Y	Largeur avant 225
Largeur arrière 225	Climatisation automatique 2 zones	Climatisation réfrigérant 1234YF
Store de portes arrière	Euro 6	Minérale vernissée
Rétroviseur gauche jour/nuit automatique	Rétroviseur droit jour/nuit automatique	Rétroviseurs rabattables électriques
Rétroviseur intérieur jour/nuit automatique	Siège avant gauche chauffant	Sièges avant chauffants
Siège avant gauche à réglage lombaire	Sièges avant à réglage lombaire	Garnitures tissu

Volant cuir	Volant sport	Aide au stationnement avant
Aide au stationnement arrière	Assistance au parking	Caméra avant
Caméra arrière de recul	Régulateur automatique de la distance	Alarme
Appel de secours	Lunette arrière teintée foncée	Vitres de portes avant acoustiques
Vitres portes arrière teintées foncées	Vitres de portes arrière acoustiques	Vitres de custode teintées foncées
Toit ouvrant électrique	Toit ouvrant vitré panoramique	Attelage avec boule rétractable électrique
Airbag passager désactivable	Protection piéton	Alerte franchissement de ligne (AFIL)
Assistant maintien de la voie	Freinage d'urgence assistée autonome (urbain)	Avertisseur d'angle mort
Avertisseur de collision avant	Contrôle pression des pneus	depuis 04.22
mesures CO2 étendues	système d'accès confort	Teleservices
tuner DAB	BMW Live Cockpit Professional	appuis-tête ar rabattables
pack de rangement	pack équipement coffre	protection acoustique des piétons
1998 cc (2,0 L) 120 KW (essence) / 83 KW (électrique)	encarts intérieurs argent Quartz mat nervuré	spécifique Europe

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		225/50R17 98Y	Summer		?
Front right	5 mm		225/50R17 98Y	Summer		?
Rear left	5 mm		225/50R17 98Y	Summer		?
Rear right	5 mm		225/50R17 98Y	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key	Not original part
2	Bumper F	Broken
4	Alloy rim FL	Grooved
5	Door FL	Grooved
6	Alloy rim RL	Grooved
7	Bumper R	Grooved
8	Rear spoiler	Scratch(es)
9	Alloy rim RR	Grooved
10	Outside rear-view mirror housing R	Grooved
11	Door FR	Dent(s)
12	Door RL	Grooved

Total: 11

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Contact key - Not original part



2 - Bumper F - Broken






4 - Alloy rim FL - Grooved




5 - Door FL - Grooved





6 - Alloy rim RL - Grooved






7 - Bumper R - Grooved







8 - Rear spoiler - Scratch(es)




9 - Alloy rim RR - Grooved






10 - Outside rear-view mirror housing R - Grooved




11 - Door FR - Dent(s)





12 - Door RL - Grooved





3 - Bodywork - Dent(s) and scratch(es) - Renta®















SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

03/11/2026 12:11