APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	VOLVO
Model / version:	XC40
Vin:	YV1XZBWVFM2571708
Plate:	2AGE807
Mileage:	160023
SOH:	
First registration:	24/03/2021
Color:	Denim Blue M

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	?

PICTURES




















































VIN INFORMATION

Radio	Système navigation	14 haut-parleurs
Téléphone	Transmission automatique	7 rapports
Pommeau de levier de vitesses cuir	Traction avant	Projecteurs directionnels
Projecteurs à LED	Projecteurs antibrouillard	Entourage de vitres chromé
Matière : alliage	Lettre repère (J)	Diamètre avant 19
Diamètre arrière 19	Largeur avant 7,5	Largeur arrière 7,5
Chauffage stationnaire	Climatisation automatique 2 zones	Essence
1477 cm3	1.50 litre	115 kw
156 ch	Métallisée vernissée	Pièces livrées peintes
Freins avant à disques	Rétroviseur gauche jour/nuit automatique	Rétroviseur droit jour/nuit automatique
Rétroviseur intérieur jour/nuit automatique	Aide au stationnement arrière	Caméra avec vision à 360°

Régulateur automatique de la distance
détecteur de pluie essuie-vitre
Avertisseur d'angle mort
sièges baquet av
airbag passager désactivable

pack éclairage intérieur
pare-chocs av/ar "Type Momentum"

CAB CHARG SCHUKO 10A
système "Plug-in"

Ouverture du coffre électriquement
Barres de toit
depuis n°châssis 495 494
grille de calandre active Shutter-System
ceintures de sécurité de type B

poignées de portes éclairées
attache-remorque semi-électrique rabattable avec prise à 13 broches
sortie d'échappement double cachée

Pare-brise chauffant
Airbag de genoux
Keyless Entry
rétroviseurs électrique "8D08"
ceintures de sécurité à avance électrique "ERR"
grille de calandre "Type Inscription"
1477 CC 95/60 KW

Thaïlande

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		235/55R18 104V	Winter	Aluminium	×
Front right	5 mm		235/55R18 104V	Winter	Aluminium	×
Rear left	5 mm		235/55R18 104V	Winter	Aluminium	×
Rear right	5 mm		235/55R18 104V	Winter	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Alloy rim FL polished	Chemical polution
3	Alloy rim RL polished	Chemical polution
4	Bumper trim R	Grooved
5	Alloy rim RR polished	Grooved
6	Alloy rim FR polished	Grooved
7	Bumper F	Grooved
8	Bumper moulding F	Dent(s) and scratch(es)

Total: 7

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Alloy rim FL polished - Chemical polution



3 - Alloy rim RL polished - Chemical polution



4 - Bumper trim R - Grooved



5 - Alloy rim RR polished - Grooved



6 - Alloy rim FR polished - Grooved



7 - Bumper F - Grooved



8 - Bumper moulding F - Dent(s) and scratch(es)



2 - Bodywork - Scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

22/10/2026 09:23

