TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48197752
Order No. / Reference: 27094715
Inspection date: 19 Oct 2026

Manufacturer: Skoda	Model: Karoq 2.0 TDI 4x4 DSG Selection
VIN: TMBLJ7NU5R5046664	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Karoq 2.0 TDI 4x4 DSG Selection	
Vehicle Identification number	TMBLJ7NU5R5046664
Mileage (Read)	83,964 km
First registration	19 Sept 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Blau Race Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	5,900 km
Last service on / at	02/2026 at 59,867 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HG792298
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / ASQ 05019		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,180 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97V	Summer tyres on Light alloy	Sonstige	4mm / 4mm
2)	225/55 R17 97V	Summer tyres on Light alloy	Sonstige	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Steel	Bridgestone	7mm / 7mm
2)	215/60 R16 99H	Winter tyres on Steel	Bridgestone	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (ticket holder on the windshield, closed storage compartment on the dashboard, 4 roof grab handles, rear with coat hooks, coat hooks on the B-pillar, high-visibility vest compartment in the front doors, sunglasses compartment in the headliner, storage compartments in the front door panels with 1.5L bottle holders, cup holders in the front center console, storage pockets on the front seatbacks, storage compartment including umbrella under the passenger seat, storage compartments behind the wheel arches in the trunk, storage compartment on the left wheel arch)
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Illuminated trunk
- Hydraulic brake assist (HBA)
- Diesel particulate filter
- Easy Start (start-stop button)
- Electronic parking brake including auto-hold function
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor ((tunnel light, coming and leaving home function))
- Front radar assistant including city emergency braking function with pedestrian detection
- Tinted windows
- Illuminated glove compartment
- Heated rear window
- Automatic interior mirror dimming
- Interior Design Loft (seat covers in black fabric - dashboard and door trim in black - "Unique Chrome" trim strip - "Anodized Cross" door trim - headliner in grey)
- Trunk cover, fixed
- Front and rear headrests are height-adjustable.
- LED brake light in the rear spoiler
- LED headlights with daytime running lights
- Steering wheel with multifunction buttons including paddle shifters (height and length adjustable)
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Fog light
- Rear parking sensors
- Radio accessories: Digital radio reception DAB+
- Tire mobility kit (tire repair spray incl. compressor)
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable
- Electromechanical power steering
- Seats: Adjustable lumbar support in the front seats
- Seats: Height-adjustable front seats
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Sun visor on driver and passenger side with illuminated vanity mirror
- Speed limiter
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Allergen filter
- Permanent all-wheel drive
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Attention and fatigue detection
- Electrically folding exterior mirrors including interior and driver's side mirrors with automatic dimming
- Exterior mirrors and door handles painted in body color
- Hill start assist
- Roof rails, black
- Digital Cockpit (8")
- eCall (automatic emergency call function in case of an accident with airbag deployment)
- ESC Electronic Stability Control
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- Cruise control
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec (start/stop system and brake energy recuperation)
- Aero rear window wiper including windshield washer system
- ISOFIX preparation on the outer rear seats (including top tether)
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger)
- Paint finish: Solid
- LED taillights in crystal glass look (and animated turn signals)
- Reading lights at the front of the headliner
- Rear center armrest with cup holders and pass-through option
- Multi-collision brake
- Package: Infotainment Basic (music system (Bolero) and 8" color display - Wireless SmartLink - voice control)
- Radio accessories: USB port in the center console (Type-C)
- Wheels: 17" alloy wheels Scutus (4x4) (wheels 7J x 17, ET 45 - tires 225/55 R17 97V)
- Karoq safety belts (Height-adjustable three-point front seat belts with belt tensioners - 3 three-point rear seat belts - Belt fastening indicators for front and outer rear seats)
- Skoda Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in case of an accident with airbag deployment) - Mobility service (connection option for quick assistance in case of breakdown) - Information service (connection option to the hotline for all questions about vehicle functions) - Free remote vehicle access for 3 years)
- Sunset (rear window and rear side windows tinted dark)
- Textile floor mats
- Lashing eyes in the trunk

- Lane keeping assistant (Lane Assist)
- 12V socket - in the center console
- Bumpers partially painted in body color
- Telephone: Comfort hands-free telephone system
- Traffic sign recognition
- Preparation for a trailer hitch (including trailer stabilization)
- Central locking with remote control
- Immobiliser

Extra equipment

- Swiveling trailer hitch with electric release (including trailer stabilization)
- Luggage net partition
- Kessy (keyless entry and start-stop system)
- Paint finish: Metallic
- Package: Driving Assistance (DSG) (Predictive Adaptive Cruise Control pACC (control range up to 210 km/h) - Adaptive Lane Keeping Assist - Traffic Sign Recognition - Capacitive Steering Wheel with Hands Off Detection - USB-C Charging Port on the Interior Mirror - Emergency and Traffic Jam Assist)
- Package: Light & Sight (Matrix LED headlights - LED ambient lighting and footwell lighting, boarding spot logo projector on the front doors - Dynamic Light Assist)
- Skoda Infotainment Online (online map updates for navigation - display of weather data, news, headlines - petrol stations and parking space search and much more)
- Winter complete wheels
- Design Selection Lodge (fabric seat covers, black/grey - dashboard and door trim in black - "Piano Black" trim strip - "Linear Dynamic" door decor - grey headliner - driving profile selection)
- Steering wheel: Heated steering wheel (leather steering wheel with multifunction buttons including paddle shifters)
- Package: Infotainment Plus (Dynamic radio navigation system (Columbus) and 9.2" color display - Digital Cockpit Plus - Wireless SmartLink - Voice control - Phonebox with inductive charging function - Infotainment Online (3-year term))
- Package: Parking (front and rear parking sensors - reversing camera)
- Package: Winter PLUS (Heated front and outer rear seats - Headlight cleaning system - Heated windshield)
- Auxiliary heating
- Variable loading floor in the trunk

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smart repair
2	Door - front right side	Door - dent(s) - Smart repair
3	Door - rear left side	Door - dent(s) - Smart repair
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 10 Jul 2026	1.691,68 €

Repainting

No.	Repainting
1	Door - rear left side, Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear left side	178 µm	Door - front left side	212 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Damage 1: Door - front right side: Door - dent(s) - Smart repair



Damage 1: Door - front right side: Door - dent(s) - Smart repair



Damage 2: Door - front right side: Door - dent(s) - Smart repair



Damage 2: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Door - rear left side: Door - dent(s) - Smart repair



Damage 3: Door - rear left side: Door - dent(s) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Repainting 1: Door - rear left side, Door - front left side



Repainting 1: Door - rear left side, Door - front left side



Repainting 1: Door - rear left side, Door - front left side



Repainting 1: Door - rear left side, Door - front left side