SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-GBT-699

2-GBT-699 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 27 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-GBT-699
Manufacturer	TOYOTA
Model	Corolla Cross
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	103

Fuel Type	Hybrid Gasoline
VIN	JTNADADB50J022009
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	17-10-2024
Odometer	65.705 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images



























UNIROYAL




Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction


Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	4 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages

Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Stootlijst	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Scratch(es)	Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Right	Scratch(es)	Stootlijst	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Stootlijst	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Replace	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Small scratch(es)	Hoekje	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small dent(s)	Restyle	No