TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48514018
Order No. / Reference: 27208543
Inspection date: 29 Oct 2026

Manufacturer: Ford	Model: Focus Turnier 1.0 EcoBoost Hybrid TITANIUM
VIN: WF0PXXGCHPMC82184	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.0 EcoBoost Hybrid TITANIUM	
Vehicle Identification number	WF0PXXGCHPMC82184
Mileage (Read)	72,159 km
First registration	23 Nov 2021
Number of holders	1
Next periodical technical inspection	11/2026
(Report on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	999 ccm / 3
Power	92 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Obsidian-Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	19 %
Last service on / at	03/2025 at 49,342 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD592321
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BUC 00110		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,970 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92V	Summer tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/60 R16 92V	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Light alloy	Semperit	5mm / 5mm
2)	205/60 R16 92H	Winter tyres on Light alloy	Semperit	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Electrically folding exterior mirrors
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 6.5 J x 16 design wheels (4) with 205/60 R16 tires (in 10-spoke design, in black-silver)
- Roof rails, aluminum
- Tachometer
- Driver information system with on-board computer, color (10.7 cm screen diagonal)
- Electronic parking brake
- FordPass Connect including eCall, live traffic information (only with navigation) and Wi-Fi hotspot
- Cruise control
- Illuminated glove compartment
- rear window wiper
- Interior mirror, automatically dimming
- Isofix mount
- Headrests: 2 front and 3 rear, height adjustable
- LED taillights
- LED headlights (LED low beam - LED high beam - LED daytime running lights incl. integrated LED turn signals at the front - LED cornering lights, static, incl. integrated LED fog light function and maneuvering light)
- Center console "Premium" front
- Navigation: Ford SYNC 4 including Ford navigation system with AppLink, 13.2" touchscreen and DAB/DAB+ (13.2" touchscreen (33 cm) - 6 speakers - Android Auto and Apple CarPlay - Steering wheel controls - Digital owner's manual - Bluetooth hands-free calling and audio streaming - USB ports - Voice control for audio and phone - Ford Power-Up software updates - Intelligent route suggestions - Customizable user profiles - Radio player - Audible and visual route guidance, dynamic and cloud-based navigation with advanced traffic information system, lane guidance and road map for Europe)
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest
- Seats: Front sports seats with enhanced lateral support
- 12-volt power outlet in the luggage compartment
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Attachment points behind the second row of seats for mounting the safety partition net
- Hill start assist
- Fabric headliner
- Roof spoiler painted in car color
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric windows front and rear
- Ford Power Start function
- luggage compartment cover
- Speed limiter
- Transmission: 6-speed manual transmission
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Leather gear knob
- Steering wheel: 3-spoke design
- Adjustable steering column
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Otto particulate filter
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist
- Tire repair kit (for use at a maximum speed of 80 km/h)
- Tire Pressure Monitoring System (TMPS)
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Headlight assistant with day/night sensor
- Electromechanical speed-dependent power steering
- Seats: Passenger seat, 2-way adjustable
- Seats: Map grid on the driver's and front passenger's seat backrests
- Start-stop system
- Carpet floor mats in the front
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats

Extra equipment

- Paint finish: Metallic
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)
- Winter complete wheels Ford alloy wheel, 2203007

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection (11.2026 fällig) - No evidence - No deduction
2	Equipment	Tirefit filler - Expired - Replace
3	Sill - left side	Sill - dent(s) - Smart repair
4	Door - front left side	Door (Innen Rahmen) - Dent / paintcoat damage - Smart repair
5	Engine	Engine (Mehrkosten können entstehen) - Leaking - Perform diagnosis
6	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
7	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
8	Side panel - rear left side	Side panel - Scratch(es) - Paint
9	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
10	Door - rear left side	Door - Scratch(es) - Paint
11	Door - rear right side	Door - Scratch(es) - Paint
12	Door - front left side	Door - Scratch(es) - Paint
13	Door - front right side	Door - Scratch(es) - Paint
14	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Abrasion - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Front, Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Documents



Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Sill - left side: Sill - dent(s) - Smart repair




Damage 3: Sill - left side: Sill - dent(s) - Smart repair



Damage 3: Sill - left side: Sill - dent(s) - Smart repair



Damage 4: Door - front left side: Door (Innen Rahmen) - Dent / paintcoat damage - Smart repair



Damage 4: Door - front left side: Door (Innen Rahmen) - Dent / paintcoat damage - Smart repair



Damage 4: Door - front left side: Door (Innen Rahmen) - Dent / paintcoat damage - Smart repair



Damage 5: Engine: Engine (Mehrkosten können entstehen) - Leaking - Perform diagnosis



Damage 5: Engine: Engine (Mehrkosten können entstehen) - Leaking - Perform diagnosis




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 7: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 7: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 7: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 7: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 7: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 8: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 8: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 8: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint




Damage 10: Door - rear left side: Door - Scratch(es) - Paint




Damage 11: Door - rear right side: Door - Scratch(es) - Paint



Damage 11: Door - rear right side: Door - Scratch(es) - Paint



Damage 11: Door - rear right side: Door - Scratch(es) - Paint




Damage 11: Door - rear right side: Door - Scratch(es) - Paint




Damage 12: Door - front left side: Door - Scratch(es) - Paint



Damage 12: Door - front left side: Door - Scratch(es) - Paint




Damage 12: Door - front left side: Door - Scratch(es) - Paint



Damage 12: Door - front left side: Door - Scratch(es) - Paint




Damage 13: Door - front right side: Door - Scratch(es) - Paint



Damage 13: Door - front right side: Door - Scratch(es) - Paint




Damage 13: Door - front right side: Door - Scratch(es) - Paint




Damage 14: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 14: Vehicle glazing: Windscreen - Broken / torn - Replace




Wear and tear 1: Side panel - rear right side: Side panel - Abrasion - Cover / polish




Wear and tear 1: Side panel - rear right side: Side panel - Abrasion - Cover / polish




Accident 1: Front, Side right




Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right




Accident 1: Front, Side right




Accident 1: Front, Side right




Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right



Accident 1: Front, Side right