TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

# Expertise

Protocol number: 48363425
Order No. / Reference: 27204961
Inspection date: 26 Oct 2026

| Manufacturer: Opel | Model: Grandland 1.5 D Automatik Ultimate |
|---|---|
| VIN: W0VZCYHZ4P6013184 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Opel Grandland 1.5 D Automatik Ultimate | |
| **Vehicle Identification number** | W0VZCYHZ4P6013184 |
| **Mileage** (Read) | 93,946 km |
| **First registration** | 25 Aug 2023 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,499 ccm / 4 |
| **Power** | 96 kW |
| **Gearbox / Number of gears** | Automatic / 8 |
| **Type of drive** | Front drive |
| **Type of vehicle** | SUV |
| **Colour / colour code** | Diamant Schwarz Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Alcantara / Leather |
| **Colour of upholstery** | Black-Anthracite |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | Available / complete | **Next maintenance in** | 27,700 km |
| **Last service on / at** | 08/2026 at 91,680 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GS834691 |
| **Previous damage / Accident** | Detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 1844 / AHG 00256 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,000 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/55 R16 98V | Summer tyres on Light alloy | Semperit | 6mm / 6mm |
| 2) | 225/55 R16 98V | Summer tyres on Light alloy | Semperit | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R17 99H | Winter tyres on Light alloy | Continental | 6mm / 6mm |
| 2) | 215/65 R17 99H | Winter tyres on Light alloy | Continental | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 06/2028 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- 2 ignition keys, both foldable
- Driver and passenger side airbags
- Airbag: Front and side airbags
- Airbag: Head airbags, front and rear outer
- Ambient lighting, center console and in the front door pockets
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag and seatbelt tensioner)
- Heated windshield
- On-board computer
- Decorative trim strips, Dax/Palladium Medium
- Third brake light
- Electronic brake force distribution (EBD)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- luggage compartment cover
- Cruise control with intelligent speed limiter (The intelligent speed limiter, in conjunction with traffic sign recognition, allows for rapid speed adjustment)
- Heated rear window
- Interior lighting, front and rear (with reading lights front and rear - luggage compartment lighting)
- Child safety lock in the rear doors, manual
- Dual-zone automatic climate control including rear footwell heating (with separate temperature control for driver and front passenger - manual recirculation - automatic air distribution - sun sensor - particle and odor filter)
- Rear headrests (3), height adjustable
- Front headrests, height adjustable
- Leather steering wheel, flat-bottomed, with steering wheel remote control
- Steering wheel: Heated premium steering wheel, vegan
- Center armrest, sliding, front, including storage compartment and cup holder
- Package: Tech Package Pro (Keyless locking and starting system "Keyless open & start" - Electric tailgate - IntelliLux LED® Pixel Matrix light, Adaptive LED pixel matrix headlights with individual light distribution and fog lights)
- Quickheat heating system
- Radio accessories: Digital radio reception DAB+ (Offers a wider selection of radio programs. Digitally broadcast radio stations and traffic information can be received.)
- Rain sensor
- Tire pressure warning
- Wheels: Alloy 7 J x 19 with 5 spokes in BiColor/Black (with tires 205/55 R 19)
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Keyless locking and starting system "Keyless Open & Start"
- Storage compartments (storage compartment in the instrument panel, driver's side - storage compartment in the center console, front - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 1.0-liter beverage bottles - illuminated glove compartment with cooling and heating function - bag hooks, on the side in the luggage compartment - lashing eyes in the luggage compartment)
- Exterior mirrors, electrically adjustable and heated, electrically folding (exterior mirror housing in black)
- Hill Start Assist
- Roof design line in chrome
- Diesel particulate filter with SCR and oxidation catalyst
- Electric parking brake
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning (with automatic emergency braking, pedestrian detection, active lane keeping assist, traffic sign recognition, driver drowsiness detection, blind spot warning)
- Transmission: 8-speed automatic
- electric tailgate
- rear window wiper
- Interior rearview mirror, automatically dimming
- IntelliLux LED Pixel Matrix Light (Adaptive LED matrix headlights with individual light distribution and the following functions: - City light - Highway light - Country road light - Static cornering light - Turning light - Parking function light - High beam: traffic-dependent dimming taking into account preceding and oncoming road users - Automatic headlight range control - Fog lights)
- LED headlights (LED taillights - LED front turn signals - manual headlight range control - high beam assist)
- Steering wheel, height and reach adjustable
- Illuminated makeup mirror in sun visor, for driver and front passenger
- Package: Infotainment package (Multimedia Navi Pro with 10" touchscreen color display - OpelConnect (incl. emergency call/ breakdown call, vehicle status) - Wireless Charging)
- Front and rear parking sensors
- Radio: Multimedia Navi Pro incl. OpelConnect (with 10" color touchscreen display and voice control for audio, telephone and navigation - Navigation: with integrated memory, European road map, 3D map display, dynamic route guidance via map and/or arrow display, GPS module - Display and readout of emails - USB interfaces - High-gloss black shark fin antenna - Bluetooth audio streaming - Hands-free system - Smartphone integration, Apple CarPlay, Android Auto - Radio)
- Rear view camera
- Speed-sensitive power steering
- Seat belts (three-point seat belts in all seats - height-adjustable seat belts, front - belt force limiters, front and rear outer seats - double belt tensioners, front - belt tensioners, rear outer seats - warning tone and light for unfastened seat belts, front and rear)
- Seats: Rear seat backrest split 40:60 and foldable

- Seats: Alcantara package, ergonomic active seats with AGR seal of approval, driver and front passenger (length, height and backrest angle manually adjustable - seat tilt electrically adjustable - lumbar support, electro-pneumatically adjustable in height and length - extendable thigh support, manually adjustable - pocket on front seat back - all seats in Alcantara, black including seat contact surfaces and partial door panels (2nd row center seat, headrests, seat bolsters in imitation leather) - FlexFold rear seat backrest split 40:60 and foldable - winter equipment)
- Start/Stop System (Reinforced starter motor - High-performance battery - Switch to deactivate the start/stop function)
- Phone: Wireless Charging (Wireless charging of smartphones in the center console)
- Pre-wiring for ISOFIX child seat mounting system, including top tether attachment points, rear outer (and for ISOFIX child seat mounting system on the front passenger seat)
- Seats: Heated seats, multi-stage, driver and front passenger
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)
- Lane departure warning (warning in case of unintentional lane departure from 60 km/h via warning tone and indicator light in the driver information display)
- 12-volt power outlet (in the center console, front)
- Bumpers and side panels in high-gloss black
- Traction control TC Plus
- Underride protection look, front and rear, in silver
- Immobiliser
- Central locking with remote control and interior switches

### Extra equipment

- GK-HP
- safety net
- Paint finish: Metallic
- WKR

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Main inspection - No evidence - No deduction |
| 2 | Fuel system | Tank flap - Scratch(es) - Smart repair |
| 3 | Side panel - rear left side | Side panel - dent(s) - Smooth repair work |
| 4 | Side panel - rear right side | Side panel - dent(s) - Smooth repair work |
| 5 | Wheel / tyres | Tyre - front right side (Flanke) - Damaged - Replace |
| 6 | Engine | Engine - Leaking - Perform diagnosis |
| 7 | Seat - front | Seat cover - left side (Wange) - Broken / torn - Replace |
| 8 | Door - rear left side | Door - Scratch(es) - Paint |
| 9 | Door - front left side | Door - Dent / paintcoat damage - Repair and paint |
| 10 | Bonnet | Bonnet (Sandstrahleffekt) - Stone chips - Paint |
| 11 | Vehicle glazing | Windscreen (Rissbildung) - Stone chips - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Sill - left side | Sill - dent(s) - No deduction |
| 2 | Door - front right side | Door edge - Scratch(es) - No deduction |
| 3 | Front bumper | Front bumper - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Front, Side - left, Provided by user / customer, from 7 Jul 2025 | 848,77 € |
| 2 | Rear, Provided by user / customer, from 14 Sept 2026 | 2.537,87 € |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front




**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN





**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents





**Figure 15:** Documents



**Figure 16:** Additional tyres




**Figure 17:** Navigation




**Figure 18:** Misc.




**Figure 19:** Misc.




**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.




**Figure 24:** Misc.



**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.




**Figure 29:** Misc.




**Damage 2:** Fuel system: Tank flap - Scratch(es) - Smart repair




**Damage 2:** Fuel system: Tank flap - Scratch(es) - Smart repair




**Damage 3:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 3:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 4:** Side panel - rear right side: Side panel - dent(s) - Smooth repair work



**Damage 4:** Side panel - rear right side: Side panel - dent(s) - Smooth repair work



**Damage 5:** Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



**Damage 5:** Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace




**Damage 5:** Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



**Damage 6:** Engine: Engine - Leaking - Perform diagnosis




**Damage 6:** Engine: Engine - Leaking - Perform diagnosis




**Damage 7:** Seat - front: Seat cover - left side (Wange) - Broken / torn - Replace



**Damage 7:** Seat - front: Seat cover - left side (Wange) - Broken / torn - Replace



**Damage 8:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 8:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 8:** Door - rear left side: Door - Scratch(es) - Paint




**Damage 8:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 8:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 8:** Door - rear left side: Door - Scratch(es) - Paint



**Damage 9:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 9:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 9:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint



**Damage 9:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 9:** Door - front left side: Door - Dent / paintcoat damage - Repair and paint




**Damage 10:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



**Damage 10:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



**Damage 10:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




**Damage 10:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




**Damage 10:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




**Damage 10:** Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



**Damage 11:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



**Damage 11:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



**Damage 11:** Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace