TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48048496
Order No. / Reference: 27060720
Inspection date: 9 Oct 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG RS
VIN: TMBJK0NX8RY030852	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG RS	
Vehicle Identification number	TMBJK0NX8RY030852
Mileage (Read)	70,778 km
First registration	5 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 77
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Black Magic Pearlescent (F9R)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Anthracite-Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	8,600 km
Last service on / at	07/2026 at 61,934 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV949150
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AVI 00125		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,005 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 91Y	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	225/45 R18 91Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95V	Winter tyres on Light alloy	Bridgestone	4mm / 4mm
2)	205/55 R17 95V	Winter tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag: Center airbag front
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors painted black, door handles in body color
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Four roof grab handles (rear with coat hooks, ticket holder on the windshield)
- AERO roof rails in gloss black
- Digital Cockpit Plus
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Chassis: Sport chassis (sporty damper tuning, ground clearance reduced by approximately 15mm)
- Dynamic High Beam Assist (Dynamic Light Assist)
- Front and rear footwell lighting
- Removable luggage roller blind
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Child safety lock for the rear doors and windows
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Height and reach adjustable leather steering wheel with multifunction buttons including paddle shifters
- Front center armrest, including storage compartment
- Multi-collision brake
- Front and rear parking sensors
- Progressive steering
- Radio accessories: 2 USB ports at the front
- Radio accessories: 8 speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: Wireless & Wired SmartLink (Apple CarPlay, Android Auto)
- Tire pressure monitoring
- Wheels: 18" Comet alloy wheels, black (7.5J x 18, ET 48 with 225/45 R18 tires)
- Safety lights in the front side doors
- Seats: Heated front seats
- Seats: Rear seat backrest split 60:40 and foldable (with center armrest and pass-through option)
- Storage compartments (storage compartments in the front door panels with 1.5l bottle holders, storage compartments in the rear door panels with 0.5l bottle holders, storage compartments in the doors with felt lining)
- Airbag, front side airbags
- Ambient lighting (dashboard, front trim strips and footwell with selectable color climate) in the interior as well as logo projector on the outside)
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Glasses compartment in the headliner
- black headliner
- AERO roof rails in black
- Diesel particulate filter
- Tachometer
- Ice scraper in the fuel filler flap
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection (including evasive steering and turning assistant)
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior features: Design Selection RS (fabric seat covers - microfiber-covered dashboard center section - red decorative stitching in the interior - dark carbon trim strip)
- Kessy, keyless entry and start-stop system
- Black radiator grille frame
- LED matrix headlights and dynamic high beam assist (AFS) (Dynamic and automatic headlight range control - headlight cleaning system including washer fluid level control)
- Two reading lights at the front (including reading lights at the rear - trunk lighting)
- Engine drag torque control (MSR)
- Fatigue detection
- Pedals in stainless steel look
- Radio: Infotainment system (with infotainment display 10")
- Radio accessories: 2 x USB charging ports in the rear and USB charging port in the rearview mirror
- Radio accessories: Digital radio reception DAB+
- Umbrella and broom compartments in the front doors
- Rain sensor and driving light assistant (Easy Light Assist)
- Tire mobility kit (tire repair spray incl. compressor)
- Electromechanical power steering
- Seat belts (Height-adjustable three-point seat belts in the front, with belt tensioners - Three three-point seat belts in the rear - Seat belt reminder indicators in all seats)

- Seats: Pockets on the backs of the front seats including smartphone pockets
- Heated seats (2)
- Sun visors with illuminated make-up mirror on driver and passenger side
- Sound generator in the interior
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Sunset
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Textile floor mats
- Glazing: Acoustic glazing in the front side windows and Sunset (dark tinted rear window and rear side windows)
- Central locking including remote control integrated into the key and EASY Start
- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear.
- Seats: Front seats are height-adjustable (with adjustable lumbar support)
- SKODA Care Connect (SOS emergency call function (Emergency Call incl. automatic activation in the event of an accident with airbag deployment), Mobility service (connection for rapid assistance in case of breakdown), Information service (connection to the hotline for all questions relating to vehicle functions), Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Front door sill trims
- Lashing eyes in the trunk
- Immobiliser

Extra equipment

- Paint finish: Pearl effect
- Package: Comfort Plus (Combi) (3-zone Climatronic - Heated outer rear seats - Heated steering wheel - 230 V socket and 3 x USB charging ports - Sunshades in the rear doors - Multifunctional storage compartment in the boot - Electric tailgate operation with comfort opening - Sleeping headrests in the rear)
- Package: Safety (Rear side airbags - Proactive occupant protection with rear impact detection - Lane change and parking assist (Side Assist))
- Seats: Electrically adjustable Ergo-Sportsi.
- Heated windscreen
- Package: Infotainment package Business Columbus (Style, RS, Scout) (Columbus navigation system - Infotainment Online (3-year term) - 3 USB charging ports - Head-Up Display - Adaptive Cruise Control (ACC) - Traveller Assist system)
- Package: Parking & Lights (for RS) (cornering lights in the fog lights - reversing camera)
- Package: Transport (Combi) (Double-sided boot mat - Media holder - Tablet holder - Waste bin - 3rd vehicle key - Net program in the luggage compartment and cargo elements - Luggage net partition - Variable loading floor)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats (VL) - Holes - Replace
2	Trim / covers	A-pillar - interior trim - right side - Scratch(es) - Loss in value
3	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
4	Roof	Roof rail - right side - Scratch(es) - Smart repair
5	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
6	Rear bumper	Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint
7	Front bumper	Front bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	2nd wheel set	2 tyres (Über 4mm) - No deduction
2	Roof	Roof - dent(s) - No deduction
3	Roof	Roof rail - left side - dent(s) - No deduction
4	Boot lid / rear door	Boot lid - dent(s) - No deduction
5	Door - rear left side	Door - dent(s) - No deduction
6	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Interior - Boot cover / roller cover

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 6 Aug 2025	925,55 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 1: Trim / covers: Floor mats (VL) - Holes - Replace




Damage 1: Trim / covers: Floor mats (VL) - Holes - Replace



Damage 2: Trim / covers: A-pillar - interior trim - right side - Scratch(es) - Loss in value



Damage 2: Trim / covers: A-pillar - interior trim - right side - Scratch(es) - Loss in value



Damage 3: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 3: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 4: Roof: Roof rail - right side - Scratch(es) - Smart repair



Damage 4: Roof: Roof rail - right side - Scratch(es) - Smart repair



Damage 4: Roof: Roof rail - right side - Scratch(es) - Smart repair



Damage 4: Roof: Roof rail - right side - Scratch(es) - Smart repair




Damage 5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage 5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 6: Rear bumper: Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint




Damage 6: Rear bumper: Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint




Damage 6: Rear bumper: Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper (Zusätzlich Spaltmaß einstellen) - Scratch(es) - Paint




Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Front bumper: Front bumper - Scratch(es) - Paint