TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 47891209
Order No. / Reference: 27026954
Inspection date: 30 Sept 2026

Manufacturer: Audi	Model: A6 Avant 40 TDI quattro S tronic advanced
VIN: WAUZZZF23RN053492	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A6 Avant 40 TDI quattro S tronic advanced	
Vehicle Identification number	WAUZZZF23RN053492
Mileage (Read)	140,096 km
First registration	17 Jun 2024
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Manhattangrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	8,800 km
Last service on / at	09/2025 at 90,167 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD476416
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BTA 02760		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,425 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102Y	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	245/45 R19 102Y	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R17 99H	Winter tyres on Light alloy	Pirelli	3mm / 3mm
2)	225/60 R17 99H	Winter tyres on Light alloy	Pirelli	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	145/65 R20 105M	Summer tyres on Steel	Sonstige	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger (full-size airbag, with front passenger airbag deactivation)
- "quattro" all-wheel drive with ultra technology (continuously monitors the driving conditions and distributes power between the front and rear axles depending on the situation. If a driving situation does not require all-wheel drive, the entire rear axle can be decoupled from the drive. During sporty cornering, the inside wheels are gently braked, thus increasing the drive torque on the outside wheels.)
- Audi connect Emergency Call & Service with m.connect Remote & Control (The Audi connect Emergency Call & Service services ensure a safe feeling on every journey. - Emergency call - Online breakdown call - Audi damage service - Audi service appointment online Audi connect Remote & Control: - Vehicle status - Remote locking/unlocking - Parking position - Remote control of auxiliary heating - Push notification of anti-theft alarm system)
- Audi pre sense front (Within system limits, it can warn of impending collisions depending on the situation and speed and initiate appropriate braking. The system is active from approximately 5 km/h. Pedestrians and cyclists can be detected at speeds up to approximately 85 km/h and vehicles at speeds up to 250 km/h: If an impending frontal collision is detected, the system warns the driver visually, audibly, and haptically in a multi-stage process.)
- Exterior mirror housings in body color
- Control buttons, matte black
- Vehicle tool kit
- third brake light
- Fabric headliner
- Decorative inlays, fine lacquer, graphite grey
- Parking aid plus with surround view (acoustic and visual parking aid front, side and rear to assist with parking and maneuvering by measuring with 12 ultrasonic sensors. A selective visual display shows the distance to detected objects in the upper display, depending on the current steering angle and the direction of travel. Optionally, activation occurs automatically as soon as the vehicle approaches a detected obstacle at a speed of less than 10 km/h).
- Electrically opening and closing tailgate (The tailgate can be opened electrically by pressing the button on the vehicle key, in the driver's door, or the soft-touch button on the tailgate handle. To close the tailgate: simply press the button on the inside of the tailgate, the button in the driver's door, or the button on the vehicle key. A6 Avant: Opening the tailgate in low-ceiling areas is made easier by a programmable opening angle.)
- Transmission: S tronic 7-speed
- rear window wiper
- ISOFIX and Top Tether child seat attachment for the outer rear seats (standard mounting for the practical attachment of i-Size and ISOFIX child seats - with additional attachment point (Top Tether) on the outer rear seats - The recommended child seats from Audi Genuine Accessories are available from your Audi Partner)
- Headrests (4) (front ones manually height adjustable)
- Airbag: Front side airbags and head airbag system (front side airbags integrated into the seatbacks - with additional head airbag system: deploys in front of the side window area and thus protects the front and outer rear passengers in the event of a side impact)
- Anti-lock braking system (ABS)
- Audi connect Navigation & Infotainment (Navigation with Google Satellite Map - Online search for navigation destinations - Online voice input - Online traffic information - Online traffic information plus - Lane-accurate navigation - Online points of interest - On-street parking - Hazard information - myAudi Navigation - High-resolution 3D city view - Online media streaming - Online radio - Hybrid radio - Weather information - Online news - Wi-Fi hotspot - User profiles - Holographic interface - Access to themed worlds)
- Audi drive select (adjustment of vehicle characteristics in the available modes auto, comfort, dynamic, efficiency, allroad, offroad, individual by adjusting steering assistance, engine characteristics or shift characteristics, dynamic all-wheel steering, damper control, adaptive air suspension, sport differential, ultra technology, adaptive speed assistant, Matrix LED headlights and setting of other optional equipment.)
- Audi virtual cockpit plus (3 individual display options: Dynamic, Sport and Classic - operation via the multifunction steering wheel - configuration of on-board computer values in the tachometer - display of the navigation map as a 3D terrain model on the high-resolution 12.3-inch full HD color display - permanent display of navigation information in the speedometer area when route guidance is active - break recommendation)
- Aluminum roof rails
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Door sill trims with aluminum inlay front and rear (unlit)
- Electronic Stability Control (ESC)
- Window trim strips in aluminum look (roof frame and window channel strips in anodized aluminum)
- Remote key (locks and unlocks doors, luggage compartment and loading flap - starts and stops the engine via the engine start/stop button - includes comfort closing/opening of windows)
- Cruise control with speed limiter (From approximately 20 km/h, the system can maintain the desired speed. This is achieved by adjusting engine power or by active braking interventions, provided engine and braking performance allow. Operation is via a separate steering column stalk. The set speed is displayed in the Audi virtual cockpit plus. The speed limiter is available from approximately 30 km/h and helps to prevent exceeding a preset maximum speed.)
- Heated rear window
- Interior lighting (front and rear roof module, including reading lights (capacitively switched), illuminated vanity mirrors for driver and front passenger, entry lights on the underside of the front doors, front/rear door controls, front storage compartment, glove compartment, front/rear footwell lighting, right/left trunk lighting)

- LED headlights (The LED headlights include the following functionalities: - Daytime running lights - Low beam - High beam - Position lights - Turn signals using incandescent bulb technology - All-weather lights (to reduce glare in poor visibility conditions) LED taillights)
- Non-smoking version (no ashtray in the front center console, one 12-volt socket each in the front and rear)
- Progressive steering (increases driving dynamics and driving comfort through more direct steering response (e.g. on winding country roads or when turning) and reduced steering effort (e.g. when parking and maneuvering); driving characteristics through a steering ratio dependent on the steering angle and speed-dependent steering assistance; various modes, adjustable via Audi drive select)
- Radio: MMI Radio plus with MMI touch response (10.1-inch color display - Audi music interface; 2 USB-C ports with data and charging function - Bluetooth interface (hands-free calling and audio streaming) - Remote MMI touch control unit with 8.6-inch color display including MMI touch response with haptic feedback; for controlling the climate control function and input field for handwriting recognition - AM/FM phase diversity - DAB+ - speed-dependent volume adjustment)
- Sun visor on driver and passenger side
- Start-stop system (helps reduce fuel consumption and CO2 emissions by switching off the engine during stationary phases, e.g. at traffic lights. For restarting, the starting process is initiated as soon as the foot brake is released. Can be deactivated at any time via a button.)
- First aid kit with warning triangle and high-visibility vests (The first aid kit is located in the left side compartment in the luggage compartment. The factory-supplied warning triangle is located in the tailgate. The factory-supplied high-visibility vests are located in the storage compartment of the driver's door.)
- Electronic immobilizer
- Heat-insulating glazing on the sides and rear (green tinted, heated rear window with timer)
- Central locking with remote control
- Comfort center armrest in the front (length adjustable and tilt adjustable)
- Manual steering wheel adjustment (adjustable in height and distance)
- MMI Navigation with MMI touch response (10.1-inch color display (1,540 × 720) - Navigation map or arrow display in the Audi virtual cockpit plus - Map updates - 3D map display - Efficiency assistant - Online traffic information - MMI search - MMI touch response for quick, intuitive operation - Easy operation of the infotainment system via natural language interaction - Detailed route information - Input of up to 10 waypoints - Selected Audi connect Navigation & Infotainment portfolio)
- Wheel: Tire pressure monitoring system (visual and audible warning in case of pressure loss in one or more wheels. Display in the Audi virtual cockpit plus)
- Wheel: Tire repair kit
- Seats: Split-folding rear seat backrest Avant (distinctive outer rear seats, visually adapted to the front seats, and an additional central seating option - 3 rear L-shaped headrests, manually height-adjustable - three 3-point seat belts - rear seat backrest split 40:20:40 or fully foldable - one-piece, foldable rear center armrest with storage compartment - with remote backrest release in the boot, removable partition net, to be attached to the body or to the folded-down rear seat backrest)
- Lane Departure Warning (within system limits, helps prevent unintentional lane departures. If the system is activated and ready, and the driver has not used the turn signal, the Lane Departure Warning helps prevent crossing detected lane markings by making corrective steering interventions. Additional steering wheel vibration can be set at the driver's request. Operating range from approximately 60 to a maximum of 250 km/h)
- Glazing: Rear window, rear door and side windows in clear glass
- Camera-based traffic sign recognition (supported by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions. If a traffic sign is outside the camera's field of view, it is retrieved from the stored navigation data of the MMI Navigation plus. The traffic sign recognition is displayed automatically in the Audi virtual cockpit and can be configured via the multifunction steering wheel).

Extra equipment

- AdBlue tank with increased filling volume (AdBlue tank with 22 liter filling volume - for diesel vehicles with SCR technology, to reduce nitrogen oxides in the exhaust gas)
- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- Deletion of model designation and performance/technology lettering
- High beam assist (within the system's limits, it automatically detects oncoming headlights, taillights of other road users, and built-up areas. Depending on the traffic situation, the high beam is automatically switched on or off.)
- Assistance Package Tour (Adaptive Driving Assistant, Adaptive Speed Assistant provides support within system limits for acceleration, braking, and maintaining speed and distance with Lane Keeping Assist - Efficiency Assistant - Turning Assistant, monitors the oncoming lane using data from the radar sensor and front camera as soon as the turn signal is activated - Evasive Steering Assist, helps the driver steer the vehicle around an obstacle in a critical situation - Emergency Assist)
- Wheel: Light alloy wheels 5-twin-spoke design, graphite grey, polished (8.5 J x 19 with tires 245/45 R 19)
- Radio accessories: Audi sound system (10 speakers including center speaker and subwoofer - 6-channel amplifier - total output of 180 watts)
- Rail system with fixing set (telescopic pole and strap for individual partitioning of the luggage compartment and secure fixing of objects, stowable under the loading floor)
- Seats: Front sports seats (with manual adjustment of seat height, seat longitudinal position, seat tilt, backrest tilt, headrest height and distance and belt height with pronounced seat side bolsters for better lateral support in curves, extendable thigh support and electric 4-way lumbar support)
- Lane change warning including Audi pre sense rear, exit warning and rear cross-traffic assist (Lane change warning helps the driver monitor the blind spot and traffic behind the vehicle. Exit warning warns of a possible collision when opening a door while the vehicle is stationary. Rear cross-traffic assist (Audi pre sense rear) uses data from the radar sensors.
- Glazing: Windscreen in climate comfort/acoustic glazing, wirelessly heated (heated windscreen made of climate comfort/acoustic glass, facilitates rapid defrosting and ensures fog-free operation through surface heating without obstructing heating wires; with heated wiper blade rest; with viewing window for telepass devices)
- Swiveling towbar with electric release (with swiveling ball head, trailer stabilization via electronic stability control (ESC), release via button in the luggage compartment, the integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving)
- Anti-theft alarm system (monitoring of doors, front and trunk lids. The Safelock, linked to the door locks, prevents the doors from being opened from the inside once the vehicle has been locked with the key. The anti-theft alarm system includes: - switchable ultrasonic interior monitoring - warning via tilt sensor in case of theft - battery-powered horn to prevent tampering)
- Fuel tank (73 liters) (fuel tank for 73 liters of gasoline/diesel fuel)
- Paint finish: Metallic
- Steering wheel: Leather steering wheel, 3-spoke, with multifunction and paddle shifters (paddle shifters allow manual changing of the driving modes.)
- Business Package (Assistance Package Tour (adaptive speed assist, efficiency assist, turn assist, evasive steering assist, emergency assist) - 4-zone automatic climate control - heated front seats - Audi phone box - automatically dimming interior mirror - automatically dimming exterior mirrors - adaptive windscreen wipers with integrated washer nozzles - high-beam assist)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Spare wheel, space-saving
- Reversing camera (The reversing camera displays the area behind the vehicle on the upper display. Dynamic display elements such as a steering angle-dependent lane calculation assist with parking or maneuvering.)
- Seat covers in fabric Rhythm
- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Front seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit)
- Telephone: Application Store and Smartphone Interface (The Audi App.Store in the vehicle's MMI provides access to a wide selection of popular apps, such as news and podcasts, sports and games, or video and entertainment. These can be downloaded directly to the vehicle and are usable within the framework of legal regulations. - The smartphone interface connects the smartphone to the vehicle and seamlessly displays smartphone content directly on the MMI display. The connection can be made via USB cable or wirelessly. - Voice control)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Indicator light (Öl nachfüllen) - Specify findings - Perform diagnosis
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
4	Roof	Roof (Anätzung) - Paint defect - Conditioning
5	Trim / covers	Boot lid - interior trim - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Wing mirror - right side	Cap - Scratch(es) - No deduction
5	Door - rear right side	Door - Scratch(es) - No deduction
6	Mudguard - left side	Mudguard - left side - Stone chips - No deduction
7	Documents	Service book - Incomplete - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Side - left, Side right, Provided by user / customer, from 3 Jul 2026	1.860,93 €
2	Front, Provided by user / customer, from 9 Jun 2026	1.990,01 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

-Die Übermittelte Servicehistorie hat unplausible Einträge, eine Lückenlose Einhaltung der Serviceintervalle ist nicht Sicherzustellen

-Das Fahrzeug weist rundherum erhöhte Lackwerte auf.

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 1: Instrument panel: Indicator light (Öl nachfüllen) - Specify findings - Perform diagnosis



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 4: Roof: Roof (Anätzung) - Paint defect - Conditioning



Damage 4: Roof: Roof (Anätzung) - Paint defect - Conditioning



Damage 5: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace



Damage 5: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace



Damage 5: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace