MACADAM

# BMW X5

## Vehicle information


| | | | |
|---|---|---|---|
| Brand: | **BMW** | License plate: | **2CLR152** |
| Gearbox: | | Body color: | |
| Model: | **X5** | LEVEL: | **WBATA610609M33357** |
| Fuel type: | | Power: | **155 kW** |
| Version: | **3.0 XDRIVE45E 155KW 4WD AUTO** | First registration | **07/09/2022** |
| Mileage: | **83087 km** | Number of doors: | |

## Summary of damages

| | |
|---|---|
| **Back** | 6 |
| **RIGHT** | 1 |
| **Interior** | 2 |
| **Roof & other** | 1 |


## Commercial photos


































## Options according to the inspector



| | |
|---|---|
| GPS | **Yes** |

## Damages

**Fast charging cable**
missing
- Replace
rear



**Bodywork**
Damaged -
Acceptable.
Roof & other










Broken **Reflector**

E - Replace

Rear









Dirty **Interior**

- Clean

Interior

















Damaged **Interior**
- Acceptable
Interior







**Right Wing Molding**
Claw(s)
E - Replace
Right







**Rear bumper molding,**
claw(s)
, paint
rear





**Rear bumper,**
claw(s)
, paint
the rear


**Rear bumper,** Smart repair claw
(s)





Rear **right inner wheel arch.**
Dent(s) and scratch(es).
Smart repair.




## Tires

**Front Left**
Summer
Aluminum
265/50/19/110/W
Pirelli
4.0 mm
**Front Right**
Summer
Aluminum
265/50/19/110/W
Pirelli
4.0 mm
**Left Back**
Summer
Aluminum
265/50/19/110/W
Pirelli
4.0 mm
**Rear Right**
Summer
Aluminum
265/50/19/110/W
Pirelli
4.0 mm

## Controls

| | | | |
|---|---|---|---|
| Category | **Private vehicle** | Registration certificate - home address section | **No** |
| Vehicle registration certificate | **Yes** | Certificate of Conformity | **Yes** |
| Compressor | **P/A** | Vehicle inspection | **OK** |
| Vehicle inspection | **07/09/2028** | Jack | **P/A** |
| Interview | **OK** | Interview | **in 21000 km** |
| Galette | **P/A** | Repair kit | **P/A** |
| Number of charging cables (220V) | **1** | Number of charging cables (fast charging) | **0** |
| Total number of keys | **2** | Factory reset | **Yes, the vehicle has been reset to factory settings.** |
| Spare wheel | **P/A** | Runflat | **P/A** |
| Type of maintenance log | **Digital interview** | | |

### Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.