TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48111107
Order No. / Reference: 27100245
Inspection date: 13 Oct 2026

Manufacturer: Seat	Model: Tarraco 2.0 TDI SCR DSG Xperience
VIN: VSSZZZKN4PW014354	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Tarraco 2.0 TDI SCR DSG Xperience	
Vehicle Identification number	VSSZZZKN4PW014354
Mileage (Read)	69,044 km
First registration	17 Aug 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Deep Schwarz (C9X)
Doors / Seats	5 / 7
Upholstery type	Leather
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	2,000 km
Last service on / at	08/2026 at 67,165 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT060669
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / AOR 03679		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,270 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 99V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/50 R19 99V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 99H	Winter tires (with run-flat tires) (Without wheel rim)	Continental	6mm / 5mm
2)	235/50 R19 99H	Winter tires (with run-flat tires) (Without wheel rim)	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	145/85 R18 103M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket at the front
- Storage pocket on the back of the front seats
- Ambient lighting (multicolored) in the door panels
- Automatic coming-home and leaving-home function
- Adaptive Cruise Control (ACC) up to 210 km/h
- Electrically adjustable, folding and heated exterior mirrors (with passenger-side mirror lowering function)
- Owner's manual holder under the driver's seat
- Chrome applications in the interior
- Black headliner
- Diesel particulate filter and SCR catalyst
- Tachometer
- Third brake light
- Electronic parking brake including auto-hold function
- Electric front and rear windows (with anti-pinch protection and one-touch function)
- Gear recommendation display
- luggage compartment cover
- Illuminated glove compartment
- LED taillights (with dynamic turn signals and LED light strip - Infinite Light)
- Rear window wiper and rear window heater
- ISOFIX child seat restraint system (for the front passenger seat and the 2nd row of seats, left and right, including top tether anchor points)
- Headrests, 2 front, 3 rear
- Steering wheel: Multifunction steering wheel in leather
- Light sensor with automatic headlight control
- Fatigue detection
- LED fog lights with cornering light function
- Park Assist with front and rear parking aid
- Radio: Media-System Plus (Audio system with 8.25" color touchscreen - Digital radio reception DAB+ - 2 USB-C ports in the front - USB-C charging socket for the 2nd row of seats - Bluetooth interface with integrated hands-free system and audio streaming - 8 speakers)
- Rear view camera
- paddle shifters on the steering wheel
- SEAT Drive Profile with "Driving Experience" button and progressive steering (driving profiles can be individually selected - selected driving profile influences steering assistance, throttle response and shift characteristics (with DSG))
- Seats: Front passenger seat backrest can be folded down completely
- Seats: Sport comfort seats in the front
- Seats: Front seats with height adjustment
- Lane departure warning system
- LED daytime running lights
- Front Assist area monitoring system with City Emergency Braking function
- Storage compartment for glasses
- Airbags (driver and front passenger airbag (passenger airbag deactivation) - side airbag for driver and front passenger - head airbag system, front and rear - driver's side knee airbag)
- Exterior mirror housings in body color
- Turn signals and welcome light integrated into the exterior mirrors
- Chrome trim on the side windows
- Silver roof rails
- Electronic differential lock (XDS)
- Three-point automatic seat belts, front and rear (warning tone for unfastened seat belts)
- Electronic Stability Control (ESC) (including Anti-lock Braking System (ABS) and Traction Control System (ASR))
- Footwell lighting
- luggage compartment, illuminated
- Transmission: 7-speed DSG automatic transmission
- Electrically operated tailgate (opening & closing) (incl.: - Sensor-controlled opening & closing (Virtual Pedal) - Keyless locking and starting system "Kessy")
- Interior mirror automatically dimming
- Body covers on the wheel arches
- Climatronic air conditioning system with 3 climate zones and rear control unit
- Radiator grille in chrome design
- Reading lights, 2 in the front and 2 in the rear
- Center console with integrated storage compartment, center armrest, cup holders
- Emergency call service
- Upholstery: Fabric/Dinamica
- Radio accessories: Full Link (Android Auto - Apple CarPlay incl. Full Link Wireless)
- Rain sensor
- Tire pressure monitoring system
- Wheels: 4 "Exclusive Aero" alloy wheels, diamond-turned finish (7J x 19 with 235/50 R19 tires)
- SEAT CONNECT (prepared for activation of the service packages Security/Assistance and Remote Access)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Side trim in silver
- Electromechanical power steering
- Seats: Lumbar support for driver and front passenger
- Seats: Rear bench seat longitudinally adjustable and asymmetrically split and foldable (with center armrest)
- Sun visors with illuminated makeup mirror
- Start-stop technology
- Front door sill trims in aluminum look, illuminated
- Variable luggage compartment floor
- Lashing eyes in the luggage compartment

- Virtual Cockpit (Fully digital instrument cluster with 10.25" TFT display)
- Electronic immobilizer
- Central locking, including tailgate, with remote control
- Full LED headlights (low beam and high beam in LED technology - dynamic headlight range control)
- thermal insulation glazing

Extra equipment

- Swiveling towbar with electric release
- Heated and infrared-reflective windshield
- Paint finish: Metallic
- Package: 7-seater package (2 individual seats in the 3rd row)
- Package: XL Driving Assistance Package for Navigation System (High Beam Assist - Side Assist - Travel Assist - Emergency Assist - Pre-Crash Assist with Rollover Detection - Leather Multifunction Steering Wheel, Heated - Traffic Sign Recognition - Adaptive Cruise Control (ACC) up to 210 km/h with Predictive Speed Control)
- Panoramic glass sliding roof, electric, including sunshade blind.
- Wheels: Spare wheel as emergency wheel
- Deletion of the lettering on the tailgate
- Luggage partition net (including remote release for folding down the rear seat backrest)
- Package: Business Package NAVIGATION (Navigation system with 9.2" color touchscreen, voice control - Full Link: Android Auto, Apple CarPlay - Wireless charger in the storage compartment of the center console - Spare wheel as emergency wheel)
- Package: Leather package (passenger seat backrest fully foldable - seat center and side bolsters in leather, color black - front headrests, longitudinally and height adjustable - sport comfort seats in front - front seats and outer seats of the 2nd row heated)
- Seats: Driver's seat electrically adjustable with memory function (exterior mirrors with memory function - lumbar support electrically adjustable)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Roof	Roof rail - left side - dent(s) - Smooth repair work
3	Trim / covers	Trim / covers - Burn hole (cigarettes) - Replace
4	Door - rear left side	Door - Dent / paintcoat damage - Smart repair
5	Seat - front	Seat cover - left side - Burn hole (cigarettes) - Loss in value
6	Front bumper	Spoiler - Dent / paintcoat damage - Smart repair
7	Wheel / tyres	Tyre - front right side (nicht fahrbereit) - Broken / torn - Replace
8	Tail light	Tail lamp - right side - Scratch(es) - Replace
9	Rear bumper	Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint
10	Bonnet	Bonnet - Scratch(es) - Paint
11	Front bumper	Front bumper - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Sill - right side	Sill - Scratch(es) - No deduction
2	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - No deduction
4	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction
5	Wheel / tyres	Alloy rim - front left side - Scratch(es) - No deduction
6	Side panel - rear left side	Side panel - dent(s) - No deduction
7	Boot lid / rear door	Boot lid - Scratch(es) - No deduction
8	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 20 Dec 2023	2.728,74 €

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
4	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
5	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	208 µm	Side panel - rear right side	220 µm
Door - rear left side	202 µm	Door - rear right side	249 µm
Door - front right side	223 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Das Fahrzeug weißt rundherum erhöhte Lackwerte auf.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 2: Roof: Roof rail - left side - dent(s) - Smooth repair work




Damage 3: Trim / covers: Trim / covers - Burn hole (cigarettes) - Replace




Damage 3: Trim / covers: Trim / covers - Burn hole (cigarettes) - Replace




Damage 4: Door - rear left side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - rear left side: Door - Dent / paintcoat damage - Smart repair



Damage 5: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Loss in value



Damage 5: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Loss in value



Damage 6: Front bumper: Spoiler - Dent / paintcoat damage - Smart repair




Damage 6: Front bumper: Spoiler - Dent / paintcoat damage - Smart repair




Damage 7: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Broken / torn - Replace



Damage 7: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Broken / torn - Replace



Damage 8: Tail light: Tail lamp - right side - Scratch(es) - Replace



Damage 8: Tail light: Tail lamp - right side - Scratch(es) - Replace



Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint




Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint




Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 9: Rear bumper: Rear bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet - Scratch(es) - Paint




Damage 10: Bonnet: Bonnet - Scratch(es) - Paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Wear and tear 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 2: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - No deduction




Wear and tear 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - No deduction




Wear and tear 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - No deduction



Wear and tear 5: Wheel / tyres: Alloy rim - front left side - Scratch(es) - No deduction



Wear and tear 6: Side panel - rear left side: Side panel - dent(s) - No deduction



Repainting 1: Mudguard - right side




Repainting 1: Mudguard - right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side



Repainting 3: Door - rear left side




Repainting 3: Door - rear left side



Repainting 4: Door - rear right side



Repainting 4: Door - rear right side



Repainting 5: Door - front right side



Repainting 5: Door - front right side