TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48286523
Order No. / Reference: 27144845
Inspection date: 23 Oct 2026

Manufacturer: Volkswagen	Model: ID. Buzz Pro
VIN: WV2ZZZEB7PH025163	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen ID. Buzz Pro	
Vehicle Identification number	WV2ZZZEB7PH025163
Mileage (Read)	49,791 km
First registration	26 Jun 2023
Number of holders	1
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Starlight Blue Metallic (T5U)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Beige
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	327 Tag(e)
Last service on / at	09/2025 at 35,314 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV206059
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CQY 00031		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	3,000 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 104T	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	265/45 R20 108T	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103T	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	255/55 R18 105T	Winter tyres on Light alloy	Continental	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS
- Airbag: Side and head airbags for driver and front passenger
- Electrically adjustable, folding and heated exterior mirrors, with passenger-side mirror lowering function.
- Exterior mirror housings in high-gloss black and door handles in body color
- CCS charging socket
- Design badges for the D-pillar in black and white
- Three-point automatic seat belts at the front with belt and end fitting tensioners and height adjustment
- Black surround for the infotainment display and central controls
- ESP
- Windows: Rear windows made of tinted heat-insulating glass
- Window: Fixed side window in the passenger compartment, front right
- luggage compartment cover
- Intelligent Speed Assist speed limiter
- Transmission: Direct drive, 1-speed
- Tailgate with window cutout
- Heated rear window
- Interior lighting in the front and rear footwells
- ISOFIX and Top Tether child seat anchorages in the 2nd row of seats
- Headrests (5)
- LED luggage compartment lighting
- Steering wheel: Multifunction steering wheel
- Multifunctional camera
- Non-smoking version
- eCall emergency call system
- Radio: App-Connect incl. App-Connect Wireless
- Radio: Digital radio reception (DAB+)
- Radio accessories: 2 USB-C ports in the instrument panel and 1 USB-C charging port in the front.
- Wheels/Tires: Wheel bolts with enhanced theft protection
- Windscreen wiper intermittent control
- Sliding door, left side in the passenger/cargo area
- Keys for locking system: 2 vehicle keys
- Seatbelt check
- Seats: Height adjustment for both front seats, manual
- Lane keeping assistant “Lane Assist”
- LED daytime running lights
- Telephone: Mobile phone interface with inductive charging function
- Ambient lighting with logo projection
- Electronic immobilizer
- Airbag for driver and front passenger
- Armrests for front seats (inside)
- Evasive steering assist and turn assist
- Exterior mirrors, driver's side convex, passenger's side convex
- Battery (58 Ah/340 A)
- third brake light
- DC/DC converter 3.0 KW
- Three-point automatic seat belts, rear outer seats, with ECE label
- e-Sound
- Parking assistance in the front and rear areas
- Single-tone signal horn
- Window: Rear window
- Window: Fixed side window in the passenger compartment, front left
- Electric windows, front
- Windscreen in heat-insulating glass
- Total weight: Permissible total weight 3,000 kg
- Cruise control system with speed limiter in conjunction with online services
- Tailgate closing without interior unlocking function
- Rear window wiper/washer system with intermittent function
- Air conditioning system "Air Care Climatronic" with active combination filter
- Mode 3 Type 2 charging cable, 16 A
- LED taillights
- Headlight range control
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Proactive occupant protection system (PreCrash Basic and Front)
- Radio: Diversity antenna for FM reception
- Wheels, tires: Covers for alloy wheels
- Wheels/Tires: Tire pressure monitoring system
- Rear seat bench and backrest can be folded down in a split configuration
- Sliding door, on the right in the passenger/cargo area
- Speed-sensitive power steering (Servotronic)
- dimmable interior safety mirror
- Sun visors with mirrors, illuminated
- Bumpers in body color
- Phone: Car2X
- Carpet flooring (Dilours), reinforced
- Door trim in plastic with insert, armrest in fabric
- Traffic sign recognition
- Central locking with keyless start system "Keyless Start" without safe locking

Extra equipment

- Operating voltage 12 V with 230 V socket (Schuko socket)
- Floor mats: Textile floor mats, front
- Paint finish: Metallic
- Mains charging cable for household socket (Mode 2 Type 2, 10A)
- Package: Assistance Package "Plus" (Lane Change Assist, Side Assist, Travel Assist including Lane Assist, Emergency Assist, Park Assist Plus, Memory for Park Assist Plus, Multifunction steering wheel in synthetic leather with touch controls, heated, illuminated door handle recesses, Central locking with Keyless Advanced keyless entry and start system with safe locking, Anti-theft alarm with interior monitoring, backup horn, tow-away protection, Adaptive Cruise Control (ACC) stop&go, speed limiter)
- Package: Infotainment Package Plus (Voice control - Navigation system "Discover Pro" - Radio "Ready 2 Discover" with 30, 48 cm (12-inch) touch color display - 9 speakers (5 front speakers and 4 rear speakers) - Mobile phone interface "Comfort" with inductive charging function)
- Package: Open & Close Package "Plus" (illuminated door handle recesses - central locking with keyless locking and starting system "Keyless Advanced" with safe locking - electric tailgate (opening and closing) with "Easy Open" and "Easy Close" function - electric sliding door left - electric sliding door right - anti-theft alarm system with interior monitoring, backup horn and tow-away protection - rear approach lighting)
- Wheels/Tires: 20" "Solna" alloy wheels (4 "Solna" alloy wheels 8 J x 20 front, with 10 J x 20 rear, in black, polished finish - wheel covers - Airstop tires 235/50 R 20 104 T XL front, Airstop tires 265/45 R 20 108 T XL rear)
- First aid kit, warning triangle and 5 high-visibility vests
- On-board tools and jack
- Premium Style "Plus" interior with Electric White steering wheel in V with comfort package (electrically adjustable front seats with memory function; reinforced carpet flooring; leather multifunction steering wheel with touch controls and heating; comfort seats (left/right, front); armrests for front seats and lumbar support on both sides; ambient lighting in 30 colors; infotainment display and control elements trim in Electric White; plastic door panels with inserts and leatherette armrests; individually adjustable heated front seats; ArtVelours Eco microfleece seat centers for front and outer rear seats)
- Package: Design package (illuminated strip between the headlights - stainless steel pedals in "Play/Pause" design - Dynamic Light Assist high beam control for LED matrix headlights - IQ.LIGHT - LED matrix headlights with automatic headlight control, bad weather light, welcome function - dynamic headlight range control with dynamic cornering lights - LED taillights with dynamic turn signals)
- Package: Comfort Package "Plus" in V with Assistance Package "Plus" (ID. Buzz Box, removable center console with storage compartments between the front seats - 2 USB-C ports in the instrument panel, USB-C charging ports front and rear - multifunction steering wheel in synthetic leather, with touch controls, heated - seat heating for both seats in the driver's cab, separately adjustable - heated windshield in heat-insulating glass - automatically dimming interior mirror - Multiflexboard, two folding boxes - net partition - intermittent windshield wipers with rain sensor - heated windshield washer nozzles, front)
- Wheels/Tires: LM 20" Airstop winter wheels "Stockton" (additional) (Tires 235/50 R20 104 T XL front, 265/45 R20 108 T XL rear - without cover)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet - Scratch(es) - Smart repair
2	Boot lid / rear door	Boot lid glazed - Scratch(es) - Smart repair
3	Steering system	Steering wheel - Abrasion - Loss in value
4	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
5	Side panel - rear left side	Side panel - Scratch(es) - Paint
6	Front bumper	Bumper with Parktronic - Scratch(es) - Paint
7	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Scratched - Replace
8	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratched - Replace
9	Door - front right side	Door - Deformed - Repair and paint
10	2nd wheel set	2nd wheel set (keine 20" 'Stockton') - Differs from the original configuration - Replace

Wear and tear

No.	Component group	Description
1	Sliding door, right	Sliding door with glass panel - dent(s) - No deduction
2	Side panel - rear right side	Side panel - dent(s) - No deduction
3	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Bonnet: Bonnet - Scratch(es) - Smart repair



Damage 1: Bonnet: Bonnet - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid glazed - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid glazed - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid glazed - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid glazed - Scratch(es) - Smart repair



Damage 3: Steering system: Steering wheel - Abrasion - Loss in value




Damage 3: Steering system: Steering wheel - Abrasion - Loss in value




Damage 3: Steering system: Steering wheel - Abrasion - Loss in value



Damage 3: Steering system: Steering wheel - Abrasion - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value




Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value




Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 6: Front bumper: Bumper with Parktronic - Scratch(es) - Paint



Damage 6: Front bumper: Bumper with Parktronic - Scratch(es) - Paint



Damage 7: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace




Damage 8: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 9: Door - front right side: Door - Deformed - Repair and paint



Damage 9: Door - front right side: Door - Deformed - Repair and paint



Damage 9: Door - front right side: Door - Deformed - Repair and paint



Damage 9: Door - front right side: Door - Deformed - Repair and paint