TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48506181
Order No. / Reference: 27101156
Inspection date: 20 Oct 2026

Manufacturer: Mercedes-Benz	Model: E 300 d 4Matic Cabrio 9G-TRONIC Avantgarde
VIN: W1K1K1KB9PF197704	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 300 d 4Matic Cabrio 9G-TRONIC Avantgarde	
Vehicle Identification number	W1K1K1KB9PF197704
Mileage (Read)	105,373 km
First registration	5 Apr 2023
Number of holders	1
Next periodical technical inspection (read from ZBI)	05/2028
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,992 ccm / 4
Power	195 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	Convertible / Roadster
Colour / colour code	Polarweiß
Doors / Seats	2 / 4
Upholstery type	Leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	261 Tag(e)
Last service on / at	07/2026 at 99,051 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ149130
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AWM 00097		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,555 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R19 98Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	275/35 R19 100Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- Exterior mirror housings with integrated ambient lighting
- Basic services
- Diesel particulate filter
- Third brake light
- Electronic Stability Program (ESP)
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Transmission: 9-speed automatic, 9G-TRONIC
- Interior lighting
- THERMATIC automatic climate control
- Headrests (4)
- Paint finish: Solid
- Steering wheel: Multifunction steering wheel in Nappa leather in a 3-spoke design
- Steering: Direct steering
- Center console piano black finish
- Navigation: Hard disk navigation
- Package: Storage
- Upholstery: Black leather, sun-reflecting
- Radio: Extended MBUX functions
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Remote Services Plus
- Windscreen wipers with rain sensor
- Service interval indicator ASSYST
- Seats: i-Size child restraint system
- Cruise control
- High-visibility vest for drivers
- Electronic immobilizer
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- 4MATIC all-wheel drive
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Tachometer
- DYNAMIC SELECT
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Velour floor mats in interior color
- Interior headliner in Crystal Grey fabric
- KEYLESS-GO start function
- Communication module (LTE) for the use of Mercedes me connect services
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: AVANTGARDE Exterior (Convertible)
- PRE-SAFE system
- Radio: MBUX multimedia system
- Radio accessories: Touchpad with controller
- Trip computer and on-board computer
- Wheels: 45.7 cm (18") light alloy wheels in a 5-twin-spoke design, painted in high-gloss black
- Seats: Rear seat backrests foldable, 50/50 split
- Power outlets: 2 USB ports in the rear
- Convertible top: black fabric convertible top
- Maintenance interval indicator "ASSYST"
- Decorative elements: aluminum with longitudinal brushing, light finish

Extra equipment

- Airbag: Sidebags in the rear, left and right
- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration (Apple CarPlay and Android Auto) - Preparation for Digital Key Handover - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - 66-Liter Fuel Tank)
- Package: Parking package with reversing camera (The parking package with reversing camera makes finding and selecting parking spaces, as well as parking in and out of parallel and perpendicular parking spaces or garages, easier. The active parking assistant steers the vehicle into parking spaces - in conjunction with automatic transmission including cruise control and automatic gear shifting.)
- Seats: Seat heating for driver and front passenger (3 different heating levels can be individually selected for each seat at the touch of a button)
- AIRCAP automatic wind deflector for draft reduction for up to 4 people (including AIRCAP control switch in the center console for activation and deactivation)
- Package: Driving Assistance Package (Active Distance Assist DISTRONIC incl. Active Speed Limit Assist, Extended Automatic Restart on Highways, Route-Based Speed Adaptation with Traffic Jam Function (only when selecting Parking Packages), Active Steering Assist incl. Active Emergency Stop Assist with SOS Function, Emergency Lane Radio, Active Brake Assist incl. Turning and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist incl. Exit Warning, Pedestrian Warning Radio, PRE-SAFE PLUS)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding - ambient lighting in the exterior mirrors)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
2	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
3	Rear bumper	Spoiler (Zierleiste) - Damaged - Replace
4	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
5	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	2nd wheel set	1 alloy rim (nicht Bestandteil der Ausstattung) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Convertible with open roof



Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.





Figure 22: Misc.




Damage 1: Equipment: Vehicle key with remote control (Batterie) - Empty - Replace



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 3: Rear bumper: Spoiler (Zierleiste) - Damaged - Replace



Damage 3: Rear bumper: Spoiler (Zierleiste) - Damaged - Replace



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace