TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48591528
Order No. / Reference: 27206402
Inspection date: 9 Nov 2026

Manufacturer: Audi	Model: A5 Sportback 35 TDI S tronic
VIN: WAUZZZF57PA065904	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A5 Sportback 35 TDI S tronic	
Vehicle Identification number	WAUZZZF57PA065904
Mileage (Read)	106,649 km
First registration	29 Aug 2023
Number of holders	2
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	navarrablau metallic (X5H)
Doors / Seats	5 / 4
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-1,000 km
Last service on / at	06/2024 at 28,835 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV267628
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BPN 00803		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,120 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 94H	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/50 R17 94H	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 94H	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/50 R17 94H	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Front side airbags and head airbag system (front side airbags integrated into the seatbacks; with additional head airbag system; deploys in front of the side window area and thus helps to protect front and outer rear passengers in the event of a side impact)
- Audi drive select (The desired vehicle characteristics can be selected via various modes to ensure the right driving experience at all times: - auto - comfort - dynamic - individual - efficiency)
- Audi pre sense city (Within system limits, an impending collision with vehicles and pedestrians can be detected at speeds up to approximately 85 km/h. In this case, the system warns the driver visually, audibly, and, if necessary, with a braking jolt. It can initiate full deceleration if required to reduce the collision speed or, if possible, avoid the collision altogether.)
- Automatic climate control (1-zone - electronically regulates air temperature, volume and distribution, sun position-dependent control - air distribution can be set using 5 main positions - 3 LEDs integrated into the seat heating/ventilation buttons provide feedback on the selected setting (optional) - buttons for defrosting the front and rear windows - manual recirculation control - with key recognition and humidity sensor - dust and odor-removing cabin air filter)
- Camera-based traffic sign recognition (supported by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions. If a traffic sign is outside the camera's field of view, it is retrieved from the stored navigation data of the MMI Navigation plus. The traffic sign recognition is displayed automatically in the Audi virtual cockpit and can be configured via the multifunction steering wheel).
- Chassis: Standard chassis (The standard chassis combines very good ride comfort with good driving dynamics. Shock absorbers and coil springs on the front and rear axles - with 5-link lightweight front axle, stabilizer bar; front axle carrier rigidly bolted to the body - with 5-link lightweight rear axle with independent suspension, stabilizer bar; rear axle carrier elastically mounted)
- Cruise control with adjustable speed limiter (The cruise control maintains the individually set speed above 20 km/h, provided the engine power allows it. The adjustable speed limiter helps to prevent exceeding a previously set maximum speed from approximately 30 km/h, e.g., within built-up areas.)
- Decorative inlays diamond lacquer silver grey (for dashboard, door panels and center console)
- Drive slip control
- First aid kit with warning triangle (warning triangle - first aid kit - 2 high-visibility vests)
- Front and rear floor mats (made of velour in black; in conjunction with interior design selection, interior S line or in the S model with contrast stitching color-matched to the respective interior color)
- Glazing: Windscreen in heat-insulating and acoustic glazing (windscreen in heat-insulating glazing, green tinted - improved external noise insulation)
- Accent surfaces in matte black (for dashboard, trim panels in door sills and center console insert)
- AdBlue tank (12 liters)
- Airbag for driver and front passenger (full-size airbag, with front passenger airbag deactivation)
- Anti-lock braking system (ABS) (with electronic brake force distribution (EBD) and brake assist)
- Audi connect Emergency Call & Service including vehicle control (Emergency Call & Service: - Emergency call - Online breakdown call - Audi damage service - Audi service appointment online Vehicle control: - Vehicle status report - Remote control locking/unlocking - Parking position - Remote control auxiliary heater - Anti-theft alarm notification)
- boot floor mat
- Diesel particulate filter (DPF) with DeNox catalyst and AdBlue tank
- Door sill trims with aluminum inlay (on the door sills)
- Electric front windows (with one-touch up/down function (including excess force limitation) and comfort operation)
- Electrically adjustable/heated exterior mirrors (with integrated LED indicator, convex, flat or aspherical mirror glass, including heated windshield washer nozzles)
- Electrically opening and closing tailgate (opening via the button on the vehicle key, the button in the driver's door panel, or the soft-touch button in the tailgate handle recess, or by a foot gesture (kick movement) in conjunction with the comfort key including sensor-controlled tailgate release; closing via the button on the inside of the tailgate, the button in the driver's door, or via the comfort key (continuous press), or by a foot gesture (kick movement) in conjunction with the comfort key including sensor-controlled tailgate release)
- Electromechanical parking brake (includes parking brake function when stationary - starting aid by automatic release when starting and emergency braking function while driving via all four wheels)
- Electromechanical power steering (maintenance-free rack and pinion steering with speed-dependent steering assistance; precise steering feel at high speeds, excellent support when parking.)
- Electronic immobilizer (integrated into engine control unit, activated by vehicle key)
- Electronic Stability Control (ESC) (networks ABS, EBV, ASR and EDS with its own sensors and compares the driving data with reference data; ensures greater stability at any speed by selectively braking individual wheels and intervening in engine management)
- Exterior mirror housings in body color
- front center armrest
- Front seats (standard seats) (with manual adjustment of seat height, seat longitudinal position, backrest angle, headrest and seat belt height)
- Fuel tank (40 liters)
- Green heat-insulating glazing (green tinted - for rear window, door and side windows - rear window heated, with timer)

- Gloss package (roof frame and window channel strips in anodized aluminum)
- Interior lighting (front and rear roof module including capacitively operated front reading lights, illuminated make-up mirror, ambient light on center console, glove compartment light)
- Lane Departure Warning (within system limits, helps prevent unintentional lane departures. If the system is activated and ready, and the driver has not used the turn signal, the Lane Departure Warning helps prevent crossing detected lane markings by making corrective steering interventions. Additional steering wheel vibration can be set at the driver's request. Operating range from approximately 60 to a maximum of 250 km/h)
- LED headlights (using LED technology; low beam, high beam, daytime running lights and position lights in LED; turn signals in incandescent technology, with all-weather light)
- Mild hybrid (Mild hybrid features an enhanced start-stop function, extended energy recuperation during braking to charge the starter battery, and additional lithium-ion storage. This allows the system to recover more energy and switch off the engine more frequently. A supplementary belt-driven starter generator (BSG) is conceptually included for mild hybrid systems. Purely electric driving is not possible.)
- Parking aid plus (Using data from the ultrasonic sensors integrated into the bumpers, the acoustic and optical parking aid at the front and rear assists with parking, maneuvering, and exiting parking spaces. Depending on the steering angle and direction of travel, the distance to detected objects is displayed in a selective, optical representation on the MMI touch display.)
- Radio: MMI Radio Plus (10.1" color display (1,540 × 720) including MMI touch operation - Audi music interface with 1 USB-A and 1 USB-C port, each with data and charging function - Bluetooth interface (hands-free calling and audio streaming) - 8 passive speakers - AM/FM phase diversity - speed-dependent volume adjustment - voice control system with natural language for controlling infotainment and vehicle functions - WLAN hardware - DAB+ digital radio)
- Seat belts: Three-point automatic seat belts for all seats (front seat belt wearer detection, color-coordinated with the interior, front belt force limiter, front belt tensioner)
- Tachometer
- third brake light
- Transmission: S tronic (7-speed)
- Wheel: Alloy wheels "15-spoke design" (7.5 J x 17 with tires 225/50 R 17)
- Wheel: Tire pressure monitoring system (visual and audible warning in case of pressure loss in one or more wheels)
- Headliner in fabric (atlas beige or titanium grey, color-matched to the respective interior color)
- Headrests (4) (height adjustable front and rear)
- Interior mirror dimming
- ISOFIX and Top Tether child seat anchorage for the outer rear seats (standard mounting for practical attachment of ISOFIX child seats - Incl. additional attachment point (Top Tether) - The recommended child seats are available from your Audi partner)
- LED rear lights (indicator, brake, tail, reversing and rear license plate lights in LED technology. Brake lights in LED technology enable earlier detection by following traffic due to faster activation.)
- Manual child lock
- Non-smoking version (one 12-volt socket each in the center console at the front in front of the gearshift/selector lever and at the rear for the 2nd row of seats - no cigarette lighter)
- Outdoor temperature display
- Radio accessories: 8 speakers
- Radio accessories: Data module Europe
- Rear seat backrest foldable (split in a 40:20:40 ratio or fully foldable, with center armrest)
- Remote key, without Safe-Lock (locks and unlocks doors, luggage compartment and fuel filler flap - including Keyless-Go - including comfort closing/opening of windows)
- Start-stop system (helps reduce fuel consumption and CO2 emissions by switching off the engine during stationary phases, e.g. at traffic lights. For restarting, the starting process is initiated as soon as the foot brake is released. Can be deactivated at any time via a button.)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction (with 6 multifunction buttons for operating the basic functions of the existing infotainment system; height and distance adjustable, with full-size airbag; leather steering wheel rim)
- Telephone: Bluetooth interface (The smartphone can be connected to the vehicle via Bluetooth to play music or make phone calls. Two mobile phones can be connected simultaneously for hands-free calling. Complete contact data is only displayed from the first primary phone registered in the MMI. Depending on the smartphone model, emails and SMS messages can also be displayed in the MMI via Bluetooth.)
- Upholstery: Fabric upholstery Index (for standard seats: - Seat center panels in fabric Index rock grey or black - Seat side bolsters, headrests and center armrest in fabric solid rock grey or black)
- Wheel: Low rolling resistance tires, speed-limited (size 225/50 R17, maximum permissible speed 210 km/h)
- Wheel: Tire repair kit (12V compressor and tire sealant, maximum speed 80 km/h)

Extra equipment

- Black glass-look accent surfaces (for dashboard, door trim panels and center console insert; in conjunction with automatic transmission including cover for storage compartment in the center console)
- Decorative inlays in matt brushed aluminum (for dashboard, door panels and center console)
- Hold assist (holds the vehicle after stopping on inclines and declines typical in road traffic for an unlimited time).
- Comfort automatic climate control 3-zone (in addition to the automatic climate control: - climate control unit with large TFT display and capacitive rocker switches - electronically regulates the air temperature and distribution individually for driver and front passenger - additional climate control unit for setting the rear passenger compartment temperature in the rear center console - automatic recirculation control via air quality sensor, with dust and odor-removing allergen filter - ventilated glove compartment - dust and odor-removing cabin air filter - residual heat utilization)
- Driving Assistance Package (Audi active lane assist - Adaptive speed assist - Audi pre sense rear and basic - Traffic jam assist - Predictive efficiency assist - Evasive steering assist - Left turn assist - High beam assist - Lane change warning)
- S line interior package (sports seats in front - S line seat covers in black fabric/leather combination with S embossing on the backrests of the front seats - 3-spoke leather steering wheel with multifunction plus including steering wheel grips in perforated leather and S emblem; steering wheel and gearshift boot with contrast stitching, color-coordinated - headliner in black fabric - decorative inlays in matt brushed aluminum with accent surfaces in gloss black - pedals and footrest in stainless steel - floor mats front and rear with contrast stitching)
- Package: Ambient Lighting Package (in addition to the interior lighting: - approach lighting in the exterior door handles - entry lights on the underside of the front doors - illuminated front cupholders - front footwell lighting - illuminated interior door handles - ambient door lighting - ambient lighting in the front center console)
- Reversing camera (captures the area behind the vehicle within the system limits. The display is adjusted according to the steering angle using dynamic display elements in the MMI touch display. The user can choose between perpendicular parking and trailer modes. Depending on the selected mode, the calculated driving lane or a guide line for coupling a trailer is displayed, also dependent on the steering angle. The reversing camera is activated by engaging reverse gear or via a button in the center console.)
- Seats: Electrically adjustable front seats with memory function for the driver's seat (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt; with memory function for the driver's side: 2 memory locations for the electrically adjustable front seats and the exterior mirrors, storable and recallable via the memory buttons in the door trim)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides with memory function (with integrated LED turn signals and curb view function for the passenger-side exterior mirror; aspherical mirror glass, including heated windshield washer nozzles. The passenger-side exterior mirror tilts downwards when reverse gear is engaged, providing the driver with a better view of the curb).
- Fuel tank (54 liters)
- Paint finish: Metallic
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus (height and reach of the leather steering wheel are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with 12 multifunction buttons. Includes a leather gearshift/ selector lever knob and a leatherette handbrake grip.)
- Navigation: MMI Navigation plus with MMI touch (navigation system on the high-resolution 10.1-inch color display, map updates, 3D city display, MMI search, MMI touch, online traffic information plus, Bluetooth interface, DAB+ digital radio reception, AM/FM phase diversity, WLAN hardware - Audi connect Navigation & Infotainment: hazard information, weather information, online voice input, WLAN hotspot, Amazon Alexa integration, online radio)
- Comfort package seats (variable headrests for the front seats - 4-way lumbar support for the front seats, electrically adjustable horizontally and vertically - comfort center armrest in the front, longitudinally adjustable and tiltable; additional storage option in the integrated storage compartment)
- Comfort Package Mirrors (Interior mirror automatically dimming, frameless - Exterior mirrors electrically adjustable, heated and folding, automatically dimming on both sides with integrated LED turn signals and curb view function for the passenger-side exterior mirror; mirror glass convex, flat or aspherical, including heated windshield washer nozzles. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, giving the driver a better view of the curb.)
- Three-seater rear seating system (distinctive outer rear seats, visually adapted to the front seats and an additional middle seat - 3 rear L-shaped headrests, manually height-adjustable for better rear visibility; rear seat backrest split in a 40:20:40 ratio or fully foldable)
- Seat covers in microfiber Dinamica Frequency/leather with S embossing (seat center panel in microfiber Frequency - seat side bolsters, headrest center panel and center armrest in leather black or rotor grey with contrasting stitching - S embossing in the backrests of the front seats)
- Front seat heating (heats seat and backrest center section, with leather upholstery and sport seats; also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via direct selection button on the climate control unit)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - Smart repair
2	Misc.	Inspection / maintenance - No evidence - Perform
3	Door - rear left side	Door - Scratch(es) - Paint
4	Boot lid / rear door	Boot lid - Scratch(es) - Paint
5	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
6	Front bumper	Front bumper - Scratch(es) - Paint
7	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance (Letzter Eintrag 2024) - No evidence - No deduction
2	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
3	Door - front right side	Door edge - Scratch(es) - No deduction
4	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 2: Misc.: Inspection / maintenance - No evidence - Perform



Damage 3: Door - rear left side: Door - Scratch(es) - Paint



Damage 3: Door - rear left side: Door - Scratch(es) - Paint




Damage 3: Door - rear left side: Door - Scratch(es) - Paint




Damage 4: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 4: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 4: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 4: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 5: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 5: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 5: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint




Damage 5: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 5: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage 6: Front bumper: Front bumper - Scratch(es) - Paint



Damage 6: Front bumper: Front bumper - Scratch(es) - Paint



Damage 6: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint