TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48199553
Order No. / Reference: 27130183
Inspection date: 19 Oct 2026

Manufacturer: Mercedes-Benz	Model: EQE 350 AMG Line
VIN: W1KEG2FBXPF030982	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz EQE 350 AMG Line	
Vehicle Identification number	W1KEG2FBXPF030982
Mileage (Read)	98,101 km
First registration	30 Aug 2023
Number of holders	1
Fuel type	Electric
Power	109 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	sodalithblau Metallic-Lacke
Doors / Seats	4 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	560 Tag(e)
Last service on / at	03/2026 at 92,227 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV748876
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BIN 00983		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,880 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	255/45 R19 104Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Automatic passenger airbag deactivation (The system automatically deactivates the passenger airbag as soon as it detects a rear-facing child seat or registers that the passenger seat is unoccupied. A transponder in the child seat is not necessary. If it detects that an adult is taking the seat, the airbag is automatically activated, reducing the risk of incorrect operation.)
- Ambient lighting (Stage the interior according to your personal preference or current mood. The 64 colors of the ambient lighting create fascinating color worlds that change dynamically or illuminate several areas in different colors.)
- Black fabric headliner
- Brake Assist, active (radar-based driver assistance system with mono camera functions: -distance warning -collision warning -autonomous emergency braking, which is activated after the dynamic warning if a collision is imminent -situation-appropriate brake support as soon as the driver brakes -intervention time settings: early, medium and late; if the emergency braking exceeds certain acceleration values, functions of the PRE-SAFE system can also be activated)
- Charging cable for wallbox and public charging station, 5m, smooth 11kW (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A).)
- Charging system: Direct current charging system (DC charging) (For optimal charging speed with a maximum of 200 kW* and therefore high convenience. Fast charging stations such as IONITY supply the direct current required for your high-voltage battery. Thus, the DC charging system provides a long-distance-capable range in the shortest possible time.)
- Climate: Pre-conditioning (Enjoy your ideal climate right from the start. Simply set the time and temperature in advance – via Mercedes me or on the head unit. Heating or cooling the interior while charging also helps maintain battery power when starting the car.)
- Cruise control
- Flex-Bottleholder (With the Flex-Bottleholder, your drinks are always within easy reach and can be securely placed in the center console. The practical, large double cupholder holds two bottles or cups with a volume of up to 770 ml.)
- Heat pump (Increase the range of your electric vehicle, especially in cold temperatures. The heat pump efficiently uses the waste heat from the electric drive and the high-voltage battery to heat the interior. This significantly reduces the need for battery power for heating, giving you greater range.)
- Heated windshield washer system (with heated windshield washer nozzles and heated washer hoses)
- High-visibility vest for drivers
- Illuminated door sills with "Mercedes-Benz" lettering
- ABS - Anti-lock Braking System
- Acoustic Surrounding Protection (To ensure that your electric vehicle does not become a danger to pedestrians and cyclists during almost silent driving, the Acoustic Surrounding Protection generates Mercedes-Benz specific sounds outside the vehicle up to a speed of approximately 30 km/h. It distinguishes between forward and reverse driving.)
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Windowbag all around
- AMG floor mats
- AMG sports pedal assembly made of brushed stainless steel with black rubber studs
- ATTENTION ASSIST (the attention assistant) (detects signs of fatigue via steering behavior and can warn the driver of impending microsleep)
- Charging system: AC charging system 11kW (More flexibility: With the powerful AC charging system, you can charge your plug-in hybrid quickly and easily with up to 11 kW (3-phase) or 7.4 kW (1-phase). In addition to a wallbox at home, you can also connect your vehicle to a variety of public charging stations. These usually supply alternating current – just like conventional sockets.)
- Door center panels and transition from the center console to the instrument panel in microfiber MICROCUT (black with red decorative stitching)
- DYNAMIC SELECT (With DYNAMIC SELECT, you can choose between the driving programs ECO, COMFORT, SPORT and INDIVIDUAL. The SPORT mode mobilizes the vehement power of the electric drive even more spiritedly. Regardless of the driving program, you can adjust the regenerative braking using the steering wheel shift paddles.)
- Electronic Stability Program (ESP)
- Instrument panel and door edges in ARTICO space grey imitation leather (with NEOTEX grain and red decorative stitching)
- LED taillights in 3D helix design (with light strip at the rear)
- Navigation accessories: Pre-installation for Live Traffic Information (Arrive at your destination stress-free, via the best route, and faster. Live Traffic Information receives more precise and up-to-date traffic data in real time than conventional systems and optimizes dynamic route guidance. Whether during rush hour or on a journey: You can react to many situations and easily bypass traffic jams and stop-and-go traffic.)
- Navigation: MBUX Navigation Premium (hard drive navigation - high-resolution navigation with satellite view - live traffic information and Car-to-X communication - fast online route calculation - map data updates: via Mercedes me connect with automatic over-the-air update via USB stick at a Mercedes-Benz dealer - navigation services: local search, online search, ads)

- LED High Performance headlights (low beam in LED reflection technology - high beam in LED reflection technology - signal light with trifunctional torch for daytime running light, position light and direction indicator in LED technology - adaptive full-LED taillights)
- Mercedes-Benz Emergency Call System (can provide a crucial time advantage in an emergency. A communication module with its own SIM card automatically triggers an emergency call upon detection of an accident, which can shorten the time until emergency services arrive. The emergency call can also be triggered manually to organize assistance.)
- Navigation accessories: Pre-installation for navigation services (Wherever you go, you're always well-informed. Your vehicle answers your questions about your journey. You can find out the number of currently available parking spaces or the current weather. This makes trip planning even easier. Helpful extra: The digital logbook automatically records your journeys upon request.)
- Navigation: Hard disk navigation (Save time with fast hard disk navigation and flexible input via touch or voice control. The 3D displays of landmarks are also a visual treat. The intelligent system reliably guides you to your destination, accessing both local and up-to-date online information.)
- Package: AMG Line Exterior (AMG-specific front bumper painted in body color with A-wing, front splitter, flics and fins on the left and right air intakes in high-gloss black with chrome trim, AMG-specific rear apron painted in body color with diffuser-look insert in high-gloss black, chrome trim strip and flics on the left and right air outlets in grained black, 48.3 cm (19") AMG light-alloy wheels in 5-spoke design (RRH), heat-insulating dark-tinted glass for rear side windows and rear window, black-panel radiator grille with central star)
- Paint finish: Metallic
- Pre-installation for digital key handover (With the pre-installation for digital key handover, you can share your vehicle with a group of people you define more easily than ever before. You retain full control and must explicitly agree to each use. Car sharing is implemented using a smartphone app and a temporarily activated second key.)
- PRE-SAFE System (The PRE-SAFE System utilizes the time before an impending accident. A variety of measures can reduce the stresses that occur. The innovative PRE-SAFE Sound generates a noise from the speakers and can trigger a natural protective reflex. This protects the inner ear by dampening the noise of the accident.)
- Radio accessory: Communication module (5G) for use with Mercedes me connect (The communication module transmits larger data volumes at high speed. The term "Advanced" refers to a particularly powerful mobile communications standard. You always benefit from this Turbo LTE, for example through even faster information flow in the many Mercedes me comfort services or Car-to-X communication.)
- Package: Display (Driver display with 12.3-inch (31.2 cm) screen diagonal, LCD with LED matrix backlighting - OLED central display with 12.8-inch (32.5 cm) screen diagonal and haptic feedback - Fingerprint scanner in the control bar below the central display - MBUX multimedia system CONNECT 20 Premium)
- Package: Interior lighting package
- Package: Parking package with reversing camera (Active Parking Assist with PARKTRONIC detects free parking spaces as you drive past. Once a parking space is selected, you can confidently park thanks to the reversing camera, ultrasonic sensors and practical visualizations - or let the system park you.)
- Pre-installation for remote and navigation services (The world of Mercedes me offers many services for your electric comfort experience. With navigation and active range monitoring, you receive corresponding range security, including necessary charging stops. The route calculation takes into account the current consumption, route profile, and checks whether the desired charging station is available.)
- Radio accessories: Digital radio (Digital radio offers you even more information and entertainment through significantly more programs. Choose your personal favorite stations. At the same time, the clear, noise-free reception enhances the listening experience.)
- Radio: Extended MBUX functions (personalization (profiles) and prediction functions - MBUX voice assistant "LINGUATRONIC" with natural language understanding - activation via Hey Mercedes - learning function of the MBUX voice assistant through connection with a cloud-based online dictionary, Mercedes me connect service free of charge for 3 years from activation - Wi-Fi hotspot - internet radio)
- Rear seat belt status indicator in the instrument cluster
- Remote and Charging Services Premium (pre-installation for Mercedes me Charge, free for 3 years from activation; pre-installation for IONITY: discounted fast charging, free for 1 year from activation; Mercedes me Services communication module)
- Remote Services Plus (Communication module - Mercedes me services: remote vehicle status query, programming of auxiliary heating/ventilation, remote door locking and unlocking, sunroof/ windows with remote locking and opening including ventilation remote control, personalization, vehicle location, vehicle tracking, geographic vehicle monitoring, parking service monitoring, finder function (Remote Vehicle Finder), notification when exceeding the driving speed, Send2Car function)
- Seats: Heated seats for driver and front passenger (The intensity can be selected in three levels. Intelligent and comfortable: The seat heating switches off automatically.)
- Seats: Rear seat backrests foldable 40/20/40 split (If you only fold down the middle segment for longer items, the two outer seats remain fully usable.)

- Radio: MBUX multimedia system (instrument display with 17.78 cm (7") diagonal - media display with 17.78 cm (7") diagonal and touch function - touch control buttons on the steering wheel - radio (FM/ AM) - USB interface in the center console under the armrest - Bluetooth telephony with contact transfer and audio streaming of music files - display of vehicle functions (driver assistance systems, driving programs and vehicle settings) - favorites storage - smartphone-related voice control)
- Rear headrests (3)
- Remote and Extended Charging Services Premium (The Remote and Extended Charging Services Premium connect you to your vehicle. You can locate it and control its functions remotely. With Mercedes me Charge, you can charge your vehicle at many public charging stations with maximum cost transparency and centralized billing. Also included: 1 year of free fast charging at IONITY stations.)
- Remote Services Premium (Communication module - Mercedes me services: remote vehicle status query, programming of auxiliary heating/ventilation, remote door locking and unlocking, sunroof/ windows with remote locking and opening including ventilation remote control, personalization, vehicle location, vehicle tracking, geographic vehicle monitoring, parking service monitoring, finder function (Remote Vehicle Finder), notification when exceeding the driving speed, Send2Car-Fun.)
- Seats: i-Size child seat attachment (in the rear - The system allows for quick and easy installation of i-Size child seats in the rear for the best possible protection of your child in the event of an accident. Top tether attachment points offer additional safety by anchoring the child seat behind the rear headrests.)
- TIREFIT (Your quick temporary solution for minor tire damage. Damage caused by embedded nails or shards of glass is sealed by sealant blown in via an air compressor. This allows you to continue driving to the nearest repair shop at speeds of up to 80 km/h.)
- Traction control (ASR)
- Transmission: Direct drive
- Upholstery: ARTICO leatherette/MICROCUT microfiber, two-tone
- Seats: Sports seats (The optimal combination of sport and comfort: The slim sports seats are reminiscent of integrated seats and optimize lateral support for dynamic driving. At the same time, they offer unrestricted everyday comfort. A design highlight: the wraparound contour lighting. 4-way lumbar support.)
- Speed Limit Assist (The system shows what is permitted: It can detect the current speed limit via the camera and display it in the instrument cluster. Additional restrictive signs for special weather conditions such as wet conditions are also detected.)
- Steering wheel: Multifunction sports steering wheel in Nappa leather (sporty steering wheel in a 3-twin-spoke design, flattened at the bottom - finished in Nappa leather, deeply embossed in the grip area - horizontal double spokes in high-gloss black, vertical double spokes in silver chrome - shift paddles in silver chrome - control via touch panels: left: instrument cluster, cruise control and limiter or Active Distance Assist DISTRONIC; right: multimedia system (e.g., audio volume and track selection, telephony and navigation), touch sensitivity adjustment)
- THERMATIC automatic climate control with 2 climate zones (allows individually adjustable temperature for driver and front passenger side; sensor system for detecting, for example, interior/exterior temperature, solar radiation, humidity and dew point; automatic recirculation; fine dust activated carbon filter for filtering dust, soot and pollen as well as for reducing pollutants and odors; dew point sensor, continuous defrost nozzle under the windshield and central defrost outlet, 2 fixed defrost nozzles for the side windows)
- Tire pressure monitoring system (This system monitors your tire pressure and warns you if it drops. This allows you to react more quickly to dangerous situations. Low tire pressure can also increase braking distance. If the system alerts you, you should add air as soon as possible. Correct tire pressure also increases tire life.)
- Wheels: 48.3 cm (19") AMG light-alloy wheels in 5-twin-spoke design (aerodynamically optimized, painted black and polished with 255/45 R19 tires on 8.5J x 19 ET47.5)

Extra equipment

- DIGITAL LIGHT with projection function in conjunction with Advanced/Advanced Plus package (HD system with projection module and background module MULTIBEAM LED: Using data from camera, sensors and navigation, the brightness value for each individual pixel is calculated almost in real time; projection function for lines, symbols, animations; adaptive high beam assist Plus ULTRA RANGE high beam; topography compensation; cornering lights with roundabout and intersection radio; active curve lighting with predictive control; extended fog lights, city lights, country road lights, motorway lights, motorway high beams and bad weather lights; front light strip)
- Steering wheel: Steering wheel heating
- Center console fine texture look black
- Package: Premium Plus (Wireless charging system for mobile devices in the front storage compartment, mirror projection of brand logos, flush door panels, Android Auto/Apple CarPlay, interior and center console, memory parking, KEYLESS-GO, comfort parking, trunk lid comfort closing, HANDS-FREE ACCESS, active ambient lighting, Burmester surround sound system, THERMOTRONIC climate control, driver assistance parking, parking parking, 360° camera, Guard 360° vehicle protection, MBUX, real-time navigation display, panoramic sunroof, head-up display, USB port, digital headlights with projection, energy-saving parking)
- Seats: Heated rear seats (Comfortable warmth in cooler weather for your rear passengers too: the heated seats quickly bring the seat cushions and backrests of the outer rear seats to a pleasant temperature. The intensity can be selected in three levels. Intelligent and convenient: the heated seats switch off automatically.)
- Chassis: AIRMATIC (air suspension struts on the front and rear axles with integrated adaptive damping system - automatic level control, depending on the load: load detection for a constant chassis level - chassis level can be raised on rough roads, automatic lowering at high speeds)
- Radiator grille with Mercedes-Benz pattern (The black panel radiator grille features finely designed stars)
- Charging cable for household socket, 8m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 2.3 kW (230 V, 1-phase, 10 A) and fits sockets of type E/F CEE 7/7)
- Package: Night for AMG Line Exterior (Exterior mirror housings in black - Belt and window line trim strips in black - Heat-insulating dark tinted glass from B-pillar - Door trim strips in black chrome - Trim parts on A-wing and front splitter in black chrome - Trim element on the rear apron with two louvers each on the left and right in black chrome)
- Radio accessories: Burmester surround sound system (15 powerful speakers - DSP amplifier with a total output of 710 W - Two 3D speakers in the front for 3D sound - Frontbass technology - Sound optimization - 2 sound presets Pure and 3D sound - Sound Experience for the interior adjustable via central display - Equalizer function for adjusting bass, midrange and treble - Noise compensation - Sound personalization - MBUX Entertainment connects your vehicle directly to streaming services)
- Decorative elements laser-cut and backlit with Mercedes-Benz pattern

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
2	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
3	Seat - front	Backrest - right side (Verkleidung) - Scratched - Replace
4	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Replace
5	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Replace
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Replace
7	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction
3	Sill - right side	Trim - Scratch(es) - No deduction
4	Door - rear left side	Door - Scratch(es) - No deduction
5	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 3 Oct 2025	3.315,50 €
2	Front, Provided by user / customer, from 22 Oct 2025	3.320,54 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.





Figure 23: Misc.



Figure 24: Misc.




Damage 1: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




Damage 1: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 2: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 2: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 3: Seat - front: Backrest - right side (Verkleidung) - Scratched - Replace



Damage 3: Seat - front: Backrest - right side (Verkleidung) - Scratched - Replace



Damage 3: Seat - front: Backrest - right side (Verkleidung) - Scratched - Replace




Damage 3: Seat - front: Backrest - right side (Verkleidung) - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace




Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace




Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 5: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 7: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 7: Vehicle glazing: Windscreen - Broken / torn - Replace