MACADAM
Polestar Polestar 2 '19 BEV


Vehicle information

Make:	**Polestar**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Polestar 2 '19 BEV**	VIN:	**YSMVSEGE4PL118371**
Fuel type:	**Electric**	Power:	**170 kW**
Version:	**78kWh Sing.M.Lo.Ra.**	First registration	**21/10/2022**
Mileage:	**106201 km**	N° of doors:	

Damage summary

Front	2
Interior	1
Left	2
Rear	3
Right	2

Commercial pictures












17°C
Trip
Trip handmatig (TM)
9 976.9 km
18.7 kWh/100km
43:23 h
72 km/h
Trip automatisch (TA)
0.0 km
-- kWh/100km
00:00 h
-- km/h
Accuading
76%
Klik om TM te resetten
ODO 106 201 km
Rem en schakel RD om te starten




YSMVSEGE4PL118371


HANKOOK




MICHELIN






Polestar 2



07:44
P


07:45
Zoeken
20°


Batterijcertificaat
Datum van diagnose: 19/10/2026
92,73%
Status van de gezondheid (SOH)*
Polestar 2 LR Single motor
VIN : YSMVSEGE4PL118371
Kilometerstand : 106.201 km
* SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA







Options according to the inspector



Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Panoramic roof	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Telephone equipment	**Yes**				

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left




Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right

Alloy rim RL
Scratch(es)
Repair and paint (complete)
Left





Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right





Boot cover
Broken
Replace
Rear






Boot lid covering R
Scratch(es)
Smart repair
Rear





Bumper F
Scratch(es)
Repair and paint (complete)
Front










Bumper R
Scratch(es)
Repair and paint (complete)
Rear








Interior
Stain
Cleaning
Interior





Windscreen
Stone chip(s)
Windscreen repair
Front





Tyres

Front Left	
Winter	
245/45/19/102/V	
Hankook	
5.3 mm	
Front Right	
Winter	
245/45/19/102/V	
Hankook	
3.8 mm	
Rear Left	
Winter	
245/45/19/102/V	
Michelin	
6.0 mm	
Rear Right	
Winter	
245/45/19/102/V	
Michelin	
5.2 mm	

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
Luggage cover	**Yes**	Number head rests	**3**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Service book	**N/A**
User's manual	**Yes**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.