APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	BMW
Model / version:	3 SERIES SEDAN
Wine:	WBA5F31070FL47713
Plate:	2APX532
Mileage:	126060
First registration:	07/06/2021
Color:	Mineral Grey

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES











































WINE INFORMATION

Automatic transmission	8 reports	Adaptive headlights
LED fog lights	Luxury Line Equipment	Material: alloy
Reference letter (J)	Front diameter 17	Rear diameter 17
Front width 7.5	Rear width 7.5	Front diameter 17
Rear diameter 17	Front height 50	Rear height 50
Forward speed index Y	Rear speed index Y	Front width 225
Rear width 225	Flat steel spare wheel	Dual-zone automatic climate control
Air conditioning refrigerant 1234YF	Interior wood finish	Essence
1998 cm3	2.00 liters	135 kW
183 hp	Euro 6	Glazed mineral
Automatic day/night left rearview mirror	Automatic day/night right-side rearview mirror	Electrically folding mirrors

Automatic day/night interior rearview mirror	Ski bag	Leather trim
Leather steering wheel	Sports steering wheel	Front parking assistance
Rear parking assistance	Front camera	Automatic distance control
Stop & Start Equipment	Alarm	Emergency call
Passenger airbag can be deactivated	Pedestrian protection	Lane Keeping Assistant
Autonomous emergency braking assistance (urban)	Blind spot warning system	Forward collision warning
Tire pressure check	since 03.21	ambient lighting
extended CO2 measures	Teleservices	DAB tuner
BMW Live Cockpit Professional	folding rear headrests	storage pack
"Sensatec" dashboard	Glossy Shadow Line window frames	Europe-specific

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	5 mm	Hankook	225/50R17 98V	Winter		?
Front right	5 mm	Hankook	225/50R17 98V	Winter		?
Rear left	5 mm	Hankook	225/50R17 98V	Winter		?
Rear right	5 mm	Hankook	225/50R17 98V	Winter		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
1	Contact key - Boordcomputer resetten	Not original part
2	Bumper F	Teeth and scratches
4	Bumper R	Grooved
5	Alloy rim FR	Grooved

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Teeth and scratches	✓	×	×

Total: 1

DAMAGE DETAILS

1 - Contact key - Boordcomputer resetten - Not original part





2 - Bumper F - Dent(s) and scratch(es)







4 - Bumper R - Grooved




5 - Alloy rim FR - Grooved

3 - Bodywork - Dent(s) and scratch(es) - Renta®












SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

12/10/2026 10:05

