Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 5 Aug 2026
Protocol number: **47836972**

WBA61DP0509N01219

Vehicle details

Operator		**Inspection condition**	sufficient
License number		**Mileage (Read)**	43,714 km
Manufacturer	BMW	**Next maintenance in**	32,000 km
Type / Model	X3 xDrive30e	**Main inspection (Report not on hand)**	08/2027
Vehicle Identification number	WBA61DP0509N01219	**Power**	215 kW
Engine displacement	1,998 ccm	**Cylinder**	—
First registration	22 Aug 2022	**Upholstery/Colour**	Leather / Black
Last maintenance	06/2026, 41,294 km	**Paintwork**	Black
Fuel type	Hybr.B/E ext.aufl	**Gearbox**	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Interior	Rear shelf - Scratch(es) - Smart repair
2	Side panel - rear left side	Sill (+3M Sanft Instandsetzen) - Dent / paintcoat damage - Smart repair

Wear and tear

No.	Component group	Description
1	Indicator - front	Mirror - left side - Abrasion - No deduction
2	Door - rear left side	Door edge - Scratch(es) - No deduction
3	Door - front left side	Door edge - Scratch(es) - No deduction
4	Side panel - rear left side	Side panel (Polier versuch, Folgekosten möglich) - Scratch(es) - No deduction
5	Side panel - rear right side	Sill - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/60 R18	Bridgestone	Summer tyres	4mm - 4mm	Not o.k.	
2	225/60 R18	Bridgestone	Summer tyres	4mm - 4mm	Not o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	12V power outlet
-	2-year warranty
-	Airbag for driver and front passenger
-	Anti-lock braking system (ABS) 3rd brake light in LED technology
-	Attention assistant
-	Automatic tailgate operation
-	BMW xDrive
-	Brake Energy Regeneration
-	Brake pad wear indicator
-	Bumper system
-	Center armrest in the rear
-	Center lock switch
-	Central locking system including 2 remote controls
-	Condition Based Service
-	Cover roller cassette
-	Crash sensor
-	Cruise control with braking function
-	cup holder
-	Door handles in car color
-	Double-joint spring strut front axle
-	Double-tone fanfare
-	Driving experience switch
-	Dynamic brake lights
-	Dynamic Stability Control (DSC)
-	Dynamic Traction Control (DTC)
-	Electric motor
-	electric window regulator
-	Electrically adjustable and heated aspherical exterior mirrors
-	Electromechanical parking brake
-	Electronic immobilizer (EWS)
-	Engine cover
-	Entry strip
-	Exhaust tips visible
-	Front and rear armrests in the center console with storage compartment
-	glove box
-	Head airbags for the 1st and 2nd rows of seats
-	Headlight range control
-	Headrests for all seats
-	Heat/sun protection glazing
-	Heated windshield washer nozzles

Code	Description
-	High-voltage battery including battery certificate
-	Home lights
-	Interior and exterior mirror package
-	Interior lighting
-	Interior trim strips in high-gloss black with pearl-gloss chrome accent strip
-	Internally ventilated front and rear brake discs
-	ISOFIX child seat attachment
-	Knee airbag
-	Lashing eyes in the luggage compartment, 5 seats
-	LED headlights
-	LED taillights
-	Loading flap
-	luggage compartment light
-	Micro/activated carbon filter
-	Model lettering
-	Multi-link rear axle
-	Non-smoking package
-	Oil level and quality sensor
-	Otto particulate filter (OPF)
-	Parking Assistant eDRIVE button
-	Passenger airbag deactivation
-	Passive pedestrian protection
-	Rain sensor and automatic headlight control
-	Rear doors with mechanical child safety lock
-	Rear seat backrest foldable and 40:20:40 split
-	Reversing lights
-	Servotronic
-	Side airbag for driver and front passenger
-	Side impact protection
-	Speed Limiter
-	Sport leather steering wheel
-	Sports seats for driver and front passenger
-	Standard charging cable (Mode 2) for household sockets
-	Start/Stop button
-	Steering column adjustment
-	Stereo speaker system
-	Storage options
-	sun visors
-	Three-point seat belts
-	through-loading system
-	Tire pressure monitoring
-	Tire Pressure Monitoring System (RPA)

Code	Description
-	Tire repair kit for 18" alloy wheels, V-spoke design 618
-	USB port
-	Vehicle key
-	Velour floor mats
-	Warning triangle with first aid kit
-	Welcome light

Extra equipment

Code	Description
025T	18" LM wheel V-spoke 618
03KA	Acoustic comfort glazing
04U9	Acoustic pedestrian protection
05AV	Active Guard
08TF	Active pedestrian protection
05AL	Active Protection
0552	Adaptive LED headlights
A070	AGM battery 70 Ah
0302	Alarm system
04UR	Ambient interior lighting
0775	Anthracite headliner
0534	Automatic air conditioning
0205	automatic transmission
04LU	black high-gloss accent pearlescent chrome
04NE	Blow-by heater
032Z	BMW Digital Key Discontinued
06U2	BMW Live Cockpit Plus
04T1	CHARGING CABLE (MODE 2)
01CB	CO2 scope
0322	Comfort access
06AK	Connected Drive Services
06C4	Connected Package Professional
0654	DAB tuner
06UX	Deletion of touch function BMW controller
05AS	Driving Assistant
0925	Dummy-SALAPA
0459	Electric seat adjustment with memory
0461	Electric seat backrest adjustment, rear
032X	Elimination of touchless operation of rear door panel.
048Z	ENTF. BF-LORDOSENST. /BF-LBV
0230	EU-specific additional scopes
01DF	EU6 rde II emissions standard
0851	German language version
0494	Heated seats for driver and passenger
05AC	High beam assist
0760	High-gloss Shadow Line
06AC	Intelligent emergency call
0431	Interior mirror automatically dimming
0430	Interior/exterior mirrors with automatic dimming
08WC	Local Content Control
0413	luggage compartment partition net
0488	Lumbar support for driver and front passenger

Code	Description
03MC	M roof rails Shadow Line
06WB	Multifunctional instrument display
0548	odometer
08KA	Oil change interval: 24 months/30,000 km
0879	Onboard literature in German
09AA	Outer skin protection
05DM	Parking assistance system
05DA	Passenger airbag deactivation
02VG	Performance Control
08R9	Refrigerant R1234yf
08WL	Special control Bluetooth/WiFi module
0481	Sports seat
0248	Steering wheel heating
0493	Storage package
06AE	Teleservices
0420	tinted glazing
02VB	Tire pressure gauge
03AC	Trailer hitch
02VC	Tyre repair kit
0423	Velour floor mats
0428	Warning triangle and first aid kit
02PA	Wheel bolt lock

Retrofitted equipment

Code	Description
FRFK	RKF HO Flash

Comments

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Vehicle details

Manufacturer	BMW	**Inspection condition**	sufficient
Type / Model	X3 xDrive30e	**Mileage (Read)**	43,714 km
Vehicle Identification number	WBA61DP0509N01219	**First registration**	22 Aug 2022

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
The inspection conditions were sufficient for the assessment of the vehicle.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front




Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior




Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: Interior




Figure 14: Interior




Figure 15: Interior




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.

Pictures of damage



Damage Interior: Interior: Rear shelf - Scratch(es)

- Smart repair



Damage Interior: Interior: Rear shelf - Scratch(es)

- Smart repair



Damage Side panel - rear left side: Side panel - rear left side: Sill (+3M Sanft Instandsetzen) - Dent / paintcoat damage - Smart repair



Damage Side panel - rear left side: Side panel - rear left side: Sill (+3M Sanft Instandsetzen) - Dent / paintcoat damage - Smart repair



Damage Side panel - rear left side: Side panel - rear left side: Sill (+3M Sanft Instandsetzen) - Dent / paintcoat damage - Smart repair