TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48080845
Order No. / Reference: 26920437
Inspection date: 13 Oct 2026

Manufacturer: Seat	Model: Leon 2.0 TDI Reference
VIN: VSSZZZKL1PR000117	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Leon 2.0 TDI Reference	
Vehicle Identification number	VSSZZZKL1PR000117
Mileage (Read)	105,006 km
First registration	22 Sept 2022
Number of holders	1
Next periodical technical inspection	02/2028
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	85 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Asphalt Blau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Dark grey
Re-import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	15,500 km
Last service on / at	02/2026 at 90,423 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ895953
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	7593 / ASD 00142		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,920 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 91T	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	195/65 R15 91H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 91H	Summer tyres on Steel rim with wheel cover	Hankook	6mm / 6mm
2)	195/65 R15 91H	Summer tyres on Steel rim with wheel cover	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the front doors
- Airbag: Passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Exterior mirror housings, bumpers and door handles in body color
- third brake light
- Electronic differential lock XDS
- Electronic parking brake
- Electric window regulator with anti-pinch protection and one-touch function
- luggage compartment cover
- Speed limiter
- Heated rear window
- ISOFIX child seat restraint system, triple in the 2nd row of seats
- Front headrests (2)
- LED technology for headlights, daytime running lights and taillights
- Emergency call service
- Radio: Media System Plus
- Radio accessories: Digital radio reception DAB+
- Wheels: Steel wheels (4) 6 J x 15", wheel covers "Urban I"
- Leather gear knob
- Power steering
- Seats: Driver's seat with height adjustment
- Sun visor on driver and passenger side
- Lane departure warning system
- Power outlet: 12V socket at the front
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control
- Driver and passenger airbags
- Airbag: Head airbag system, front and rear
- Electrically adjustable and heated exterior mirrors
- LED turn signals integrated into the exterior mirrors
- On-board computer
- Diesel particulate filter
- Tachometer
- Electronic Stability Control (ESC) including Anti-lock Braking System (ABS)
- Gear recommendation display
- Luggage compartment lighting
- Transmission: 6-speed manual
- rear window wiper
- Keyless Go (engine start/stop button)
- "Climatronic" air conditioning system
- Rear headrests (3)
- Front reading light
- Fatigue detection
- Upholstery: Cloth
- Radio accessories: 4 speakers
- Tire pressure monitoring system
- Wheels: Tyre fit
- SEAT CONNECT
- Seat belts: Three-point automatic front and rear
- Seats: Rear seat backrest asymmetrically split and foldable
- Start-stop system and recuperation
- Front Assist area monitoring system with City Emergency Braking function
- thermal insulation glazing

Extra equipment

- Deletion of the model designation on the rear
- Navigation system ZN2,PZ4,R3D,R3C
- Package: Winter Package PW1
- Virtual Cockpit PFK
- Paint finish: Metallic
- Package: Comfort Package (Bluetooth - Cruise control - Multifunction steering wheel in leather and leather gear knob)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim (Halter Hutablage) - Broken / torn - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Side panel - rear right side	Side panel (Vogelkotverätzung) - Paint defect - Paint
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Door - front left side	Door - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Waschstraßenkratzer) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side right, Provided by user / customer, from 3 Jul 2026	2.964,10 €
2	Front, Provided by user / customer	
3	Rear, Provided by user / customer	

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der montierte Radsatz ist nicht Bestandteil der Ausstattung.

- Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Damage 1: Trim / covers: Boot lid - interior trim (Halter Hutablage) - Broken / torn - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Side panel - rear right side: Side panel (Vogelkotverätzung) - Paint defect - Paint



Damage 3: Side panel - rear right side: Side panel (Vogelkotverätzung) - Paint defect - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Door - front left side: Door - Corrosion - Repair and paint



Damage 5: Door - front left side: Door - Corrosion - Repair and paint