TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48474169
Order No. / Reference: 27275371
Inspection date: 2 Nov 2026

Manufacturer: Ford	Model: Kuga 2.5 Duratec PHEV ST-LINE X
VIN: WF0FXXWPMHSC71575	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV ST-LINE X	
Vehicle Identification number	WF0FXXWPMHSC71575
Mileage (Read)	31,809 km
First registration	27 Oct 2025
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,488 ccm / 4
Power	111 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Desert Island Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	39 %
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HN224307
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / CBJ 00002		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,400 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104V	All-season tyres on Light alloy	Goodyear	7mm / 7mm
2)	225/60 R18 104V	All-season tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	165/70 R17 114M	Summer tyres on Steel	Maxxis	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 360-degree camera
- Ambient lighting at the front
- Anti-lock braking system
- Exterior mirrors, electrically adjustable, heated and electrically folding with ambient lighting (exterior mirrors painted in body color, electrically adjustable, heated and with integrated turn signals, additionally electrically folding with ambient lighting)
- Roof rails, black
- Design package ST-Line X (ST-Line X Design: - Front door sill trim ST-Line X Design, design strip on the bumper in aluminum, brake calipers painted red and - large roof spoiler)
- Eco Coach (Efficiency indicator for environmentally friendly driving style)
- Selective driving mode switch (5 driving modes to choose from: Normal, Sport, Eco, Slippery and Unpaved Roads)
- Chassis: Sport-tuned chassis
- Electric front and rear windows with all-around closing function
- Front footwell lighting
- Luggage compartment cover, flexible and removable
- Adaptive cruise control (with stop & go function and lane keeping assist)
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Inductive charging station for mobile devices
- ISOFIX mounts on the outer seats of the 2nd row
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- LED taillights
- Steering wheel, ST-Line design, flattened at the bottom (and with red decorative stitching, Sensico in leather look)
- Make-up mirrors in driver and passenger sun visors
- Front center console (with cup holders, integrated armrest and storage compartment underneath)
- Front and rear parking pilot system
- Pedal assembly with aluminum surface
- Upholstery: Premium Sensico upholstery in leather/suede look
- Pre-Collision Assist, additionally with cross-traffic detection (including forward alert system (FA) additionally with cross-traffic detection, camera and radar based, additionally Post-Collision Assist)
- Radio accessories: 5G modem
- Tire Pressure Monitoring System (TPMS)
- Wheels: 18" alloy wheels, 5-spoke design (7.5 J x 18 with 225/60 R18 tires)
- Wheels: Tire repair kit (maximum speed 80 km/h when used)
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Airbags (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger)
- ST-Line body styling kit (upper grille, ST-Line design - lower grille, ST-Line design - rear bumper, ST-Line design)
- On-board computer
- third brake light
- Fabric headliner, black
- Roof spoiler, large
- Anti-theft device (engine shutdown)
- Tachometer
- eCall (emergency call system for sending an emergency call in case of an accident or manual activation)
- Electronic shifter (rotary switch)
- Electronic Stability Program (ESP) (additionally with electronic brake booster)
- Lane keeping assist including lane keeping assist and lane change assist (including centering assist)
- Electric parking brake with auto hold function
- Ford Key Free system including Ford Power Start function and electric tailgate (keyless unlocking/locking - keyless start)
- Transmission: continuously variable automatic transmission (CVT)
- Heated rear window
- rear window wiper
- Intelligent speed limiter with speed limit display (including exit assistant)
- Front and rear headrests (5) height adjustable
- Paint finish: Metallic
- Charging cable for the public charging station
- LED headlights (LED daytime running light signature with integrated LED turn signals - LED low beam with switch-off delay - high beam with automatic high beam control)
- Rear center armrest with two cup holders
- Fatigue warning
- Package: Driver Assistance Package (Automatic Transmission) (Intelligent Cruise Control, Adaptive 2.0 - 360 Degree Camera - Wrong-Way Driver Warning - Pre-Collision Assist with Cross Traffic Alert - Evasive Steering Assist - Door Edge Protectors - Intelligent Speed Limiter with Speed Limit Display - Ford Intelligent Drive Assist, Semi-Automated Driving - Traffic Jam Assist with Stop & Go Function and Lane Keeping Assist)

- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Memory function for seat settings & exterior mirrors
- Seats: Rear bench seat, sliding with 60:40 split adjustable and folding backrest (with folding lever in the trunk)
- Carpet floor mats front and rear, ST-Line design
- Blind spot assist with cross traffic alert (including emergency braking function when reversing out of parking spaces and trailer detection)
- Glazing: Front doors with acoustic laminated glass
- Traffic sign recognition system including wrong-way driver warning function, extended (camera and map-based)
- Black trim strips (black border around the upper and lower side windows)
- Radio: Ford SYNC 4 including Ford navigation system with 13.2" touchscreen (AppLink - DAB/DAB+ - B&O sound system with 10 speakers - FordPass Connect including eCall and Live Traffic - Amazon Alexa Built-In voice control - Android Auto and Apple CarPlay - Bluetooth hands-free calling and audio streaming - Digital owner's manual - Steering wheel controls - Ford Power-Up software updates - Intelligent route suggestions - Customizable user profiles - Radio player - USB port - Voice control via audio and telephone - Audible and visual route guidance)
- Seats: Driver's seat, 10-way electronically adjustable (driver's seat, 10-way electronically adjustable including adjustable lumbar support and memory function - passenger seat, 8-way manually adjustable including manually adjustable lumbar support)
- Seats: Front seats, individually and variably heated
- Power outlet: 12-volt socket in the front center console and in the luggage compartment
- Door child safety lock, manual
- Door edge protector
- USB ports 2 front and rear (2 USB ports at the front under the dashboard (1x Type-A/ 1x Type-C) 2 USB ports at the rear of the center console (Type-C))
- Immobiliser

Extra equipment

- Swiveling towbar (incl. ESP trailer stabilization)
- Head-up display
- Paint finish: Desert Island Blue Metallic
- Package: Winter Package (Heated windscreen - Heated steering wheel - Heated outer rear seats)
- Panoramic sliding sunroof, electric, including roof console with glasses storage compartment
- Wheels: 18" all-season tires
- Anti-theft alarm system with dual-tone horn including interior monitoring
- LED matrix headlights, adaptive including coast-to-coast light bar (combined LED position light and turn signal - LED matrix high beam with high beam assist, glare-free - tourist mode, manual - predictive cornering light, map and camera based, dynamic)
- Wheels: Spare wheel (T165/70 R17 tire - instead of tire repair kit - permissible at max. 80 km/h when used)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (bei 30000 km) - No evidence - No deduction
2	Body	Underbody panelling (Vorne unt) - Loose - Un- / install
3	Front bumper	Bumper with Parktronic (Rechts unten) - Scratch(es) - Smart repair
4	Rear bumper	Bumper with Parktronic - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Misc.: Inspection / maintenance (bei 30000 km) - No evidence - No deduction



Damage 2: Body: Underbody panelling (Vorne unt) - Loose - Un- / install



Damage 2: Body: Underbody panelling (Vorne unt) - Loose - Un- / install



Damage 2: Body: Underbody panelling (Vorne unt) - Loose - Un- / install




Damage 2: Body: Underbody panelling (Vorne unt) - Loose - Un- / install



Damage 3: Front bumper: Bumper with Parktronic (Rechts unten) - Scratch(es) - Smart repair




Damage 3: Front bumper: Bumper with Parktronic (Rechts unten) - Scratch(es) - Smart repair



Damage 3: Front bumper: Bumper with Parktronic (Rechts unten) - Scratch(es) - Smart repair




Damage 4: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 4: Rear bumper: Bumper with Parktronic - Scratched - Paint



Damage 4: Rear bumper: Bumper with Parktronic - Scratched - Paint




Damage 4: Rear bumper: Bumper with Parktronic - Scratched - Paint



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction