TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48566906
Order No. / Reference: 27226130
Inspection date: 9 Nov 2026

Manufacturer: Skoda	Model: Enyaq iV 80
VIN: TMBJC9NY8PF087636	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Enyaq iV 80	
Vehicle Identification number	TMBJC9NY8PF087636
Mileage (Read)	124,881 km
First registration	9 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Car station wagon
Colour / colour code	Blau Race Metallic (F5W)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	367 Tag(e)
Last service on / at	11/2025 at 100,124 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT132537
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AWS 00155		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,600 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 104W	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	255/45 R20 101H	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag, driver and passenger
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Evasive steering assist including turn assist
- Outdoor temperature display
- Hill start assist
- Design Selection Loft
- Third brake light
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Front radar assistant with pedestrian and cyclist detection and city emergency braking function
- Tinted windows
- Rear window wiper including windshield washer system
- Isofix anchorage on the front passenger seat
- Child safety locks on the rear doors
- Climatronic air conditioning (2-zone)
- Front and rear headrests are height-adjustable.
- LED headlights with daytime running lights
- LED taillights
- Steering wheel: Leather steering wheel with multifunction buttons
- Navigation system
- Front and rear parking sensors
- Rain sensor and driving light assistant with coming and leaving home function
- Tire pressure monitoring
- Rear view camera
- Rear seat backrest split 60:40, foldable
- Seat belts
- Seats: Front seats height-adjustable including manually adjustable lumbar support
- Lane keeping assistant (Lane Assist)
- Traffic sign recognition
- heat pump
- Airbag, center airbag front
- Airbag, front and rear head airbags
- acoustic windscreen
- Traction control (ASR)
- Electrically adjustable, heated and folding exterior mirrors, including automatic dimming.
- AERO anodized roof rails
- Digital instrument cluster (Virtual Cockpit)
- E-Sound
- Increased battery charging power max. 125 kW
- Electric windows front and rear
- Cruise control
- Transmission: 1-speed (EV)
- Heated rear window
- Automatic interior mirror dimming
- Isofix anchorage on the outer rear seats including top tether
- Removable boot cover
- Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A)
- Steering wheel adjustable for height and reach
- Manual headlight range adjustment
- Multi-collision brake
- Package: Chrome
- Radio: Infotainment system with capacitive 13" color display
- Tire Mobility Kit
- Wheels: 19" Regulus AERO alloy wheels, anthracite, polished
- Power steering
- Safety lights in the front side doors
- Skoda Care Connect
- Speed limiter
- 12V socket - in the trunk
- Immobiliser
- Central locking including remote control integrated into the key

Extra equipment

- Airbag, rear side airbags 6C4
- Paint finish: Metallic
- Package: Driver Assistance PLUS PSB
- Package: Infotainment PLUS RAB
- Package: Light & Visibility PLUS PKA
- Package: SPORTLINE (80) WS0
- Panoramic sunroof, electric (deletion of the glasses compartment in the headliner)
- Wheels: 20" Vega anthracite-gloss-turned alloy wheels (front: 8Jx20 tires 235/50 R20 100T - rear: 9Jx20 tires 255/45 R20 101T)
- Luggage net partition
- Package: Convenience PLUS (Sportline) PD9
- Package: Family BASIC PX1
- Package: Air conditioning PLUS PWB
- Package: Seat Comfort BASIC PB0
- Package: Transport (Net program in the trunk incl. charging cable bag - Variable loading floor in the trunk - Remote release of the rear seat backrests in the trunk - Cargo elements in the trunk)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Smart repair
2	Door - front right side	Door edge - Scratch(es) - Smart repair
3	Wing mirror - right side	Mirror housing (Materialabtrag) - Scratch(es) - Replace
4	Door - front right side	Brightware - lower - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Front bumper	Spoiler - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Umbrella

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Navigation




Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 3: Wing mirror - right side: Mirror housing (Materialabtrag) - Scratch(es) - Replace




Damage 3: Wing mirror - right side: Mirror housing (Materialabtrag) - Scratch(es) - Replace




Damage 3: Wing mirror - right side: Mirror housing (Materialabtrag) - Scratch(es) - Replace



Damage 4: Door - front right side: Brightware - lower - Scratch(es) - Paint



Damage 4: Door - front right side: Brightware - lower - Scratch(es) - Paint




Damage 4: Door - front right side: Brightware - lower - Scratch(es) - Paint



Damage 4: Door - front right side: Brightware - lower - Scratch(es) - Paint



Missing part 1: Equipment: Umbrella - Missing - Replace



Missing part 1: Equipment: Umbrella - Missing - Replace