TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 45487425
Order No. / Reference: 26284415
Inspection date: 15 May 2026

Manufacturer: Volkswagen	Model: Multivan T7 Kurz eHybrid
VIN: WV2ZZZSTZNH004371	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Multivan T7 Kurz eHybrid	
Vehicle Identification number	WV2ZZZSTZNH004371
Mileage (Read)	111,268 km
First registration	24 Mar 2022
Number of holders	1
Power / Engine displacement	110 kw / 1,395 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Starlight blue metallic (T5U)
Doors / Seats	5 / 7
Upholstery type	Cloth
Colour of upholstery	Grey-Light grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-200 km
Last service on / at	08/2025 at 95,770 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ065667
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	With complaint
Manufacturer key number/ type code number	0603 / CQI 00015		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	**fine dust sticker**	
Permitted total weight	2,750 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 104H	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	215/60 R17 104H	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103H	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	235/55 R17 103H	Summer tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V system
- Storage compartments: Various shelves and storage compartments
- Airbag: Side and head airbags for driver and front passenger (head airbags for the outer rear seats - center airbag in the front)
- Exterior mirror housings in high-gloss black
- LED turn signals, integrated into the side of the exterior mirrors
- On-board tools and tire mobility set (in the storage compartments in the luggage compartment)
- DC/DC converter 3.0 KW
- Decorative inlays: Decorative inlays "Scale Light Grey"
- e-Sound
- Chassis: 17" disc brakes at the front and 16" disc brakes at the rear
- Windows: Front pane made of laminated safety glass, heat and sound insulating
- Transmission: DSG (dual-clutch transmission), 6-speed automatic
- Glove compartment without light, lockable
- Tailgate closing without interior unlocking function
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Cargo space divider (load capacity 20 kg) with bag hooks and luggage net
- Strip between the headlights painted in glossy black
- Headlight range control
- Multifunctional display: Digital Cockpit Pro
- Multimedia systems: 2 USB interfaces (Type C) in the dashboard
- Emergency braking assistant "Front Assist" (with pedestrian and cyclist detection)
- Radio: "Ready 2 Discover" with 25.4 cm (10 inch) color touchscreen
- Radio: Digital radio reception (DAB+)
- Radio accessories: Voice control
- Wheels/Tire Accessories: Lockable wheel bolts
- Sliding door in the passenger/cargo compartment: sliding door on the left
- Keys for locking system: 2 vehicle keys
- Power steering
- dimmable interior safety mirror
- Seat covers: Bi-color fabric seat covers, "Bright Dots" design
- Sun visors with mirrors, ticket holder on the driver's side (airbag label on the sun visor and B-pillar on the passenger side)
- Partitions: Mesh partition
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing
- Euro 6d ISC-FCM emissions standard
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Evasive steering assist and turn assist
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirrors, left and right convex
- Battery LiFePO4 450 A (40 Ah)
- Floor coverings: Reinforced velour carpet in the passenger compartment
- third brake light
- Roof rails/roof load carrier: Mounting points for roof rack system (6 pieces)
- Tachometer
- Electronic Stability Program, ABS, ASR (with deactivation button), EDS (Hill Start Assist)
- Chassis: Suspension and damping, standard
- Electric windows, front
- Cruise control system with speed limiter (and "Intelligent Speed Assist")
- Glove compartment with flap
- Boot lid
- Rear window with wiper/washer system, heated
- Child seat anchorage ISOFIX and Top Tether (for each individual seat in the passenger compartment)
- LED headlights with LED daytime running lights
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Multi-collision brake
- Fatigue detection
- Non-smoking version
- eCall emergency call system
- Particle filter: Gasoline particulate filter
- Radio: App-Connect incl. App-Connect Wireless (for Apple CarPlay and Android Auto)
- Radio accessories: 8 speakers (passive)
- Wheels/Tires: Tire pressure monitoring system
- Windscreen wiper interval control, 4-stage adjustable (for the front windscreen wipers)
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Seat belt monitoring system (warning tone and light for unfastened seat belts front and rear)
- Seats: Left and right seats in the 1st row (with height adjustment - including 2-way headrest)
- Lane keeping assistant “Lane Assist”
- Daytime running lights with cornering lights
- Telephone: Mobile phone interface
- First aid kit, warning triangle and high-visibility vest

- Lashing eyes (4 pieces) (2 fixed lashing eyes in the cargo area - 2 variable lashing eyes for the rail system)
- Central locking with keyless start system "Keyless Start" without safe locking

Extra equipment

- Parking assistance in the front and rear areas
- Air conditioning: 3-zone "Air Care Climatronic" with additional control unit in the passenger compartment
- Charging cable for AC charging station (Mode 3)
- Wheels/Tires: "Dundrod" 6.5 J x 17 alloy wheels, diamond-turned finish (4 "Dundrod" 6.5 J x 17 alloy wheels, in black, diamond-turned finish - tires 235/55 R 17 103 H xl, optimized for low rolling resistance - wheel center cover for alloy wheels - lockable wheel bolts)
- Drawers under the outer seats in the passenger compartment and 2 waste bins
- Heated seats for the driver's cab, left and right, separately adjustable
- Windows (glass type in the cargo/passenger compartment) - rear windows tinted
- Paint finish: Metallic
- Radio accessories: USB interface (2 USB-C ports at the front - 4 USB-C charging ports in the passenger compartment)
- Rear View reversing camera
- Sliding door: Closing aid on both sides for sliding doors (sliding door left and right with closing aid)
- Seats: Armrests on the front seats, on both sides (with electric lumbar support and folding table)
- Seating configuration - 1. Seat packages: 7-seater package = 2-2-3 (approval for a maximum of 7 seats - 3 individual seats in the 3rd row - 2 individual seats facing forward in the 2nd row)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Seat - front	Seat cover - right side - Soiled - Clean
3	Instrument panel	Indicator light (Motorkontrolle) - on - Perform diagnosis
4	Misc.	Inspection / maintenance - Due - Perform
5	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
6	Bonnet	Bonnet (Lack abgeplatzt) - Paint defect - Repair and paint
7	Rear bumper	Rear bumper - Scratch(es) - Paint
8	Front bumper	Front bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - No deduction
2	Side panel - rear left side	Side panel - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Log book

Equipment - Tirefit compressor

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 5 Aug 2025	2.353,46 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Seat - front: Seat cover - right side - Soiled - Clean



Damage 3: Instrument panel: Indicator light (Motorkontrolle) - on - Perform diagnosis



Damage 4: Misc.: Inspection / maintenance - Due - Perform



Damage 5: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 5: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 6: Bonnet: Bonnet (Lack abgeplatzt) - Paint defect - Repair and paint




Damage 6: Bonnet: Bonnet (Lack abgeplatzt) - Paint defect - Repair and paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper - Scratch(es) - Paint

Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer:	WV2ZZZSTZNH004371
Hersteller / Modell:	VOLKSWAGEN VOLKSWAGEN Multivan T7 Kurz eHybrid

Datum	KM-Stand	Beschreibung
11.08.2025	95.770	Bremsklötze hinten; Bremsscheiben hinten; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
14.05.2025	89.398	AU
10.03.2025	83.520	Systemtest/Eigendiagnose
08.01.2025	79.576	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Systemtest/Eigendiagnose; Wartung Sonstiges
08.08.2024	69.362	Systemtest/Eigendiagnose
11.06.2024	62.937	Bremsflüssigkeit; Bremsflüssigkeit ern; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
06.12.2023	49.167	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
02.05.2023	31.301	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.09.2022	16.898	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges