APPRAISAL REPORT



IDENTIFICATION VEHICLE

Make:	BMW
Model / version:	X2
Vin:	WBAYN910105V74923
Plate:	2CMX835
Mileage:	121016
SOH:	
First registration:	21/09/2022
Color:	Saphirschwar

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?



DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES

























VIN INFORMATION

Système navigation	Transmission automatique	6 rapports
4 roues motrices	Projecteurs à LED	Matière : alliage
Lettre repère (J)	Diamètre avant 17	Diamètre arrière 17
Largeur avant 7,5	Largeur arrière 7,5	Diamètre avant 17
Diamètre arrière 17	Hauteur avant 55	Hauteur arrière 55
Indice de vitesse avant W	Indice de vitesse arrière W	Largeur avant 225
Largeur arrière 225	Climatisation automatique	Accoudoir central avant
Hybride essence	1499 cm3	1.50 litre
92 kw	125 ch	Métallisée vernissée
Rétroviseur gauche chauffant	Rétroviseur droit chauffant	Rétroviseur gauche jour/nuit automatique
Rétroviseur droit jour/nuit automatique	Rétroviseurs rabattables électriques	Rétroviseur intérieur jour/nuit automatique
Siège avant gauche à réglage lombaire	Sièges avant à réglage lombaire	Garnitures simili-cuir
Volant cuir	Volant sport	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Assistance au parking

Caméra avant
Caméra arrière de recul
Régulateur automatique de la distance
Affichage tête haute
Ouverture du coffre électriquement
Alarme
Appel de secours
Lunette arrière teintée foncée
Vitres portes arrière teintées foncées
Vitres de custode teintées foncées
Protection piéton
Freinage d'urgence assistée autonome (urbain)
Avertisseur de collision avant
Contrôle pression des pneus
depuis 08.22
Advantage
mesures CO2 étendues
norme supplémentaire RDE
tuner DAB
Connected Drive Services
pack de rangement
boulons antivol de roue
encarts intérieurs oxyde d'argent foncé mat avec accents noir brillant
spécifique Europe

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		225/55R17 97w	Summer		?
Front right	5 mm		225/55R17 97w	Summer		?
Rear left	5 mm		225/55R17 97w	Summer		?
Rear right	5 mm		225/55R17 97w	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Luggage compartment cover	Damaged
2	Bumper F	Grooved
4	Door FL	Scratch(es)
5	Inner door sill RR	Dent(s) and scratch(es)
6	Outside rear-view mirror housing R	Grooved
7	Door FR - 2X	Dent(s)
8	Door RR	Dent(s) and scratch(es)
9	Alloy rim RR	Grooved
10	Bumper R	Dent(s) and scratch(es)
11	Door RL	Dent(s)

Total: 10

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Luggage compartment cover - Damaged





2 - Bumper F - Grooved






4 - Door FL - Scratch(es)







5 - Inner door sill RR - Dent(s) and scratch(es)


6 - Outside rear-view mirror housing R - Grooved




7 - Door FR - 2X - Dent(s)








8 - Door RR - Dent(s) and scratch(es)





9 - Alloy rim RR - Grooved



10 - Bumper R - Dent(s) and scratch(es)





11 - Door RL - Dent(s)




3 - Bodywork - Dent(s) and scratch(es) - Renta®











SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

19/10/2026 09:28

