TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48458604
Order No. / Reference: 27218694
Inspection date: 2 Nov 2026

Manufacturer: Ford	Model: Kuga 2.5 Duratec PHEV ST-LINE
VIN: WF0FXXWPMHPJ84188	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV ST-LINE	
Vehicle Identification number	WF0FXXWPMHPJ84188
Mileage (Read)	122,344 km
First registration	23 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2028
(Report on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,488 ccm / 4
Power	112 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Magnetic Grey Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	94 %
Last service on / at	10/2026 at 121,043 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GX209733
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BTM 00020		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,320 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 104V	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	225/60 R18 104V	All-season tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Body styling kit
- Fabric headliner
- Roof spoiler
- Dual exhaust system
- Electronic Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric windows front and rear
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- Heated rear window
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Front and rear headrests (5) height adjustable
- charging cable
- LED fog lights
- Steering column, adjustable in height and reach
- Front center console with integrated armrest
- MyKey key system
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Rear view camera
- Headlights with delayed shut-off
- Power steering
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Carpet floor mats front and rear
- Black trim around the side windows
- Central locking with remote control and remote luggage compartment release
- Ambient lighting
- Electrically adjustable, heated and folding exterior mirrors
- Tires: 7.5 J x 18 light alloy wheels (4) in 5x2-spoke design in Rock Metallic (with tires 225/60 R 18)
- third brake light
- Roof rails, black
- 12.3-inch digital instrument panel
- Tachometer
- Driving mode switch selective
- Chassis: Sport chassis
- Electric parking brake with auto hold function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- LED taillights
- Steering wheel: ST-Line design, flattened at the bottom and with red decorative stitching, in Sensico synthetic leather
- Navigation system: Ford navigation system incl. Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth® hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - SMS text-to-speech function - Road map for Europe)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Seats: Driver and passenger seats, 8-way manually adjustable
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front seats, individually and variably heated
- Power outlet: 12-volt connection in the luggage compartment
- Immobiliser

Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Package: Technology (Adaptive LED headlights with glare-free high beam assist and dynamic cornering lights, automatic headlight range control and LED fog lights - Head-up display)
- Paint finish: Special metallic paint finish
- Safety partition net (including attachment points behind the first and second rows of seats)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Tires: 4 all-season tires 225/60 R 18 100V
- Package: Driver Assistance Package (Automatic Transmission) (Intelligent Adaptive Cruise Control with Traffic Sign Recognition System - Traffic Jam Assist with Stop&Go Function and Lane Keeping Assist - Wrong-Way Driver Warning System - Evasive Steering Assist - Driver Drowsiness Detection - Pre-Collision Assist including Forward Collision Warning System with Cross Traffic Alert - Blind Spot Assist with Emergency Braking Function and Trailer Detection - Active Park Assist with Parking Assist and Semi-Autonomous Vehicle Steering - Front Camera with Split View - Door Edge Protectors - Intelligent Speed Limiter with Speed Limit Display)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Interior	Interior - Scratch(es) - No deduction
3	Sill - left side	Sill - Scratch(es) - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Front

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents




TSN / VSN: BTM
(4) Kilometerstand: 121(
letzte HU: 00.(

nannter Untersuchungsart geprüft und abschließend folgendes Ergebn

	(8) Nächste HU:		
plakette	10.28		
eteilt			

ems-Kennw.	Berechn. Druck (bar)	Summe der Bremskräfte ∑FB Ist (daN)	Erforderliche Bremskräfte ∑FB Min (daN)	Bre
r/-)				
,14	-	602	448	
4,01	-	460	373	
-	-	272	-	

Figure 13: Documents



Wartungs-Checkliste

Ausstehende Service-Aktionen. Stellen Sie bitte sicher, dass diese durchgeführt wurden.
Keine Mitteilung(en) zu Rückrufaktionen gefunden

Fahrt in Werkstatt	
Instrumente, Warn- und Kontrollleuchten und Hupe	Funktion prüfen
Windschutzscheibe, Scheibenwischer, Waschanlage	Funktion u. Zustand prüfen ggf. einstellen/reparieren/erneuern (gem. Berechnung)
Innenraum	
Außenbeleuchtung und dazugehörige Kontrolleuchten; Instrumentenbeleuchtung	Funktion / Zustand prüfen
Feststellbremse	Funktion / Zustand prüfen, ggf. einstellen
Serviceintervall / Öiservice-Anzeige oder intelligentes Ölüberwachungssystem (IOLM)	Zurücksetzen nach Ölwechsel bei allen mit IOLM ausgestatteten Fahrzeugen, unabhängig davon, ob eine Meldung im Kombiinstrument angezeigt wird
Sicherheitsgurte, Gurtschlösser und Gurtpeitschen	Sicherheitsgurt vollständig abrollen, Gurtband auf Beschädigung prüfen, Gurtschloss auf Funktion prüfen
Aktivkohlefilter	Erneuern

Figure 14: Documents




Digitaler Service Nachweis
Kopie für den Kunden

Fahrzeugangaben
VIN : WF0FXXWPMHPJ84188
Modell : KUGA
Motor : 2.5L DURA D4 IVCT ATK HEV/PHEV
Farbe : MAGNETIC
Wartungsintervall : Alle 30000 KM oder 24 Monate (je nachdem, was zuerst eintritt)
Amtl. Kennzeichen :
Zulassung :
Zulassungsland :
Garantie - Standdatum : 23.10.2023
Nächster TÜV fällig : 01.10.2026

Nächste Inspektion	Fälligkeitsdatum	oder nach Kilometerstand
4 Jahr (60000 km)	05.11.2024 angepasst für aktuellen, durchschnittlichen Jahreskilometerstand (48844KM) 26.03.2026 bei normaler Jahreslaufleistung	45514KM (je nachdem, was zuerst eintritt)

Reparaturbetrieb	Auftragsdaten	Kilometerzähler	Beschreibung
Emil Frey Hessengarage Am Riederbruch 8 Frankfurt 60386 GERMANY 069420987-0 info@hessengarage.de www.hessengarage.de	Auftragsdatum : 26.09.2024 Auftragsnummer : 04795200	Ablesewert : 45514 KM	Planmäßige Wartung abgeschlossen Öl-Wechsel (IOLM) Ergebnis der Karosserie-/ Lackinspektion Nicht durchgeführt Zusätzliche Wartungsarbeiten Keine ausstehenden Service-Aktionen Öl-Wechsel (IOLM)
Hessengarage Offenbach Sprendlinger Landstr. 210 Offenbach es069	Auftragsdatum : 26.03.2024 Auftragsnummer : 024572	Ablesewert : 20870 KM	Planmäßige Wartung abgeschlossen 2 Jahr (30000 km)

Figure 15: Documents




Digitaler Service Nachweis
Kopie für den Kunden

Fahrzeugangaben
VIN : WF0FXXWPMHPJ84188
Modell : KUGA
Motor : 2.5L DURA D4 IVCT ATK HEV/PHEV
Farbe : MAGNETIC
Wartungsintervall : Alle 30000 KM oder 24 Monate (je nachdem, was zuerst eintritt)
Zulassungsland :
Garantie - Standdatum : 23.10.2023
Nächster TÜV fällig : 01.10.2026

Nächste Inspektion	Fälligkeitsdatum	oder nach Kilometerstand
4 Jahr (60000 km)	05.11.2024 angepasst für aktuellen, durchschnittlichen Jahreskilometerstand (48844KM) 26.03.2026 bei normaler Jahreslaufleistung	45514KM (je nachdem, was zuerst eintritt)

Reparaturbetrieb	Auftragsdaten	Kilometerzähler	Beschreibung
Emil Frey Hessengarage Am Riederbruch 8 Frankfurt 60386 GERMANY 069420987-0 info@hessengarage.de www.hessengarage.de	Auftragsdatum : 01.09.2025 Auftragsnummer : 094204	Ablesewert : 80134 KM	Planmäßige Wartung abgeschlossen Öl-Wechsel (IOLM) Ergebnis der Karosserie-/ Lackinspektion Nicht durchgeführt Zusätzliche Wartungsarbeiten Keine ausstehenden Service-Aktionen Bremsflüssigkeitswechsel Öl-Wechsel (IOLM)
Emil Frey Hessengarage Am Riederbruch 8 Frankfurt	Auftragsdatum : 26.09.2024 Auftragsnummer : 04796200	Ablesewert : 45514 KM	Planmäßige Wartung abgeschlossen

Figure 16: Documents



Digitaler Service Nachweis
Kopie für den Kunden

Fahrzeugangaben
VIN : WF0FXXWPMHPJ84188
Modell : KUGA
Motor : 2.5L DURA D4 IVCT ATK HEV/PHEV
Farbe : MAGNETIC
Wartungsintervall : Alle 30000 KM oder 24 Monate (je nachdem, was zuerst eintritt)
Zulassungsland :
Garantie - Standdatum : 23.10.2023
Nächster TÜV fällig : 24.10.2028

Nächste Inspektion	Fälligkeitsdatum	oder nach Kilometerstand
10 Jahr (150000 km)	23.07.2027 angepasst für aktuellen, durchschnittlichen Jahreskilometerstand (37272KM) 02.10.2028 bei normaler Jahreslaufleistung	150000KM (je nachdem, was zuerst eintritt)

Reparaturbetrieb	Auftragsdaten	Kilometerzähler	Beschreibung
Emil Frey Hessengarage Am Riederbruch 8 Frankfurt 60386 GERMANY 069420987-0 info@hessengarage.de www.hessengarage.de	Auftragsdatum : 02.10.2026 Auftragsnummer : 14065700	Ablesewert : 121043 KM	Planmäßige Wartung abgeschlossen 8 Jahr (120000 km) Ergebnis der Karosserie-/ Lackinspektion Nicht durchgeführt Zusätzliche Wartungsarbeiten Offene Service-Aktionen durchgeführt Austausch des Pollen-/ Geruchsfilters Austausch der Zündkerzen Öl- und Ölfilterwechsel Austausch des Luftfilters

Figure 17: Documents



Figure 18: Documents




Figure 19: Documents




Figure 20: Navigation




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.






Figure 40: Misc.



Damage 1: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 1: Vehicle glazing: Windscreen - Broken / torn - Replace



Accident 1: Front



Accident 1: Front



Accident 1: Front



Accident 1: Front



Accident 1: Front




Accident 1: Front

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Accident 1: Front



Accident 1: Front