TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48030671
Order No. / Reference: 27020193
Inspection date: 8 Oct 2026

Manufacturer: Audi	Model: A3 40 TFSI Sportback quattro S tronic S line
VIN: WAUZZZGY0NA093047	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 40 TFSI Sportback quattro S tronic S line	
Vehicle Identification number	WAUZZZGY0NA093047
Mileage (Read)	53,670 km
First registration	29 Jun 2022
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	1,984 ccm / 4
Power	140 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Car hatchback
Colour / colour code	daytonagrau perleffekt (Z7S)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	Yes (not ozone-treated)
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	6,400 km
Last service on / at	04/2026 at 48,268 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ206877
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BXZ 00119		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,000 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/50 R17 93H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	205/50 R17 93H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger (with front passenger airbag deactivation)
- All-wheel drive "quattro" (driving situation-dependent all-wheel drive of all 4 wheels)
- Anti-lock braking system (ABS) (with electronic brake force distribution (EBD), hydraulic brake assist)
- Audi connect Emergency Call & Service with m.connect Remote & Control (The Audi connect Emergency Call & Service services ensure a safe feeling on every journey. - Emergency call - Online breakdown call - Audi damage service - Audi service appointment online Audi connect Remote & Control: - Vehicle status - Remote locking/unlocking - Parking position - Remote control of auxiliary heating - Push notification of anti-theft alarm system)
- Electrically adjustable and heated exterior mirrors (with integrated LED indicator lights - left mirror glass aspherical, right convex - including heated windshield washer nozzles)
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches (speed, time, mileage, outside temperature, fuel warning with remaining range, shift indicator (for manual and automatic transmissions in manual mode), current radio station or music track, radio and media lists, classic-style display; if available: telephone menu (in conjunction with multifunction steering wheel), trip computer with short- and long-term memory, fuel-saving tips for more economical driving including break recommendations)
- Electromechanical parking brake (includes parking brake function when stationary, starting aid by automatic release when starting off and emergency braking function while driving via all four wheels)
- Electric windows front and rear
- Remote key (without Safe-Lock) (locks and unlocks doors, luggage compartment and fuel filler flap - including comfort closing/opening of windows)
- Transmission: S tronic 7-speed
- rear window wiper
- Interior lighting (front and rear roof module, including reading lights (incandescent bulbs) - glove box lighting (incandescent bulb) - LED trunk lighting right)
- Rear headrests (3)
- Light and rain sensor
- Otto particulate filter
- Radio: MMI Radio plus (10.1-inch color display (1,540 x 720) including MMI touch operation, digital instrument cluster with 10.25-inch color display, Audi music interface with two USB-C ports, each with data and charging function, Bluetooth interface (hands-free calling and audio streaming), passive speakers with 4 speakers in the front and 2 in the rear (80 watts), AM/FM phase diversity, DAB+ speed-dependent volume adjustment, voice control system for controlling infotainment and vehicle functions, WLAN hardware)
- Start-stop system
- 12-volt power outlet in the rear
- 12V socket
- Airbag: Front side airbags with head airbag system and front interaction airbag (In addition to the front side airbags and the head airbags, an interaction airbag is installed at the front, which deploys within the system boundaries between the driver and front passenger seats if required)
- Traction control ASR (prevents wheel spin by reducing engine power, thus providing more stability and improved traction on the road)
- Audi pre sense front (within system limits, uses a front radar to detect the area in front of the vehicle and warns the driver with visual and acoustic signals to indicate a potential hazard from vehicles ahead, whether moving or stationary – pedestrian and cyclist detection registers, within system limits, when a pedestrian or cyclist is moving on or crossing the road. The system then warns the driver with an acoustic and visual signal)
- Exterior mirror housings in body color
- third brake light
- Roof edge spoiler S
- Tachometer
- Rear parking aid (supports reversing and maneuvering within the system limits by acoustically indicating the distance to a detected object behind the vehicle. The measurement is carried out by ultrasonic sensors discreetly integrated into the bumper, which are activated when reverse gear is engaged.)
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Electric auxiliary air heater
- Electronic Differential Lock (EDS)
- Electronic Stability Control (ESC)
- Chassis: Sport chassis (Sport chassis with more dynamic spring and damper tuning and lowering by 15 mm, for more direct road contact and sportier handling.)
- Front and rear floor mats (made of velour in black)
- Removable luggage compartment cover
- Speed limiter (assists you in maintaining a constant driving style and adhering to speed limits by adjusting the maximum speed)
- Electrically operated child safety lock
- i-Size child seat attachment and top tether for the outer rear seats
- Front headrests
- Non-smoking version (with 12-volt socket and storage compartment)
- Tire pressure monitoring system (visual and audible warning in case of pressure loss in one or more wheels)
- Tire repair kit (with tire sealant and compressor)
- Electromechanical power steering (with speed-dependent steering assistance)
- 3-point automatic seat belts (3-point automatic seat belts for all seats, pyrotechnic belt tensioners, belt height adjustment at the front, belt force limiters on all outer seats)

- Daytime running light
- Glazing: Green tinted heat-insulating glazing (for rear window, door and side windows - rear window heated, with timer)
- Electronic immobilizer

- Lane Departure Warning (within system limits, helps prevent unintentional lane departures. If the system is activated and ready, and the driver has not used the turn signal, the Lane Departure Warning helps prevent crossing detected lane markings by making corrective steering interventions. Additional steering wheel vibration can be set at the driver's request. Operating range from approximately 60 to a maximum of 250 km/h)

Extra equipment

- 2-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver and front passenger side - with sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Adaptive Cruise Control (S tronic) (Using a radar sensor, it detects vehicles ahead within the system's limits and maintains a largely constant speed and distance within the control range. The speed range is between 0 and 210 km/h. The control range is 30 to 210 km/h. In stop-and-go traffic, vehicles can brake to a standstill and, under certain conditions, automatically accelerate again. The distance can be adjusted in 5 steps via Audi drive select or the ACC menu.)
- Aluminum roof rails
- Gloss package (window trim strips in anodized aluminum)
- Paint finish: Daytona Gray Pearl Effect
- S line interior package (S tronic) (front sport seats with manual adjustment of seat height, seat fore/aft position, seat tilt, backrest tilt and seat belt height, as well as headrests; fabric Puls/mono.pur 550-K synthetic leather; 3-spoke leather steering wheel with multifunction plus and shift paddles including leather steering wheel grips; front and rear door armrests in synthetic leather; aluminum spectrum dark decorative inlays; illuminated front door sill trims with aluminum inlays and S lettering; black fabric headliner; front center armrest; stainless steel floor mats, pedals and footrest)
- Seats: Rear seat backrest foldable (three-part), with center armrest (split in a 40:20:40 ratio or fully foldable; with center armrest and cupholders)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with twelve multifunction buttons. Shift paddles allow manual gear changes.)
- Telephone: Audi Phone Box (universal Bluetooth interface - convenient, integrated hands-free system - coupling antenna for connecting the mobile phone to the external antenna for improved reception quality - reduced radiation in the vehicle interior - LTE support - charging option via USB port or wireless charging (Qi standard) - forget-to-use warning - charging status indicator in the MMI touch display - connection of a second mobile phone)
- Ashtray at the front and cigarette lighter (cigarette lighter - removable ashtray with lid)
- Business package (USB ports with charging function in the rear - Audi connect Navigation & Infotainment plus - Audi phone box - Audi virtual cockpit plus - Smartphone interface (Android Auto and Apple CarPlay) - MMI Navigation plus with MMI touch - Cruise control)
- Camera-based traffic sign recognition (Supports the driver by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions, which are within the detection range of the front camera. The traffic sign recognition is displayed automatically in the digital instrument cluster or in the optional Audi virtual cockpit.)
- Deletion of model designation and performance/technology lettering
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- LED headlights and LED taillights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights (to reduce glare in poor visibility conditions), motorway lights, static cornering lights, maneuvering lights (illumination of the maneuvering area at the front and sides when reversing), automatic dynamic headlight range control, intersection lights (in conjunction with MMI Nav. plus), dynamic rear turn signals, brake lights, tail lights, rear license plate lights, reversing lights)
- Phone: LTE support for Audi phone box
- Seat covers in Puls fabric/mono.pur 550 synthetic leather combination with S embossing (center section of the front and both outer rear seats in Puls fabric - side bolsters, headrests, middle rear seat and front center armrest (if ordered) in mono.pur 550 synthetic leather - with rock grey contrast stitching and S embossing in the backrests of the front seats)
- Telephone: Smartphone interface in conjunction with MMI Navigation plus with MMI touch (The smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display. Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI touch display and voice control. The connection can be established either using a suitable USB cable or wirelessly.)
- Wheel: Alloy wheels - 18 inch - 5-V spokes, polished (8.0 J × 18, tire 225/40 R 18)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats (VL) - Holes - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Door - rear right side	Door - dent(s) - Smooth repair work
4	Mudguard - right side	Mudguard - right side - Scratch(es) - Smart repair
5	Interior	Interior (Rauch) - Odour - Ozone treatment
6	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
7	Trim / covers	Roof lining - Holes - Smart repair
8	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Replace
9	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Replace
10	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Replace
11	Vehicle glazing	Windscreen - Broken / torn - Replace
12	Front bumper	Front bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
2	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
3	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
4	Door - front left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Trim / covers: Floor mats (VL) - Holes - Replace




Damage 1: Trim / covers: Floor mats (VL) - Holes - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace




Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair




Damage 4: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair




Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Trim / covers: Roof lining - Holes - Smart repair



Damage 7: Trim / covers: Roof lining - Holes - Smart repair



Damage 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Replace



Damage 9: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 9: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 9: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace




Damage 10: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 10: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 10: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Replace



Damage 11: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 11: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 12: Front bumper: Front bumper - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper - Scratch(es) - Paint