VOLVO XC90

Vehicle information


Brand:	**VOLVO**	License plate:	**2BCP921**
Gearbox:		Body color:	
Model:	**XC90**	LEVEL:	**YV1LFBMVDN1797075**
Fuel type:		Power:	**223 kW**
Version:	**2.0 T8 PHEV REGISTRATION 7PL. AUTO 4WD**	First registration	**01/10/2021**
Mileage:	**201183 km**	Number of doors:	


Summary of damages


Back	4
Before	1
RIGHT	8
LEFT	2
Interior	3
Roof & other	1

Commercial photos
































Gecombineerd:		g/km		l/100 km
Gewogen, gecombineerd:	47	g/km	2.1	l/100 km
Afwijkingsfactor			N/A	
Verification factor:			N/A	

2 Puur elektrische voertuigen en extern oplaadbare hybride elektrische voertuigen (indien van toepassing)

Elektriciteitsverbruik (gewogen, gecombineerd)	163	Wh/km
Elektrische actieradius	50	km

3. Voertuig uitgerust met een of meer eco-innovaties: Neen
3.1 Algemene code van de eco-innovatie(s):
3.2 Totale CO2-emissiebesparing dankzij de eco-innovatie(s) (hernalen voor elke geteste referentiebrandstof)
3.2.1 NEDC-besparingen: g/km
3.2.2 WLTP-besparingen: g/km
4. Alle aandrijflijnen behalve puur elektrische voertuigen, krachtens Verordening (EU) 2017/1151 (indien van toepassing)

WLTP-waarden	CO_2-emissies		Brandstofverbruik	
Low		g/km		l/100 km
Medium		g/km		l/100 km
High		g/km		l/100 km
Extra High		g/km		l/100 km
Gecombineerd		g/km		l/100 km
Gewogen, gecombineerd	65	g/km	2.9	l/100 km

5. Puur elektrische voertuigen en extern oplaadbare hybride elektrische voertuigen, krachtens Verordening (EU) 2017/1151 (indien van toepassing)
5.1 Puur elektrische voertuigen

Elektriciteitsverbruik		Wh/km
Elektrische actieradius		km
Elektrische actieradius in de stad		km

5.2. Extern oplaadbare hybride elektrische voertuigen

Elektriciteitsverbruik (EC AC,weighted)	162	Wh/km
Elektrische actieradius (EAER)	48	km
Elektrische actieradius in de stad (EAER stad)	52	km

Diversen
51. Voor voertuigen voor speciale doeleinden: aanduiding overeenkomstig bijlage I, deel A, punt 5.
bij Verordening (EU) 2018/858 van het Europees Parlement en de Raad:
52. Opmerkingen: Extra band/wielcombinatie (geen referentie aan RR):
hoogst goedgekeurde rolweerstand klasse volgens paragraaf 35
235/55R19 Min 104H; 8Jx19x42.5 275/45R20 Min 104H; 9Jx20x38.5 275/40R21 Min 104H; 9Jx21x38.5
275/35R22 Min 104H; 9Jx22x38.5 M&S Min 104Q
Aanb werk Trek
...met 24 GHz-korteafstandsradarapparatuur

Options according to the inspector

GPS	**Yes**


Damages

Luggage cover

damaged

Smart repair

Rear







Bodywork


Damaged -

Acceptable.

Roof & other


















MACADAM

MACADAM

MACADAM

BRUGGE
MACADAM

MACADAM


MACADAM
BRUGGE

MACADAM

MACADAM

MACADAM

MACADAM

MACADAM

MACADAM

MACADAM

MACADAM

MACADAM

Damaged **Interior**
- Acceptable
Interior






























Worn **Interior** - Check Interior




Polished right-hand side aluminum rim .
Scratch(es) left-hand side
- Repair and paint (complete)








Polished ARG alloy
rim with scratches
on the left - Repair and paint (complete
)



Polished front right alloy wheel
with scratches on
the left - Repair and paint (complete)








Polished front left alloy wheel
with scratches
on the left - Repair and paint (complete
)





Tire repair kit
missing.
Check
rear.




Tire repair kit
missing.
Check
rear.




Right rear fender molding

- Dent(s) and scratch(es)
- Replace and

paint














Door molding ARD

Claw(s)


- Replace and paint

Right










Front left door molding with

claw(s)

- Replace and paint.

Right





Rear bumper dent

(s) and scratch(es)


Smart repair

Rear














Front bumper, Smart repair
claw(s), front









Front Right
Tire Tear -
Acceptable




Right **rear door**
- Dent(s) and scratch(es)
- Repair and paint (complete)












Front **Right Door**
Scratch(es)
LI - Repair and paint (complete)





AVG Backrest Cover
Damaged
Smart Repair
Interior





Tires

Front Left
Summer
Aluminum
275/45/20/110/V
Continental
4.0 mm
Front Right
Summer
Aluminum
275/45/20/110/V
Continental
3.0 mm
Left Back
Summer
Aluminum
275/45/20/110/V
Continental
4.0 mm
Rear Right
Summer
Aluminum
275/45/20/110/V
Continental
4.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**07/10/2026**	Interview	**OK**
Interview	**28922.0**	Interview	**350 days**
Repair kit	**Yes**	Number of charging cables (220V)	**1**
Number of charging cables (fast charging)	**0**	Total number of keys	**2**
Factory reset	**Yes, the vehicle has been reset to factory settings.**	Type of maintenance log	**Maintenance logbook present**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.