ARVAL
BNP PARIBAS GROUP

2CQS320

INSPECTION REPORT

End of contract

GENERAL INFO

File	322973
License plate	2CQS320
Vehicle identification number	TMAJD81AGNJ264054
Dossier	2022 174 073
Make	Hyundai Tuc.CRDi 48V 100kW Fee
Mileage	111020
First registration	20/10/2022
client availability date	28/09/2026
inspectionDate	05/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





B
2-CQS-320
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
27	Front / Logo / Replace	N
28	Front / Calendar / Replace	N
32	Front Bonnet // Painting	N
18	Bumper Front / Spoiler / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
272	Bumper Front / Trim Right / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
153	Rear Bonnet // Painting	N
158	Rear Bonnet / 3rd Stoplight / Replace	N
101	Door Rear Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
110	Wing Rear Left // Smart Repair Small	N
114	Wing Rear Left // Repair & Painting	N
16	Bumper Front // Polish	Y
41	Windshield // Replace	Y
66	Wing Front Left // Polish	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
162	Roof // Painting	N
183	Wing Rear Right // Painting	Y
187	Wing Rear Right / Trim / Replace	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
211	Door Front Right // Smart Repair Medium	Y
230	Wing Front right // Smart Repair Small	Y
237	Wing Front right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N


569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
773	Interior / A Pillar Lower Cover / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Rocker Panel Right // Smart Repair Medium-scratch + dent


Door Rear Right // Painting-scratch





Door Front Right // Smart Repair Medium-scratch





Wheel Two Tone Front Right // Repair-scratch





Wing Front right / Trim / Replace-scratch




Bumper Front // Polish-scratch




Roof // Painting-Chemical reaction







Interior Cleaning // Small-stain




Dashboard / Steering Wheel / Replace-worn

Windshield // Replace-stone chipping




Wheel Two Tone Rear Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch






Wing Rear Right // Painting-scratch




Wing Rear Right / Trim / Replace-scratch




Interior / A Pillar Lower Cover / Replace-scratch




Wing Front Left // Polish-scratch





Wheel Two Tone Front Left // Repair-scratch





Rocker Panel Left // Smart Repair Medium-scratch




Door Front Left // Smart Repair Medium-dent




Wing Front right // Smart Repair Small-dent




Front / Logo / Replace-scratch




Front / Calendar / Replace-scratch







Front Bonnet // Painting-scratch




Door Rear Left // Smart Repair Medium-scratch




Door Rear Left // Painting-scratch



Wing Rear Left // Smart Repair Small-scratch




Wing Rear Left // Repair & Painting-scratch + dent









Bumper Front / Lower Cover Not Painted / Replace-scratch + dent









Bumper Front / Spoiler / Replace-scratch





Bumper Front / Trim Right / Replace-Chipped paint





Rear Bonnet / 3rd Stoplight / Replace-scratch






Bumper Rear / Spoiler / Replace-scratch









Bumper Rear / Lower Cover Not Painted / Replace-scratch









Rear Bonnet // Painting-scratch